· · · · · · · · · · · · · · · · · · ·	3 ,				
STATE OF KANSAS STATE CORPORATION COM 200 Colorado Derby Bu		WELL PLUGGI K.A.R8	NG RECORD 2-3-117	API NUMBER 15-023-20251 -00-00	
Wichita, Kansas 6720	2			LEASE NAME Northrup A	
	3- N.C	TYPE OR PRINT NOTICE: Fill out completely and return to Cons. Div. office within 30 days.		WELL NUMBER7	
	4			3300 Ft. from S Section Line 1320 Ft. from E Section Line	
LEASE OPERATOR Cities	s Service Oi	il and Gas Cor	poration	SEC. 26 TWP. 2S RGE. 42 XXXXX (W)	
ADDRESS 3545 N.W. 58th	*			COUNTY _ Cheyenne	
PHONE #(405) 949-4432					
Character of Well D 8				Date Well Completed 11/1/87	
(OII, Gas, D&A, SWD, I		Contract of Market		Plugging Commenced $\frac{10/31/87}{}$	
				Plugging Completed 11/1/87	
Oid you notify the KCC				this well? yes	
thich KCC Office did y	ou notify?	District #6	· }		
- 100 1 (11 10	14				
s Aco-1 filed? yes	IT NO	T, is well log	attached?	yes	
Producing Formation No	one - Dry Ho	ole Depth to	Тор		
Producing Formation No	one - Dry Ho ss of all wa	ole Depth to	Top	BottomT.D. 5027'	
Producing Formation No show depth and thickness OIL, GAS OR WATER REC	one - Dry Ho ss of all wa ords	Depth to	gas format	T.D. 5027' ions CASING RECORD	
roducing Formation No how depth and thickness OIL, GAS OR WATER RECO	one - Dry Ho ss of all wa ords tent	ole Depth to	gas format	BottomT.D. 5027'	
roducing Formation No how depth and thickness OIL, GAS OR WATER RECEPTION	one - Dry Ho ss of all wa ords	Depth to	gas format	T.D. 5027' ions. CASING RECORD	
Producing Formation No. Show depth and thickness OIL, GAS OR WATER RECO	one - Dry Ho ss of all wa ords tent	ole Depth to	gas format	T.D. 5027' ions. CASING RECORD	
Producing Formation No. Show depth and thickness OIL, GAS OR WATER RECO Formation Cont LKC & Marm.	one - Dry Hoss of all water	Depth to	gas format	Bottom T.D. 5027' ions CASING RECORD Put in Pulled out 421' 0'	
Show depth and thickness OIL, GAS OR WATER RECO Formation Cont LKC & Marm. Describe in detail the state	one - Dry Hoss of all water order to the second sec	ole Depth to	gas format Size 8 5/8" was pluggeducing it	Bottom T.D. 5027' ions CASING RECORD Put in Pulled out 421' O' ad, indicating where the mud fluid was into the hole. If cement or other plugs	
Show depth and thickness OIL, GAS OR WATER RECO Formation Cont LKC & Marm. Describe in detail the laced and the method dere used, state the Plugged well as for	one - Dry Hoss of all water or methods character	From To	gas format Size 8 5/8" was pluggeducing it idepth place	Bottom T.D. 5027' ions. CASING RECORD Put in Pulled out 421' O' ed, indicating where the mud fluid was not the hole. If cement or other plugs ced, from feet to feet each set.	
Formation Contact And the Contact And the Contact And the Marm. Escribe in detail the laced and the method ere used, state the Plugged well as for (25 sx) Anhydrite.	one - Dry Hoss of all water ones of all water ones of all water or methods character llows: Plug	From To From To which the well used in intro of same and #1 4800' (25	size Size 8 5/8" was pluggeducing it idepth places SX) Marm.;	Bottom T.D. 5027' ions. CASING RECORD Put in Pulled out 421' 0' ad, indicating where the mud fluid was into the hole. If cement or other plugs sed, from feet to feet each set. Plug #2 4500 (25 sx) LKC; Plug #3 362	
Chow depth and thickness OIL, GAS OR WATER RECO Formation LKC & Marm. escribe in detail the laced and the method ere used, state the Plugged well as for (25 sx) Anhydrite; pipe; Plug #6 40-st	one - Dry Hoss of all water or stands or methods character llows: Plug Plug #4 288 urf. (10 sx.)	From To Fro	gas format Size 8 5/8" was pluggeducing it idepth plac sx) Marm.; akota; Plu	Bottom T.D. 5027' ions. CASING RECORD Put in Pulled out 421' 0' ed, indicating where the mud fluid was not the hole. If cement or other plugs ced, from feet to feet each set. Plug #2 4500 (25 sx) LKC; Plug #3 362 g #5 471'-371' (50 sx) bottom of surf sx) State Witness: Mr. Marion Schmidt	
Formation Contact And the Market Contact And	one - Dry Hoss of all water or all water or methods character llows: Plug Plug #4 288 arf. (10 sx)	From To	gas format Size 8 5/8" was pluggeducing it idepth place SX) Marm.; akota; Plughole (15	Bottom T.D. 5027' ions. CASING RECORD Put in Pulled out 421' O' ed, indicating where the mud fluid was into the hole. If cement or other plugs ed, from feet to feet each set. Plug #2 4500 (25 sx) LKC; Plug #3 362 g #5 471'-371' (50 sx) bottom of surf sx) State Witness: Mr. Marion Schmidt CK of this form.)	
Formation Confidence of Plugging Contra	one - Dry Hoss of all water one of all water one of all water or or methods character or allows: Plug Plug #4 288 prf. (10 sx.) all descript ctor Rains	From To From T	gas format Size 8 5/8" was pluggeducing it idepth place SX) Marm.; Dakota; Pluggeducing it idepth place SX) Marm.; Dakota; Pluggeducing it idepth place SX) Marm.; Dakota; Pluggeducing it identified it identifi	Bottom T.D. 5027' ions. CASING RECORD Put in Pulled out 421' 0' od, indicating where the mud fluid was into the hole. If cement or other plugs sed, from feet to feet each set. Plug #2 4500 (25 sx) LKC; Plug #3 362 g #5 471'-371' (50 sx) bottom of surf sx) State Witness: Mr. Marion Schmidt CK of this form.) CO. License No.	
Formation Contact the laced and the method lere used, state the Plugged well as for (25 sx) Anhydrite; pipe; Plug #6 40-st (If addition ame of Plugging Contract ddress 435 Page Cour	manner in wormethods character llows: Plug Plug #4 288 urf. (10 sx.) al descript ctor Rains	From To	gas format Size 8 5/8" was pluggeducing it idepth place SX) Marm.; Dakota; Pluggeducing it idepth place SX) Marm.; Dakota; Pluggeducing it idepth place SX) Marm.; Dakota; Pluggeducing it identified it identifi	Bottom T.D. 5027' ions. CASING RECORD Put in Pulled out 421' 0' od, indicating where the mud fluid was into the hole. If cement or other plugs sed, from feet to feet each set. Plug #2 4500 (25 sx) LKC; Plug #3 362 g #5 471'-371' (50 sx) bottom of surf sx) State Witness: Mr. Marion Schmidt CK of this form.) CO. License No.	
Show depth and thickness OIL, GAS OR WATER RECO Formation LKC & Marm. Describe in detail the end of the method were used, state the Plugged well as for (25 sx) Anhydrite; pipe; Plug #6 40-st (If addition dame of Plugging Contraddress 435 Page Cour	manner in wor methods character llows: Plug Plug #4 288 urf. (10 sx.) al descript ctor Rains	From To From T	gas format Size 8 5/8" was pluggeducing it idepth place SX) Marm.; Dakota; Pluggeducing it idepth place SX) Marm.; Dakota; Pluggeducing it idepth place SX) Marm.; Dakota; Pluggeducing it identified it identifi	Bottom T.D. 5027' ions. CASING RECORD Put in Pulled out 421' 0' od, indicating where the mud fluid was into the hole. If cement or other plugs sed, from feet to feet each set. Plug #2 4500 (25 sx) LKC; Plug #3 362 g #5 471'-371' (50 sx) bottom of surf sx) State Witness: Mr. Marion Schmidt CK of this form.) CO. License No.	
Show depth and thickness OIL, GAS OR WATER RECO Formation Constitution LKC & Marm. Describe in detail the placed and the method were used, state the Plugged well as for (25 sx) Anhydrite; pipe; Plug #6 40-st (If addition) Itame of Plugging Contracted and the plugging Contracted and the plugging Contracted Coliver For Chahoma	manner in wormsthous: Plug #4 288 arf. (10 sx.) al descript ctor Rains	From To From T	gas format Size 8 5/8" was pluggeducing it idepth place sx) Marm.; akota; Pluggeducing it idepth place by Marm.; akota; Pluggeducing it idepth place sx) Marm.; akota; Pluggeducing it idepth place sx) Marm.; akota; Pluggeducing it idepth place sx) Marm.; akota; Pluggeducing it identified it id	Bottom T.D. 5027' Ions. CASING RECORD Put in Pulled out 421' 0' ed, Indicating where the mud fluid was not the hole. If cement or other plugs ed, from feet to feet each set. Plug #2 4500 (25 sx) LKC; Plug #3 362 g #5 471'-371' (50 sx) bottom of surf sx) State Witness: Mr. Marion Schmidt CK of this form.) CO. License No.	

(Address)

SUBSCRIBED AND SWORN TO before me this

My Commission Expires:

CONSERVATION DIVISION
Wichita, Kansas

Oklahoma City,

Form CP-4 Revised 07-86