

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: Pratt Well Service, Inc.
Address: P.O. Box 847, Pratt, KS 67124
Phone: (620) 672-2531 Operator License #: 5893
Type of Well: oil Docket #: _____
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR)
The plugging proposal was approved on: _____ (Date)
by: _____ (KCC District Agent's Name)
Is ACO-1 filed? Yes No If not, is well log attached? Yes No
Producing Formation(s): List All (If needed attach another sheet)

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

API Number: 15-113-21026-00-00
Lease Name: Runbeck A *KCC*
Well Number: #1 "A" *8-12-04*
Spot Location (QQQQ): NE - SW - SW -
unknown Feet from North / South Section Line
unknown Feet from East / West Section Line
Sec. 8 Twp. 17 S. R. 3 East West
County: McPherson
Date Well Completed: 12/82 3-19-1983 *KCC*
Plugging Commenced: May 12, 2004 *8-12-04*
Plugging Completed: May 13, 2004

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)				
Formation	Content	From	To	Size	Put In	Pulled Out
				8 5/8"	331'	
				5 1/2"	3465'	

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Set plug @ 3250' spot cement on plug. Look for free pt. shoot 1100" work it, not loose, 800' worked it not loose, shoot 600', 400', 400' again still not free perforate 395' RD perf. water pumped down casing circulate around surface. pump cement down casing up surface, pump some down surface, full R.D & M.O pumped 161 sx 60/40 poz 4% gel down 5 1/2" csg - on backside of csg pumped 14 sx 60/40 poz 4% gel to surface.
CIBP @ 3250'

Name of Plugging Contractor: Kizzar Well Servicing, Inc. License #: 7868
Address: P.O. Box 346, Chase, KS 67524

RECEIVED
AUG 12 2004

Name of Party Responsible for Plugging Fees: Pratt Well Service, Inc.
State of Kansas County, Pratt, ss.

KCC WICHITA

Kenneth C. Gates, President (Employee of Operator) or (Operator) on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

(Signature) X Kenneth C. Gates
(Address) P.O. Box 847, Pratt, KS 67124

SUBSCRIBED and SWORN TO before me this 11 day of August, 2004
Amy Robertson My Commission Expires: 3/13/08
Notary Public

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

B