## KANSAS STATE CORPORATION COMMISSION

## CONSERVATION DIVISION AGENT'S REPORT

TO: 15-153-30142-00-00

J. P. Roberts
Assistant Director
500 Insurance Building
212 North Market
Wichita 2, Kansas



***			A A STATE OF THE S	
File No.	County:	Rawlins	Designates and the second of the second	nachdrafia -szanovanacjalnycká porodkynikycký plane
Location: SE SE SE	Sec. 5 Tw	p. 3 Rge.	permanent - antituderent (	(W) <u>34</u>
Name of Field:	egakingiranan merupakan sision ook oo kom e kasusta ka padan kigu nagisin vara awak ka anas sakasis ka para ta	Total Dept	h: 4520	ang a disentang a mendangah terminakan dan pelakutan sebagai sebagai dan Karama Banda dan dan sebagai sebagai
I have this date complete	d supervision of	plugging of:		
Lease Name: Samson		Well	10.1	ang akang kito sayan da managan managan matatan sati da masa sayan ang ak
Operator's Full Name:	Raymond Oil C	O Sententalaga, manop-mater talasi, andra, maker-mada jumpa, anapo matarataman naturalaga (matarataman naturalaga	andonenská damlánnapoda panapo sonazonkohydinnáhoskiskytálkohydistorovanác v s	
Complete Address:			-	
Plugging Contractor	Murfin Drg Co	2 g	and the second	
Address:	Wichita, Kans	as License	: No.	kegar aharmannakenska u veskelaharjakan (barasa)
Oll WellGas Well_	Input Well_	SWD Well_	D & A	
Other well as hereafter I	ndicated:	ude signs armount and a south	and members of the second seco	SOMMERCO CONTRACTO C
Was any delay in plugging	, operations cause	d by Conservati	on Division	Agent?
YesNox				
If yes how long?		Reason:		elifeje in leastin valdat für genistle settlich in densib v. volver volute
	ntra euro de crisco de constante de constant			s Languaga makang maka
	na natari kalapatinin kutatapan kunanati ruma ingan nago ang katalin anda sa sa sa sa sa sa		, i The contact of the control of th	
Operation Completed: Hou	r 3AM Day 1	6 Month 4	Year	62
The above well was plugge	d as follows:			
8 5/8" 128' circulated	with cement.	inders i lague. Lundquaggiowyggiona o oliv i richiriyada i vikilik libradi vikilik lundagarrinda vakult- vak	makeen kangamaa kaassoo oo	intellinents till som ott til med til som state skall state skall state skall skall skall skall skall skall sk
Circulated hole with he	avy mud, set ceme	nting plug at 5	50' displa	uced 20
sax cement through dril	l pipe, heavy mud	to 180', set p	lug and 20	Sex
cement at 180', heavy m	ud to 35', set pl	ug, hulls and f	'illed to bo	ttom
celkar with cement.	ygyyssäästäääsää hinkääsää hinkääsi jop annokaassista assan uskiik silkussiikka silkussisti syytin avaliktisjä		ana kan nancyanak pinganyang nakakakali perdangih ang alaman pengambang kepakara na berbatan k	
` \			essiffer a minar or report from the control of the	gasakeronna spytt klikiristis valutstimustus Savkingasjonneron eiri tili yaga
			nyidhistaanyaalangkii shipiqaqahiyo shifa qoraqiiddiilinidiirmiinid biiyust Yibullaru	esspelisteleler part ent til kalenstellig i mossy't omton. Ostolik
				•
	Sig	ned: Rdon	letty Ion Division	
1/ 1/	1/	Conservati	on Division	n Agent
Reviewed: Harold Sup	Holes TVIsor			

Remarks:

INVOICED

DATE 5/4/62

INV. NO. 4890-W