KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

TO: J. P. Roberts Assistant Director 500 Insurance Building 212 North Market Wichita 2, Kansas

Remarks:

15-147-00633-00-00

12-20-61

File No.	County:	P	hillir)ន		·
Location; SW NE Sec.					(W)	18
Name of Field:						•
I have this date completed supervision of pl	ugging of	*		-		
Lease Name: Morgan	www.www.www.We	11 No.				
Operator's Full Name: W. Pat Simmons					Mana Tanan danah	
Complete Address: 5830 Broadway		•		kkastralatuudistatkistatussi geestiada saga waxi seessi saabkii qaandak	osaczna z com bolen znipodów.	en algument e flores de Regions des Addisses
Plugging Contractor Buick Drg Co	Alto sidem eero Statelik 1904 kan oo Soffield (Sofia Sofia)	record and about the control of the	encrimentalismosmaanalismosootism	new policies a revisi es cano como à travel po arbu sincerais contratary ploide, pe	erningerskillperspriktigsweg	District of the second
Address: Hutchinson, Kans	9. S	Licen	se No.	r/Google-protection-poly-poly-poly-poly-poly-poly-poly-poly		
Oil Well Gas Well Input Well	e (1579-bold politic des clarace con 2016-bon de za activación de conscionación	_SWD We	11	D & A	<u> </u>	
Other well as hereafter indicated;	a sa principal mana a proposa di sala sa principa di sala sa princ	enter account of the second of		Francis er en astenskinnstnindel knivenskinningstrakten bei knivenskallen beskelle beskelle beskelle beskelle	dat tra charmy line valental respect on the	
Was any delay in plugging operations caused	by Conser	vation	Divisi	on Agent?	•	
Yes						
If Yes how long?	Re	ason:	averica successor i noncollegación por se		200 TO SERVICE OF THE PROPERTY OF THE PROPER	
CONNECTION OF THE PROPERTY OF	itraestati kanansi koji ka kulongi kan kanansi kanansi ka ka	naman namani sakasa sa kanaa sa	, Mark esperance republishmental presence and			and the second s
wer to receive the special control of the spe	and construct for the recognised three second constructions and the second constructions are second constructions.	en de la composition	nesse uzen di elemento necessione	mengeri mang kanalahan Kalana Kanalahan kanalahan da kanalahan da kanalahan da kanalahan da kanalahan da kanal		ningan menangan menangan ka
Operation Completed: Hour 9AM Day		Month	12	Year	61	
The above well was plugged as follows:	,					,
8 5/8" 192' circulated with cement		e kilotaka kangan k		Och odda 2004 i 1804 i 1804 i 1805 i 180		
Circulated hole with heavy mud, se	plug a	t 540	, dis	placed 20	sax	cemen:
through drill pipe, heavy mud to 18	30 ', set	plug	and 2	O sax cem	ent,	heavy.
mud to 35', set plug, hulls and fi					-	
		alan u manisan ann asan kalannari saka asan a				Sa training and a sample of
	s en en eller state de la company de la comp		Kalandar Padding and account value of the resident	ngang kalunda pandangan mengalikat dan kecanggan dan dan dan dan kecanggan beranggan beranggan beranggan berang	Notice is contain a proper consistence	
:	,					
	•	Signed:		Level Commence	Leely	to MCCANA Language construction of the language of the languag
			Conse	rvation Div	ision /	Agent