KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

15-153-30157-00-00

STATE CORPORATION COMMISSION

AUG 28 1963
S-25-63
CONSERVATION DIVISION IN Wichita, Kansas

J. P. Roberts
Assitant Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

| Complete Address: 650 Fourth National Bank Bldg., Wichita, Kansas. Lease Name Williams Ranch Well No. 1 Location CSE-NW Sec. 11 Twp. 4 Rge. (E) (W) 36 County Rawlins Total Depth 4860; Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated; Plugging Contractor: Above Address: License No. Operation Completed: Hour 9:30PM Day 24 Month 8 Year 1963 The Above well was plugged as follows: 295'8 5/8" Surface pr pipe, cement circulated. Circulated hole with heavy mud, set plug @ 699' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with \(\frac{1}{4} \) sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with \(\frac{1}{2} \) Sk. hulls and 10 Sx cement to bottom of cellar. | Operator's Full Name | Empire Drilli | ng Company | 7 g an an inscription and a section of the section | nagy variance business of the collection is subjected by many consistent with | wareness and the state of the s | ngayyin a considerate said proved historic da alla da |
|--|--|--|---|--|--|--|--|
| Location CSE-NW Sec. 11 Twp. 4 Rge. (E) (W) 36 County Rawlins Total Depth 4860: Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated: Plugging Contractor: Above Address: License No. Operation Completed: Hour 9:30PM Day 24 Month 8 Year 1963 The Above well was plugged as follows: 295!8 5/8" Surface has pipe, cement circulated. Circulated hole with heavy mud, set plug @ 699' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with ½ sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with ½ Sk. | | | | | | | |
| Location CSE-NW Sec. 11 Twp. 4 Rge. (E) (W) 36 County Rawlins Total Depth 4860: Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated: Plugging Contractor: Above Address: License No. Operation Completed: Hour 9:30PM Day 24 Month 8 Year 1963 The Above well was plugged as follows: 295!8 5/8" Surface has pipe, cement circulated. Circulated hole with heavy mud, set plug @ 699' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with ½ sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with ½ Sk. | Lease Name | Williams Rand | $oldsymbol{1}$ | well No. | Secretario de servicio de la companio del la companio de la companio de la companio del la companio de la companio del la companio de la companio del la compan | | And State Bearing in carbon and States |
| County Rawlins Total Depth 4860' Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated: Plugging Contractor: Above Address: Incense No. Operation Completed: Hour 9:30PM Day 24 Month 8 Year 1963 The Above well was plugged as follows: 295'8 5/8" Surface PRE pipe, cement circulated. Circulated hole with heavy mud, set plug @ 699' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with \(\frac{1}{4}\) sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with \(\frac{1}{2}\) Sk. | | | | | | | |
| Abandoned Oil Well Gas Well Input Well SWD Well D&A X Other well as hereafter indicated: Plugging Contractor: Above Address: License No. Operation Completed: Hour 9:30PM Day 24 Month 8 Year 1963 The Above well was plugged as follows: 295'8 5/8" Surface par pipe, cement circulated. Circulated hole with heavy mud, set plug @ 699' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with \(\frac{1}{4}\) sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', set plug with \(\frac{1}{2}\) Sk. | | | | | | | |
| Other well as hereafter indicated: Plugging Contractor: Above Address: License No. Operation Completed: Hour 9:30PM Day 24 Month 8 Year 1963 The Above well was plugged as follows: 295'8 5/8" Surface pipe, cement circulated. Circulated hole with heavy mud, set plug @ 600' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with ½ sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with ½ Sk. | | | | | | | |
| Plugging Contractor: Above Address: License No. Operation Completed: Hour 9:30PM Day 24 Month 8 Year 1963 The Above well was plugged as follows: 295'8 5/8" Surface **pre pipe, cement circulated. Circulated hole with heavy mud, set plug @ 699' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with ½ sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with ½ Sk. | , • | | | | | | |
| Operation Completed: Hour 9:30PM Day 24 Month 8 Year 1963 The Above well was plugged as follows: 295'8 5/8" Surface in pipe, cement circulated. Circulated hole with heavy mud, set plug @ 699' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with \(\frac{1}{4} \) sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with \(\frac{1}{2} \) Sk. | | | | | | | dependent for the second |
| Operation Completed: Hour 9:30PM Day 24 Month 8 Year 1963 The Above well was plugged as follows: 295'8 5/8" Surface in pipe, cement circulated. Circulated hole with heavy mud, set plug @ 699' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with \(\frac{1}{4} \) sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with \(\frac{1}{2} \) Sk. | Address: | | ellen fillster der ett seg i frest frest statte ster i militärste fillste statt ster ett statte er ett statt s | | License | No. | and an assessment and the second seco |
| 295'8 5/8" Surface ire pipe, cement circulated. Circulated hole with heavy mud, set plug @ 600' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with \(\frac{1}{4} \) sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with \(\frac{1}{2} \) Sk. | Operation Completed: | Hour 9:30pm Da | y 24 _{desident} assanderin errenta err | Month 8 | Year mustamusamusamusamusamusamusamusamusamusamus | 196 | 3 |
| Circulated hole with heavy mud, set plug @ 600' and displaced 20 Sx cement thru DP. Heavy mud to 280', set plug with \(\frac{1}{2} \) sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with \(\frac{1}{2} \) Sk. | | | | , | | | |
| cement thru DP. Heavy mud to 280', set plug with $\frac{1}{4}$ sack hulls and 20 Sx. cement displaced thru DP. Heavy mud to 30', se't plug with $\frac{1}{2}$ Sk. | 2951 8 5/8" Surfa | ce pre pipe, | cement cir | culated. | toponikanandicati Ostotikanasaji saartosianingkanik di citologaan | | |
| Sx. cement displaced thru DP. Heavy mud to 30', set plug with \$ Sk. | Circulated hole wi | th heavy mud, | set plug | @ 6 99 † and | displac | ed 20 S | X |
| SHOOTH AND THE PROPERTY OF THE | cement thru DP. H | eavy mud to 2 | 801, set p | lug with 3 | sack hu | ills and | . 20 |
| SHOOTH AND THE PROPERTY OF THE | | | | | | | |
| | | | | | | | |
| | | | Lette any benedigt conserve we make a tradition to the encoderate discuss discuss from the same | nen-medicinek sastrazziokastokonkonkonkonkonkonkonkonkonkonkonkonkon | | and a second | nagadinga daga na iring nama daga medilikka alikuraka |
| | Amonglid in classificity with Europe Council and particular and control of Council and Co | , | water | november state of the state of | nezavanosti vaneziromaniyana kondynemozik te kultu-elektyne uzanginda kiliku- | ers troubly-constructions states are been constructed by seein | Month of the Security Control of |
| | CLUMP (CLUMP) TO CLUMP CLUMP (CLUMP) AND THE COMPLETE COMPLETE CLUMP (CLUMP) AND THE CLUMP CLUMP (CLUMP) AND THE CLUMP C | as glace as busine his own, guillet a to a batter pass of a driver addressed, as a Visio Response by Commerce and Assessment | | en und kinn da an entre en | | erangerenkingsverkin reskinderen stagten have verkering bisker |) |
| I hereby definit that the apve well was plugged as herein stated. Signed: W. A. Thehole | , | 1 1 | was plugg ed | as herein st | ated. | Dies | hola |
| DATE 8/28/63 Well Plugging Supervisor NV. NO. 766/-w | / | | | the management of the same | Well Plug | ging Sup | ervisor |