## 4 - 032211

R

API Number: 15-023-20,098-00s1 TO: STATE CORPORATION COMMISSION 300'N.of CONSERVATION DIVISION - PLUGGING NW SE SE /4 SEC. 09 , 04 , 40 W 130 SOUTH MARKET, SUITE 2078 1290 feet from S section line WICHITA, KANSAS 67202 990 \_\_\_ feet from E section line Lease: Federal Well # 1-9-440 Operator license# 4570 Operator: Samedan Oil Corporation County: Cheyenne 68.86 9400 N. Broadway - 5. 700 Well total depth 2119 Address: 1650 17th Street - Suite #1100 Denver, CO 80265 OK. Cit. Of. 73/14 Conductor Pipe: \_\_\_\_\_ 0 inch @ \_\_\_\_ 0 feet Surface pipe 8 5/8 Inch @ 226 feet Aband. oil well\_\_\_, Gas well\_x\_, Input well\_\_\_, SWD\_\_\_, D & A\_\_\_\_ Plugging contractor: Halliburton Services License# -Address: Hays, Kansas 67601 Company to plug at: Hour: P.M. Day: 20 Month: March Year: 1997 Plugging proposal received from: Scott Steinke Company: Samedan Oil Corporation Phone: Were: Order 180 sxs cement 60/40 pozmix - 6% gel. Plugging Proposal Received by: Carl Goodrow Plugging operations attended by agent? All[ X ], Part[ ], None[ Completed: Hour: 12:00 P.M., Day: 20, Month: March , Year: 1997 Actual plugging report: 8 5/8" set at 226' w/200 sxs. 4 1/2" set at 1400' w/125 sxs. Prod. Perfs at 1254' - 1290'. Mixed and pumped down 4 1/2" 120 sxs cement to Max. P.S.I. 1000#. S.I.P. 850#. Mixed and pumped down 8 5/8" annulus 60 sxs cement to Max. P.S.I. 1000#. Held. Plug complete. Remarks: \_ Condition of casing(in hole): GOOD\_\_\_\_\_\_ BAD\_\_ Anhy.plug: YES\_\_\_ Bottom plug(in place): YES\_\_\_\_, CALC\_\_\_, NO\_\_\_ Dakota plug: YES\_X\_, NO\_\_\_ Plugged through TUBING\_\_\_\_\_, CASING . Elevation: ] observe the plugging. (agent) APR 0 4 1997 Form CP-2/3

3-2 OMAY 21 1997