4-041838 15-147-00518-00-00

API Number:15- - 10-12-49 TO: STATE CORPORATION COMMISSION NE SW SW /4 SEC. 30 , 05 S, 20 W CONSERVATION DIVISION - PLUGGING \_\_\_\_\_ feet from S section line 130 SOUTH MARKET, SUITE 2078 990 WICHITA, KANSAS 67202 4290 feet from E section line Operator license# 5447 Lease: States B Well # 6 County: Phillips //9.30 Operator: OXY USA, Inc. 

 Well total depth
 3671
 feet

 Conductor Pipe:
 0
 inch @
 0
 feet

 Address: P.O. Box 300 Tulsa, Oklahoma 74102-0300 Surface pipe 8 5/8 Inch @ 205 feet w/250 sxs.cmt.Aband. oil well\_x, Gas well\_\_, Input well\_, SWD\_, D & A\_\_ Plugging contractor: Halliburton Cementing, Inc. License#\_ Address: Hays, Kansas 67601 Company to plug at: Hour: 3:00 P.M. Day: 6 Month: November Year 1996 Plugging proposal received from: Jim Nowell Company: OXY USA, Inc. Phone: 918-561-3564 Were: 5 1/2" casing set at 3670' w/150 sxs. Open hole. Plugging Proposal Received by: Dennis L. Hamel Plugging operations attended by agent? All[ ], Part[ X ], None[ ] Hour: <u>5:30 P.M.</u>, Day: <u>6</u>, Month: <u>November</u>, Year: <u>1996</u> Completed: Actual plugging report: Dug out casing and orange peeled 5 1/2" to 8 5/8" casing. Install 2" riser to surface. Rigged up H.L.S. & perf at 1170' and 1810' with 2 spf. MIRU Murfin Drilling, RIH with 2 3/8" tubing. Open ended to 3620'. Pumped 65 sxs MIDCON 2 with 2% CC and 300# cottonseed hulls. Pulled 48 jts. to 2100'. Pumped 65 sxs cement & 200# hulls. Pulled tubing to 600'. Pumped 40 sxs cement and circulated to surface. POOH with rest of tubing. Hooked up to 5 1/2" casing and pumped 20 sxs cement. Max. P.S.I. 600#. S.I.P. 450#. Hooked up to 8 5/8" casing and pumped 40 sxs MIDCON 2 cement with 2% CC and 100# hulls. Max. P.S.I. 175#. S.I.P. 25#. Total cement used 240 sxs. Remarks: Allied Cementing. Condition of casing(in hole): GOOD\_X BAD\_ Anhy.plug: YES X NO Bottom plug(in place): YES\_X\_, CALC\_\_\_\_\_, NO\_\_\_ Dakota plug: YES\_\_\_X\_, NO\_\_\_ Plugged through TUBING X , CASING ... Elevation: 2241 K.B.

I did 0 1 CdE Dt[ ] observe the plugging.

DATEJAN 101

110)-

Nennis J. Hame
(agent)

Form CP-2/3