X 4-**041842**

15-137-00598-00-00

TO:	API Number: 15 06-23-57
STATE CORPORATION COMMISSION	
CONSERVATION DIVISION - PLUGGING	SW_NE_NW /4 SEC. 36 , 05 S, 21 W
130 SOUTH MARKET, SUITE 2078	feet from S section line
WICHITA, KANSAS 67202	feet from E section line
Operator license# 5447	Lease: Kitzke Well #6
Operator: OXY USA, Inc.	County: Norton
0,014,011, 1110,	
Address: P.O. Box 300	Well total depth 3664 feet
Tulsa, Oklahoma 74102-0300	Well total depth 3664 feet Conductor Pipe: 0 inch @ 0 feet
	Surface pipe 8 5/8 Inch @ 240 feet
	w/200 sxs.cmt.
	W/200 SKS.CHC.
Aband. oil well_x_, Gas well, Input well	_, SWD, D & A
Plugging contractor: Halliburton Cementing,	Inc. License#
·	
Address: Hays, Kansas 67601	
Company to plug at: Hour: 1:00 P.M. Day: 7 Month	: November Year 1996
Plugging proposal received from: Jim Nowell	
Company: OXY USA, Inc.	Phone: 918-561-3564
Were: 5 1/2" casing set at 3648' w/400 sxs.	
D.V. at 1837' w/400 sxs - surface.	
	TY off
	CT 100 / 100
Plugging Proposal Received by: Dennis L. Hamel	
Plugging operations attended by agent? All[], Part[X], None[]	
	· · · · · · · · · · · · · · · · · · ·
Completed: Hour: 2:30 P.M., Day: 7, Month:	November , Year: 1996 /
Actual plugging report: Dug out casing and orang	e peeled 5 1/2" to 8 5/8" casing. Install
2" riser to surface. This well has a D.V. tool at 1837'. Cemented with 400 sxs 50/50 pozmix	
and 200 cu ft strata-crete. MIRU Murfin Drilling, R.I.H. with 2 3/8" tubing. Open ended to	
3620'. Pumped 65 sxs MIDCON 2 with 2% C.C. and 200# cottonseed hulls. Pulled 48 jts. to	
2150'. Pumped 65 sxs cement and 200# hulls. Pu	11ed tubing to 600'. Pumped 25 sxs cement
and circulated to surface. POOH with rest of tubing. Hooked up to 5 1/2" casing and pumped	
20 sxs cement. Max. P.S.I. 500#. S.I.P. 275#. Hooked up to 8 5/8" casing and pumped 2 sxs	
MIDCON 2 cement with 2% C.C. and zero lbs hulls. Rig down. Total cement used 175 sxs.	
Remarks: Allied Cementing.	
Condition of casing(in hole): GOOD X BAD Anhy.plug: YES X NO	
Bottom plug(in place): YES X , CALC, NO	
Plugged through TUBING X , CASING .	Elevation: 2220 G.L.
<pre>I did[x] / did not[] observe the plugging.</pre>	Kennes J. Hamel
	A. (agent)

ND,

4-041842 15-137-00598-00-00 API Number: 15- - 06-23-57 STATE CORPORATION COMMISSION **SW NE NW** /4 SEC. 36 , 05 S, 21 W CONSERVATION DIVISION - PLUGGING 130 SOUTH MARKET, SUITE 2078 ___ feet from S section line 3630 WICHITA, KANSAS 67202 4290 _ feet from E section line Lease: Kitzke Well # 6 Operator license# 5447 County: <u>Norton</u> //9.08 Operator: OXY USA, Inc. Address: P.O. Box 300 Well total depth 3664 feet Conductor Pipe: 0 inch @ 0 feet Tulsa, Oklahoma 74102-0300 Surface pipe 8 5/8 Inch @ 240 feet w/200 sxs.cmt. Aband. oil well_x_, Gas well____, Input well___, SWD___, D & A___ Plugging contractor: Halliburton Cementing, Inc. License# -Address: Hays, Kansas 67601 Company to plug at: Hour: 1:00 P.M.Day: 7 Month: November Year 1996 Plugging proposal received from: Jim Nowell Company: OXY USA, Inc. Phone: 918-561-3564 Were: 5 1/2" casing set at 3648' w/400 sxs. D.V. at 1837' w/400 sxs - surface. Plugging Proposal Received by: Dennis L. Hamel Plugging operations attended by agent? All[], Part[X], None[Hour: 2:30 P.M., Day: 7, Month: November, Year: 1996 Completed: Actual plugging report: Dug out casing and orange peeled 5 1/2" to 8 5/8" casing. Install 2" riser to surface. This well has a D.V. tool at 1837'. Cemented with 400 sxs 50/50 pozmix and 200 cu ft strata-crete. MIRU Murfin Drilling, R.I.H. with 2 3/8" tubing. Open ended to 3620'. Pumped 65 sxs MIDCON 2 with 2% C.C. and 200# cottonseed hulls. Pulled 48 jts. to 2150'. Pumped 65 sxs cement and 200# hulls. Pulled tubing to 600'. Pumped 25 sxs cement and circulated to surface. POOH with rest of tubing. Hooked up to 5 1/2" casing and pumped 20 sxs cement. Max. P.S.I. 500#. S.I.P. 275#. Hooked up to 8 5/8" casing and pumped 2 sxs MIDCON 2 cement with 2% C.C. and zero lbs hulls. Rig down. Total cement used 175 sxs. Remarks: Allied Cementing. Condition of casing(in hole): GOOD_X BAD____ Anhy.plug: YES X NO_ Bottom plug(in place): YES_X_, CALC_____, NO___ Dakota plug: YES X , NO 2220 G.L. Plugged through TUBING X , CASING_ Elevation: Kenny J. Hamel

] observe the plugging.

100,

(agent)

Form CP-2/3