STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
211 No. Broadens
Wichita Kangas

15-137-00258-00-00

WELL PLUGGING RECORD

NORTH	T 405 T			ity. Sec. <u>13</u>		•	\ YY
	Location as "N	E/CNW%SW%"	or footage fr	om lines <i>SI</i>	SE NE		
	Lease Owner_	Jones,	Shelby	irne & Fai	mer, Inc		
	Lease Name	MOORE Russe		2 9 7 9	·	_ Well No	
	Character of W	/ell (completed	as Oil Coc	or Dry Hole) <i>Di</i>	~7 <i>1</i>		
	Date well com	pleted	On, Gas (3-23		19 56
		Application for plugging filed 3-23					19 56
							19 56
							19 <u>56</u>
	Plugging compl		Lor produci-	ng formation Dr	3 <u>-23</u>		_19_ 56
			or producit	ig formation	<i>}</i>		
	If a producing	well is abandon	ed, date of l	ast production			19
Locate well correctly on above	Was permission	n obtained from	the Conserv	vation Division of	its agents befo	ore plugging	was con
Section Plat	menced?	<u></u>	<i>es</i>				
ne of Conservation Agent who sur ducing formation	pervised plugging of thi	s well	5	<u> </u>	lon Pet t y	20	00
w depth and thickness of all wate	er, oil and gas formation	epm to top	Botton	m	Total Depth of	Well 386	Fee
						r	
OIL, GAS OR WATER RECOR	DS				(CASING RE	CORD
FORMATION	CONTENT	FROM	то	SIZE	PUT IN	PULLED	TUO
				8-5/8"	235 1	None	
			<u> </u>				
				 	P		
				 			
Filled hole with				of same and depth			
Pushed plug to 2	heavy mud	of plug					
Pushed plug to 2 Dumped 1/2 sack	heavy mud 225 ' hulls on top						
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c	heavy mud 25! hulls on top ement and du						
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t	heavy mud 25' hulls on top ement and du						
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t	heavy mud 25' hulls on top ement and du						
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4	heavy mud 25; hulls on top ement and du						
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa	heavy mud 25! hulls on top ement and du op ot hulls	mped on	t•p of	hulls			
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa	heavy mud 25! hulls on top ement and du op ck hulls ement and fi	mped on	t•p of	hulls			
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa	heavy mud 25! hulls on top ement and du op ck hulls ement and fi	mped on	t•p of	hulls			
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa	heavy mud 25! hulls on top ement and du op ck hulls ement and fi	nped on	top of	hulls p with sa			
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c	heavy mud 25! hulls on top ement and du op ck hulls ement and fi	nped on	top of	hulls p with sa			
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c	heavy mud 25; hulls on top ement and du op ck hulls ement and fi	nped on 1led hold description is necess helburne	top of	hulls p with sa			
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c	heavy mud 25! hulls on top ement and du op ck hulls ement and fi (If additional of Jones, S	nped on 1led hold description is necess helburne	top of	hulls p with sa			
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c	heavy mud 25! hulls on top ement and du op of ck hulls ement and fi (If additional of) Russell,	nped on Lled holi lescription is necess helburne Kansas	top of top of	hulls p with sa			
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c	heavy mud 225! hulls on top ement and du cop ck hulls ement and fi (If additional of Jones, Si Russell,	nped on Lled hold lescription is necess helburne Kansas	top of top of top of the to the top of	hulls p with sa of this sheet) er, Inc.	me.		
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c e of Plugging Contractor ress TE OF	heavy mud 225! hulls on top ement and du cop ck hulls ement and fi (If additional of Jones, Sones, S	nped on Lled holi lescription is necess helburne Kansas	top of top of ary, use BACK & Farm	p with sa of this sheet)	me.	f. No. al.	lescribed
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c e of Plugging Contractor ress TE OF	heavy mud 225! hulls on top ement and du cop ck hulls ement and fi (If additional of the second seco	lled holi clescription is necess helburne Kansas NTY OF RE (general seconds)	top of	p with see of this sheet) er, Inc.	ss. or operator) o	f. No. al.	lescribed
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c Te of Plugging Contractor Tess Te of Kansas John 0. being first duly sworn on oath,	heavy mud 225! hulls on top ement and du cop (If additional of the same are true and the same are true an	lled holi lescription is necess helburne Kansas NTY OF	top of	p with see of this sheet) er, Inc.	ss. or operator) o	f. No. al.	lescribed g of the
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c Te of Plugging Contractor Tess Te of Kansas John 0. being first duly sworn on oath,	heavy mud 225! hulls on top ement and du cop (If additional of the same are true and the same are true an	lled holi clescription is necess helburne Kansas NTY OF RE (general seconds)	top of	p with see of this sheet) er, Inc.	ss. or operator) o	of the above-c	lescribed
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c Te of Plugging Contractor_ ress	heavy mud 225! hulls on top ement and du cop (If additional of the same are true and the same are true an	lled holi lescription is necess helburne Kansas NTY OF	top of	p with sa of this sheet) er, Inc. Russel.	ss. or operator) of herein container	of the above-c	lescribed
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c Te of Plugging Contractor ress TE OF	heavy mud 25! hulls on top ement and du op (If additional, Jones, S. Russell, COUNTARMER says: That I have knot the same are true and	lled holi lescription is necess helburne Kansas NTY OF	top of top of	of this sheet) er, Inc. Russel. April	ss. or operator) of herein container L. Kansa	of the above-cod and the lo	described og of the
Pushed plug to 2 Dumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Dumped in 1/2 sa Mixed 10 sacks c te of Plugging Contractor ress TE OF	heavy mud 25! hulls on top ement and du op (If additional, Jones, S. Russell, COUNTARMER says: That I have knot the same are true and	lescription is necess helburne Kansas NTY OF	top of top of	of this sheet) er, Inc. Russel. April	ss. or operator) of herein container L. Kansa	of the above-cod and the lo	lescribed og of the
Pushed plug to 2 Bumped 1/2 sack Mixed 15 sacks c Filled hole to t Pushed plug to 4 Bumped in 1/2 sa Mixed 10 sacks c ne of Plugging Contractor lress ATE OF	heavy mud 225! hulls on top ement and du cop (If additional of Jones, S.) Russell, COUNTARMER says: That I have known the same are true and (If additional of the same are true and the same	lescription is necess helburne Kansas NTY OF	top of top of	p with sa of this sheet) er, Inc. Russel.	ss. or operator) of herein container L. Kansa	of the above-cod and the lo	og of the

PLUGGING
PL SEC 13 1 5 R 24W
WORK MOE 48 LWE 13

4-4-56