

DISTRICT CONSERVATION AGENT'S REPORT

15-039-00044-00-00

*R*

TO:

State Corporation Commission  
Conservation Division  
800 Bitting Building  
Wichita, Kansas

FILE NO. \_\_\_\_\_

LOCATION NW NW SW

SEC. 20 TWP. 5 RGE. 26

*W*

Dry Hole X Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have today completed supervision of plugging of:

Well No. 1 Lease \_\_\_\_\_ Bader \_\_\_\_\_

Operator Herndon Drg Co Address Lyons, Kans

Field \_\_\_\_\_ County ~~Phillips~~ Decatur

Total Depth 4235 Feet.

(Describe briefly the manner in which the well was plugged)

8 5/8" at 250' circulated with cement.

Filled with rotary mud to 240', set cementing plug, 1 sack  
hulls and 15 sax cement, filled with mud to 40', set wood  
plug 1/2 sack hulls and 10 sax cement to bottom cellar.

RECEIVED  
STATE CORPORATION COMMISSION  
JUN 16 1951  
CONSERVATION DIVISION

6-16-51

*Edson*  
District Conservation Agent

Date 6-14-51

**PLUGGING**  
FILE SEC. 20 TWP. 5 RGE. 26  
BOOK PAGE 88 LINE 19

*F*

DISTRICT CONSERVATION AGENT'S REPORT

15-039-00044-00-00

TO:

State Corporation Commission  
Conservation Division  
800 Bitting Building  
Wichita, Kansas

FILE NO. \_\_\_\_\_

LOCATION 7W. 70 - Sec

SEC. 20 TWP. 5 RGE. 26

Dry Hole  Abandoned Oil Well \_\_\_\_\_ Abandoned Gas Well \_\_\_\_\_

I have today completed supervision of plugging of:

Well No. \_\_\_\_\_ Lease Bader

Operator Herndon Dr Co Address Lyns, Kans

Field \_\_\_\_\_ County Deeatur

Total Depth 2735 Feet.

(Describe briefly the manner in which the well was plugged)

Since I showed Norton Co instead  
of Deeatur.  
Please make correction on  
my report.

RECEIVED  
STATE CORPORATION COMMISSION

JUN 16 1951 6-16-51

[Signature]  
CONSERVATION DIVISION  
Wichita, Kansas  
District Conservation Agent

Date \_\_\_\_\_