

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

15-065-00879-00-00

WELL PLUGGING APPLICATION FORM

File One Copy

Lease Owner Jones, Shelburne & Farmer, Inc. Address Russell, Kansas  
(Applicant)  
Lease (Farm Name) JENKINS Well No. 1  
Well Location SW SW SW Sec. 33 Twp. 6 Rge. (E) - (W) 21  
County Graham Field Name (if any) Wildcat  
Total Depth 3746 Oil Gas Dry Hole Dry  
Was well log filed with application? Yes If not, explain: \_\_\_\_\_

Date and hour plugging is desired to begin 4-25-56 9:30 PM

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner \_\_\_\_\_

Raymond Kaba Address Plainville, Kansas

Plugging Contractor Jones, Shelburne & Farmer, Inc.

Plugging Contractor's License No. \_\_\_\_\_

Address Russell, Kansas

Invoice covering assessment for plugging this well should be sent to \_\_\_\_\_

Jones, Shelburne & Farmer, Inc. Address Russell, Kansas

and payment will be guaranteed by applicant.

RECEIVED  
STATE CORPORATION COMMISSION

MAY 1956

CONSERVATION DIVISION  
WICHITA, KANSAS

John W. Farmer  
Applicant or Acting Agent

Date April 27, 1956

53-56

**PLUGGING**  
FILE SEC 33 T 6 R 21W  
BOOK PAGE 57 LINE 21





STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

15-065-00879-00-00

April 27, 1956

Well No. 1  
Lease Jenkins  
Description SW SW SW 33-6-21W  
County Graham  
File No. 57-21

Jones, Shelburne, & Farmer, Inc.  
Russell, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Hays, Kansas.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

By S. S. Greider  
S. S. Greider  
WELL PLUGGING SUPERVISOR

cc:  
District Plugging Supervisor