
STATE OF KANSAS STATE CORPORATION COMMISSION

Give Al Make Re Mail or Co St 24



WELL PLUGGING RECORD

All Information Completes Required Affidavit	5	Sheridan	COU	mey a wood			
or Deliver Report to	Location a	s "NE/CN	w ₄ sw ₄	" or foota	ge from l	ines	
Conservation Division		NW SW	SE				
State Corporation Comm.	Lease Owne	er pe	etrole	eum Managem	ent, Inc.		
245 North Water	Lease Name	•	Adell	<i>#</i> 205	W	ell No.	
Wichita, KS 67202	Office Add	ires's	Great	Bend, Kan	sas 67530		
	Character	of Well	(Comp	leted as 0	il, Gas o	r Dry H	ole)
	Date Well	complete	ed .	-			19
	Applicatio	on for pl	uggir	g filed_			19
	Application	on for pl	Luggir	g approved			19
	Plugging c			5/25/76			19 19
	Plugging C	completed	ì	6/10/76		a forms	
				of well or depleted.			
	If a produ	ucing wel	ll is	abandoned,	date of	last pr	oduction 19
	Vas permis	ssion obt	tained	i from the	Conservat	ion Div	ision o
Locate well correctly on above Section Plat	its agents	s before	plugg	ging was co	mmenced?	yes	
of Conservation Agent who	o supervised plu	ugging of	f this	s well Bal	lthazor		
ucing formation	Depth	to top	,	SOL LOM	Total De	epth of	Well_3
depth and thickness of a	ll water, oil ar	nd gas ic	ormati	lons.			
IL, GAS OR WATER RECORDS						CASING	RECORD
FURNATUM	CONTENT	Finales	10	SUZE	FIST NG	PULL	ED OUT
				8-5/8	219		one
				5111	3818	12	181
Describe in detail the man placed and the method or	methods used in	introdu	cing	it into the	e porg.	II ceme	e mud fl nt or ot eet to
placed and the method or gs were used, state the ch feet for each p	methods used in paracter of same plug set.	introdu and dep	cing th pl	it into the aced, from	e hold.	II ceme	at or or
placed and the method or s were used, state the character feet for each p	methods used in paracter of same olug set. ran 5 sacks cem	introdu and dep	cing th pl	it into the aced, from	e hold.	II ceme	at or or
placed and the method or gs were used, state the character for each p Sanded to 3625' and	methods used in paracter of same olug set. ran 5 sacks cem pulled 39 join	ent. Sh	cing th pl ot pi eezed	aced, from pe at 2830' well with	e hold.	II ceme	at or or
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls. 70 sa	methods used in paracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17	ent. Sh ts. Squ sacks ge	cing th pl ot pi eezed	aced, from pe at 2830' well with	e hold.	II ceme	at or or
placed and the method or gs were used, state the character for each p Sanded to 3625' and	methods used in paracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17	ent. Sh ts. Squ sacks ge	cing th pl ot pi eezed	aced, from pe at 2830' well with	e hold.	II ceme	at or or
placed and the method or ss were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with	methods used in paracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17	ent. Sh ts. Squ sacks ge	cing th pl ot pi eezed	aced, from pe at 2830' well with	e hold.	II ceme	at or or
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls. 70 sa	methods used in paracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17	ent. Sh ts. Squ sacks ge	cing th pl ot pi eezed	aced, from pe at 2830' well with	e hold.	II ceme	at or or
placed and the method or ss were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with	methods used in paracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17	ent. Sh ts. Squ sacks ge	cing th pl ot pi eezed	aced, from pe at 2830' well with	e hold.	II ceme	at or or
placed and the method or ss were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with	methods used in paracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17	ent. Sh ts. Squ sacks ge	cing th pl ot pi eezed	aced, from pe at 2830' well with	e hold.	II ceme	at or or
placed and the method or ss were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with	methods used in paracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17	ent. Sh ts. Squ sacks ge	cing th pl ot pi eezed	aced, from pe at 2830' well with	e hold.	II ceme	at or or
placed and the method or ss were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE.	methods used in haracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cemen	e and deposits. Squ sacks geat.	cing th pl ot pi eezed l and	it into the aced, from pe at 2830' well with released	e hold.	for the state of t	at or or
placed and the method or ss were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE.	methods used in haracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cemen	ent. Shets. Squesacks gent.	cing th pl ot pi eezed l and	it into the aced, from pe at 2830' well with released	e hold.	for the state of t	at or or
placed and the method or s were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional	methods used in haracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cemen	ent. Shets. Squesacks gent.	cing th pl ot pi eezed l and	it into the aced, from pe at 2830' well with released	e hold.	for the state of t	at or or
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor	methods used in haracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cemen l description is KELSO CASING CHASE, KAN	e and deposent. Shots. Squesacks gent. s necessacks pulling	cing th pl ot pi eezed l and	it into the aced, from pe at 2830' well with released	e hold.	for the state of t	at or or
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor	methods used in haracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cemen MELSO CASING CHASE, KAN	e and deposits. Squacks gent. s necessary Pulling	cing th pl ot pi eezed l and	pe at 2830' well with released	this she	eet)	eet to
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D	methods used in paracter of same olug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cemen CHASE, KAN KANSAS COUNT	e and deposits. Squacks gent. s necessary of RICO (6)	cing th pl ot pi eezed l and	it into the aced, from pe at 2830' well with released	this she	eet)	bove-describ
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D well, being first duly sworm on cath,	methods used in paracter of same plug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cemen KELSO CASING CHASE, KAN KANSAS COUNT DARRELL KELSO	ent. Sherreduce and deposits. Squares gent. Sherreduce and sacks gent. Sher	cing th pl ot pi eezed l and ary, u	it into the aced, from pe at 2830' well with released ase BACK of of owner) or (otements, and materials)	this she	eet)	bove-describ
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D	methods used in paracter of same plug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cement KELSO CASING CHASE, KAN KANSAS OARRELL KELSO Lays: That I have known at the same are true and contact	ent. Sh ts. Squ sacks ge t. sa	cing th pl ot pi eezed l and ary, u	it into the aced, from pe at 2830' well with released ase BACK of of owner) or (otements, and materials)	this she	eet)	bove-describ
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D well, being first duly sworm on cath,	methods used in paracter of same plug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cement KELSO CASING CHASE, KAN KANSAS OARRELL KELSO Lays: That I have known at the same are true and contact	ent. Sherreduce and deposits. Squares gent. Sherreduce and sacks gent. Sher	cing th pl ot pi eezed l and ary, u	e at 2830' well with released see BACK of of owner) or (or tements, and mate cod)	this she	eet)	bove-describ
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D well, being first duly sworm on cath,	methods used in paracter of same plug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cement KELSO CASING CHASE, KAN KANSAS OARRELL KELSO Lays: That I have known at the same are true and contact	ent. Sh ts. Squ sacks ge t. sa	cing th pl ot pi eezed l and ary, u	e at 2830' well with released see BACK of of owner) or (or tements, and mate cod)	this she	eet)	bove-describ
placed and the method or gs were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D well, being first duly sworm on cath,	methods used in paracter of same plug set. ran 5 sacks cem, pulled 39 join packs cement, 17 h 60 sacks cemen l description is KELSO CASING CHASE, KAN KANSAS COUNT PARSELL KELSO (SI	ent. Sh ts. Squ sacks ge t. sa	cing th pl ot pi eezed l and ary, u	e at 2830' well with released see BACK of of owner) or (or tements, and mate cod)	this she	eet)	bove-describ
placed and the method or s were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D well, being first duly swom on eath, above-described well as filed and the	methods used in paracter of same plug set. ran 5 sacks cem, pulled 39 join packs cement, 17 h 60 sacks cemen l description is KELSO CASING CHASE, KAN KANSAS COUNT PARSELL KELSO (SI	ent. Sh ts. Squ sacks ge tt. snecessa pulling NSAS rroi RIC ledge of the i	cing th pl ot pi eezed l and ary, u	it into the aced, from pe at 2830' well with released see BACK of the control of control	this she	eet)	bove-describ
placed and the method or s were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D well, being first duly swom on eath, above-described well as filed and the	methods used in paracter of same plug set. ran 5 sacks cem, pulled 39 join packs cement, 17 h 60 sacks cemen l description is KELSO CASING CHASE, KAN KANSAS COUNT PARSELL KELSO (SI	ent. Sh ts. Squ sacks ge tt. snecessa pulling NSAS rroi RIC ledge of the i	cing th pl ot pi eezed l and ary, u	it into the aced, from pe at 2830' well with released see BACK of the control of control	this she	eet) or) of the all stained and	bove-describ
placed and the method or s were used, state the ch feet for each p Sanded to 3625' and 2015', 1530', 1210', 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D well, being first duly swom on eath, above-described well as filed and the	methods used in paracter of same plug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cemen l description is KELSO CASING CHASE, KAN KANSAS COUNT DARRELL KELSO says: That I have known at the same are true and count at the same are true at the same at t	ent. Sh ts. Squ sacks ge at. s necessa pulling ysas rol RIC ledge of the legentary of	cing th pl ot pi eezed l and ary, u	it into the aced, from pe at 2830' well with released see BACK of the control of control	this she	eet) or) of the all stained and	bove-describ
placed and the method or s were used, state the ch feet for each p Sanded to 3625! and 2015!, 1530!, 1210!, 3 sacks hulls, 70 sa plug, displaced with PLUGGING COMPLETE. (If additional e of Plugging Contractor STATE OF R. D Well, being first duly sworm on eath, above described well as filed and the	methods used in haracter of same plug set. ran 5 sacks cem, pulled 39 join acks cement, 17 h 60 sacks cemen l description is KELSO CASING CHASE, KAN KANSAS COUNT DARRELL KELSO says: That I have knowled the same are true and count (Simple count is says: 14th	ent. Sh tent. Sh tent. Squ sacks ge tt. s necessa g PULLING NSAS TY OI RIC ledge of the f correct. So h lightere)	cing th pl ot pi eezed l and ary, u	it into the aced, from pe at 2830' well with released see BACK of the control of control	this she	eet) or) of the all stained and	bove-describ