Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4

JUN 2 0 2005 Type or Print on this Form
Form must be Signed

		Inc.			API Number: 15	- 175-21152 ~ O O ~ O O
Address: 155 N. Market, Suite 500				Lease Name: McCoy		
Phone: (316) 264 -8378 Operator License #: _6044					Well Number: 1-25	
					Snot Location (QQ)	QQ): <u>S/2</u> - <u>N/2</u> - <u>N</u>
Type of Well: Gas (Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) Ocket #:						North / South Section Lin
The plugging proposa	il was approved on: 06-0	8-2005		(Date)	2.000	East / West Section Lin
by: Jim Holland (KCC District Agent's Name)					Sec. 25 Twp. 31 S. R. 32 East V	
Is ACO-1 filed? ✓ Yes No If not, is well log attached? Yes No					Seward	
لست	s): List All (If needed attach	_	l-manual 1		Data Well Complete	1 1/21/1990 2-1-1991
Morrow	Depth to Top: .	5,400' Botto	_{m:} <u>5,520'</u>	_{T.D.} <u>5,520'</u>	Date Well Complete	06-08-2005
	Depth to Top: _	Botto	m:	T.D	Plugging Commenc	d:_06-13-2005
	Depth to Top:	Botto	m:	T.D	Plugging Completed	d: 00 10 2000
Show depth and thick	ness of all water, oil and	gas formations.				
	or Water Records				Surface Conductor & Pro	
Formation	Content	From	То	Size	Put In	Pulled Out
Morrow	Gas .	5,400'	5,520'	8-5/8"	1,673'	0
				4-1/2"	5,895'	1,978'
					,	,
	manner in which the well		-	•		•
hole. If cement or oth Mixed and pump hole with mud. mud. Mix and pu 450'. Pulled remain Name of Plugging Co	ner plugs were used, state ed 200 lbs. hulls and TOOH and lay dowr ump 50 sacks cement	the character of 20 sacks central tubing. She from 1700' to d 10 sacks of Horton Pluggi OK 73951 Stelbar Oil	f same depth period of 4-1/2" can be 1550'. Purcement and sing, Inc9731 Corporati	olaced from (botto -3/8" tubing to sing off at 1,9 lled casing to olug from 40' to	om), to (top) for each o plug perforations 978'. Pulled casr 550'. Mix and pur	from 5,414' to 5,214'. Circulate hole was 30 sacks cement from 550 and cap 8-5/8", 3 ft below surface
hole. If cement or oth Mixed and pump hole with mud. mud. Mix and pu 450'. Pulled remain Name of Plugging Co	ner plugs were used, state ed 200 lbs. hulls and TOOH and lay down ump 50 sacks cement ainder of casing. Mixed ontractor: Sargent and HOOX 49BA Tyrone,	the character of 20 sacks central tubing. Shot from 1700' to d 10 sacks of Horton Pluggion OK 73951 Stelbar Oil	f same depth period of 4-1/2" can be 1550'. Purcement and sing, Inc9731 Corporati	olaced from (botto -3/8" tubing to sing off at 1,9 lled casing to olug from 40' to	om), to (top) for each oplug perforations 978'. Pulled cash 550'. Mix and pur operations of surface. Cut off a	plug set. from 5,414' to 5,214'. Circulate hole was 30 sacks cement from 550 and cap 8-5/8", 3 ft below surface
hole. If cement or oth Mixed and pump hole with mud. mud. Mix and pu 450'. Pulled remain Name of Plugging Co Address: RR 1, B	her plugs were used, state ed 200 lbs. hulls and TOOH and lay down ump 50 sacks cement ainder of casing. Mixed ontractor: Sargent and I ox 49BA Tyrone, onsible for Plugging Fees: County	the character of 20 sacks central tubing. Shot from 1700' to d 10 sacks of Horton Pluggion OK 73951 Stelbar Oil	f same depth period of 4-1/2" can be 1550'. Purcement and sing, Inc9731 Corporati	olaced from (botto -3/8" tubing to sing off at 1,9 lled casing to plug from 40' to on, Inc.	om), to (top) for each oplug perforations 978'. Pulled casr 550'. Mix and pur o surface. Cut off a	plug set. from 5,414' to 5,214'. Circulate from 5,414' to 5,214'. Circulate ng to 1700'. Circulate hole was mp 30 sacks cement from 550' and cap 8-5/8", 3 ft below surfact
hole. If cement or oth Mixed and pump hole with mud. mud. Mix and put 450'. Pulled remains and Plugging Control RR 1, But Name of Party Responstate of Kansas Roscoe L. Mendesworn on oath, says:	ner plugs were used, state ed 200 lbs. hulls and TOOH and lay down ump 50 sacks cement ainder of casing. Mixed ontractor: Sargent and I ox 49BA Tyrone, onsible for Plugging Fees: County enhall	the character of 20 sacks central tubing. She that from 1700' to d 10 sacks of Horton Pluggi OK 73951 Stelbar Oil	f same depth penent down 2 tot 4-1/2" cat to 1550'. Purcement and sing, Inc9731 Corporation	olaced from (botto -3/8" tubing to sing off at 1,5 lled casing to plug from 40' to on, Inc. , ss. (Employee of	om), to (top) for each oplug perforations on plug perforations on plug perforations on the purpose of the perforations on the perforation of the p	plug set. from 5,414' to 5,214'. Circulate hole with the sacks cement from 550' and cap 8-5/8", 3 ft below surface.
hole. If cement or oth Mixed and pump hole with mud. mud. Mix and put 450'. Pulled remains and Plugging Control RR 1, But Name of Party Responstate of Kansas Roscoe L. Mendesworn on oath, says:	ther plugs were used, state and 200 lbs. hulls and TOOH and lay down tump 50 sacks cement and of casing. Mixed satisfactor: Sargent and hox 49BA Tyrone, consible for Plugging Fees: County enhall That I have knowledge of	the character of 20 sacks central tubing. She that from 1700' to d 10 sacks of Horton Pluggi OK 73951 Stelbar Oil	f same depth penent down 2 tot 4-1/2" cat to 1550'. Purcement and sing, Inc9731 Corporation	olaced from (botto -3/8" tubing to sing off at 1,5 lled casing to plug from 40' to on, Inc. , ss. (Employee of	om), to (top) for each oplug perforations on plug perforations on plug perforations on the purpose of the perforations on the perforation of the p	plug set. from 5,414' to 5,214'. Circulate hole with the first sacks cement from 550' and cap 8-5/8", 3 ft below surfact sacks cemen
hole. If cement or oth Mixed and pump hole with mud. mud. Mix and put 450'. Pulled remains and Plugging Control RR 1, But Name of Party Responstate of Kansas Roscoe L. Mendesworn on oath, says:	ther plugs were used, state and 200 lbs. hulls and TOOH and lay down tump 50 sacks cement and of casing. Mixed satisfactor: Sargent and hox 49BA Tyrone, consible for Plugging Fees: County enhall That I have knowledge of	the character of 20 sacks centre tubing. She from 1700' to d 10 sacks of the Horton Pluggion OK 73951 Stelbar Oil Sedgwick Sedgwick (Signature)	f same depth prent down 2 ot 4-1/2" car o 1550'. Purcement and sing, Inc9731 Corporation	on, Inc. (Employee of ers herein contains)	om), to (top) for each oplug perforations on plug perforations on plug perforations on the purpose of the perforations on the perforation of the p	plug set. a from 5,414' to 5,214'. Circulate hole with the from 550's and cap 8-5/8", 3 ft below surfaction on above-described well, being first a above-described well is as filed, an according to the first and cap 8-5/8".
hole. If cement or oth Mixed and pump hole with mud. mud. Mix and pu 450'. Pulled remain Name of Plugging Control Address: RR 1, Bushame of Party Responsible of Kansas Roscoe L. Mendesworn on oath, says: same are true and control Mixed and pump hole with mud.	ther plugs were used, state and 200 lbs. hulls and TOOH and lay down tump 50 sacks cement and of casing. Mixed satisfactor: Sargent and hox 49BA Tyrone, consible for Plugging Fees: County enhall That I have knowledge of	the character of 20 sacks centre tubing. She trom 1700' to d 10 sacks of Horton Pluggion OK 73951 Stelbar Oil Sedgwic (Signature) (Address)	f same depth prenent down 2 ot 4-1/2" case of 1550'. Purcement and sing, Inc. -9731 Corporation k ents, and matter and sing an	on, Inc. (Employee of ers herein contains)	om), to (top) for each popular perforations of plug perforations of plug perforations of the plug perforations. Pulled cash of the plug perforation of	plug set. a from 5,414' to 5,214'. Circulate hole with the from 550's and cap 8-5/8", 3 ft below surfaction on above-described well, being first a above-described well is as filed, an according to the first and cap 8-5/8".