6 061409	API NUMBER 15- 181-20,275 000 V
STATE CORPORATION COMMISSION Conservation division - Plugging Sect	The second of th
200 COLORADO DERBY BUILDING	
WICHITA, KANSAS 67202	4770 feet from S section line
TECHNICIAN'S PLUGGING REPORT	3300 feet from E section line
Operator License # 5145	
Operator: <u>Dréiling Oil Inc.</u>	
Address Box 1000	Well Total Depth 4850 feet
Victoria, Kansas 67671	Conductor Pipe: Size feet
	Surface Casing: Size 8 5/8 feet 393 w/300
Abandoned Oll Well Gas Well_	Input WellSWD WellD&A_X
	lling Co. License Number
•	CICONSO MUNDOI
Address Wichita, Kansas	22 T 00
	Pay: 22 Month: Jan Year:19 88
Plugging proposal received from	
(company name) Abercrombie Drilli	ng Co. (phone)
order 190 sks 60/40 Poz 6	% Gel 1 sk F.C. and 8 5/8" plug.
	no less than 36 vis mud between all plugs with good
circulation and no fluid	loss.
,	±0005
	Cilhort C Sahaal
Plugging	Proposal Received by Gilbert G. Scheck (TECHNICIAN)
Plugging Operations attended by Agent	?: AllPartNone_X
Operations Completed: Hour:3:45 PM	
ACTUAL PLUCCING PEROPT	7
	plug at 3125' w/20 sks
	plug at 3125' w/20 sks plug at 1900' w/100 sks and 1 sk F.C.
2nd	J. St. Marie Committee of the Committee
2nd :	plug at 1900' w/100 sks and 1 sk F.C.
2nd : 3rd : 4th :	plug at 1900' w/100 sks and 1 sk F.C.
2nd : 3rd : 4th : 10 si	plug at 1900' w/100 sks and 1 sk F.C. plug at 450' w/40 sks plug at 40' w/10 sks 2-5-88
2nd : 3rd : 4th : 10 si	plug at 1900' w/100 sks and 1 sk F.C. plug at 450' w/40 sks plug at 40' w/10 sks ks in rat hole
2nd : 3rd : 4th : 10 s: 10 s: Remarks: Cemented by Allied.	plug at 1900' w/100 sks and 1 sk F.C. plug at 450' w/40 sks plug at 40' w/10 sks ks in rat hole
2nd 3rd 4th 10 s 10 s Remarks: Cemented by Allied. (If additional descripting of the content of the conte	plug at 1900' w/100 sks and 1 sk F.C. plug at 450' w/40 sks plug at 40' w/10 sks ks in rat hole ks in mouse hole. on is necessary, use BACK of this form.)
2nd : 3rd : 4th : 10 si Remarks: Cemented by Allied. (If additional descripting contains the second c	plug at 1900' w/100 sks and 1 sk F.C. plug at 450' w/40 sks plug at 40' w/10 sks ks in rat hole ks in mouse hole. on is necessary, use BACK of this form.)