

15-065-21043-00-00

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
Wichita, Kansas 67217

Rev. 3-15-72
FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner John O. Farmer, Inc.
Address Box 352 Russell, Kansas 67665
Lease (Farm Name) Trexler Well No. #1
Well Location NE SE NE Sec. 24 Twp. 7S Rge. 23W (E) (W)
County Graham Total Depth 3725' Field Name Wildcat
Oil Well Gas Well Input Well SWD Well Rotary D & A X
Well Log filed with application as required Yes
Date and hour plugging is desired to begin 1:00 A. M. 8-29-78

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:
Raymond Kaba Address 807 S. Jefferson Plainville, Kansas

Plugging Contractor John O. Farmer, Inc. License No.
Address Box 352 Russell, Kansas 67665

Invoice covering assessment for plugging this well should be sent to:
Name John O. Farmer, Inc.
Address Box 352 Russell, Kansas 67665

and payment will be guaranteed by applicant or acting agent.

RECEIVED
STATE CORPORATION COMMISSION
SEP 05 1978 9/5/78
CONSERVATION DIVISION
Wichita, Kansas
Signed: John O. Farmer
Applicant or Acting Agent
Date: September 1, 1978

State of Kansas



15-065-21043-00-00

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)
245 North Water
WICHITA, KANSAS 67202

September 1, 1978

WELL PLUGGING AUTHORITY

Well No.	1
Lease	Trexler
Description	NE SE NE Sec. 24-7-23W
County	Graham
Total Depth	3725
Plugging Contractor	John O. Farmer


John O. Farmer, Inc.
Box 352
Russell, Kansas 67665

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. ~~Gilbert Baithazor, P.O. Box 9, Route #1, Palco, Kansas 67657~~
is hereby assigned to supervise the plugging of the above
named well.