

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 30 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4 September 2003 Type or Print on this Form Form must be Signed All blanks must be Filled

Lease Operator: D.S. Langston

Address: 310 W. Central #202 Wichita, Ks. 67202

Phone: (316) 265-4411 Operator License #: 30525

Type of Well: Oil per CP 2/3 3-21-06 per Oil per Dist 3 4.14.06 Docket #: (Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR)

The plugging proposal was approved on: (Date)

by: Richard Lacey (KCC District Agent's Name)

Is ACO-1 filed? Yes No If not, is well log attached? Yes No

Producing Formation(s): List All (If needed attach another sheet)

Depth to Top: Bottom: T.D. (repeated three times)

API Number: 15-165-21,357-00-01

Lease Name: Moore

Well Number: 1

Spot Location (QQQQ): SE SW NW

2310 Feet from X North / X South Section Line

990 Feet from East / X West Section Line

Sec. 25 Twp. 18 S. R. 16 East X West

County: Rush KCC 4-11-06

Date Well Completed: PKT Per

Plugging Commenced: 2-23-06 CP 2/3

Plugging Completed: 2-24-06

Show depth and thickness of all water, oil and gas formations.

Table with columns: Oil, Gas or Water Records (Formation, Content) and Casing Record (Surface Conductor & Production) (From, To, Size, Put In, Pulled Out). Rows show casing sizes 8-5/8" and 4-1/2" with depths 997' and 1181'.

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed, from feet to feet each seal.

Purped sand to bottom, dumped 4 sacks cement on top, purped 50 sacks cement and displaced to 1200'. Cut casing loose @1181', pulled up to 1020', purped 10 sxs gel & 50 sacks cement, pulled up to 500', purped 40 sxs cement, pulled up to 40', purped 20 sacks cement, 60/40 pos, 6% gel. Plugging Complete.

Name of Plugging Contractor: Mike's Testing & Salvage, Inc. License #: 31529

Address: P.O. Box 467 Chase, Kansas 67524

Name of Party Responsible for Plugging Fees: D.S. Langston

State of Kansas County: Rice ss.

Mike Kelso (Employee of Operator) or (Operator) on above-described well, being first duly

sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.


(Signature) Mike Kelso

(Address) P.O. Box 467 Chase, Kansas 67524

SUBSCRIBED and SWORN TO before me this 14th day of March, 2006

Irene Herzberg Notary Public

My Commission Expires:



Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

RECEIVED MAR 16 2006 KCC WICHITA

Pain