## KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

## **WELL PLUGGING APPLICATION**

Please TYPE Form and File ONE Copy

Form CP-1 September 2003 This Form must be Typed Form must be Signed All blanks must be Filled

Well Operator: Kenneth S. White		KCC License #:	30128
Address: 2400 N. Woodlawn, Suite 11		<sub>City:</sub> Wichita	(Operator's)
State: Kansas	Zip Code: 67220		) 682 - 6300
<sub>Lease:</sub> Freymiller	Well #:_1 <b>→ 5</b>	Sec. 5 Twp. 26	S. R. 11 East West
C - NW - SE -	Spot Location / QQQQ Co	<sub>unty:</sub> Pratt	
1320 1980 Feet (in exact footage) From  1320 2040 Feet (in exact footage) From  Check One:  Oil Well  Gas Well	North / South (from ne	arest outside section corner) Line o arest outside section corner) Line o  Water Supply Well	f Section (Not Lease Line) f Section (Not Lease Line)
SWD Docket #	ENHR Docket # _		Other:
Conductor Casing Size:	Set at:	Cemented with:	Sacks
Surface Casing Size: 8-5/8"	Set at: _307'	Cemented with: 1	75 Sacks
Production Casing Size: 4-1/2"	Set at: 4294'	Cemented with: 1	50 Sacks
List (ALL) Perforations and Bridgeplug Sets: 404	11-4056, 4075, 4077, 4087,	4089, 4097, 4099	
Elevation: 1850 ( G.L. / K.B.) T.D.: 440  Condition of Well: Good Poor  Proposed Method of Plugging (attach a separate page casing for recovery, pull casing and plug	ge if additional space is needed): Fil	Junk in Hole with sand to 3900' and du	(Stone Corral Formation) Imp 5 sacks cement, shoot
Condition of Well: Good Poor  Proposed Method of Plugging (attach a separate page)	Casing Leak  ge if additional space is needed): Fil	Junk in Hole with sand to 3900' and du	(Stone Corral Formation) Imp 5 sacks cement, shoot
Condition of Well: Good Poor  Proposed Method of Plugging (attach a separate pag casing for recovery, pull casing and plug  Is Well Log attached to this application as required?	Casing Leak  ge if additional space is needed): File  g @ 650' w/50 sacks cement	Junk in Hole with sand to 3900' and du , 70 sacks @ 275', 15 sack	(Stone Corral Formation) Imp 5 sacks cement, shoot
Condition of Well:	Casing Leak  ge if additional space is needed): Fil  g @ 650' w/50 sacks cement	Junk in Hole with sand to 3900' and du , 70 sacks @ 275', 15 sack	(Stone Corral Formation)  Imp 5 sacks cement, shoot  s @ 40', 60/40 PozMix, 6% gel
Condition of Well: Good Poor  Proposed Method of Plugging (attach a separate pag casing for recovery, pull casing and plug  Is Well Log attached to this application as required?	Casing Leak  Ge if additional space is needed): File  Ge if additional space is needed in the space is n	Junk in Hole  with sand to 3900' and du  70 sacks @ 275', 15 sack  ed? Yes No  ne Rules and Regulations of the	imp 5 sacks cement, shoot s @ 40', 60/40 PozMix, 6% gel RECEIVED MAR 0 2 2006 KCC WICHITA State Corporation Commission.
Condition of Well: Good Poor  Proposed Method of Plugging (attach a separate page casing for recovery, pull casing and pluge is Well Log attached to this application as required?  If not explain why? Sent in when drilled  Plugging of this Well will be done in accordance List Name of Company Representative authorized	Casing Leak  Ge if additional space is needed): File  Ge if additional space is needed in the space is n	Junk in Hole  with sand to 3900' and du , 70 sacks @ 275', 15 sack  ed?	imp 5 sacks cement, shoot s @ 40', 60/40 PozMix, 6% gel RECEIVED MAR 0 2 2006 KCC WICHITA State Corporation Commission.
Condition of Well:  Good  Poor  Proposed Method of Plugging (attach a separate page casing for recovery, pull casing and pluge)  Is Well Log attached to this application as required?  If not explain why?  Sent in when drilled  Plugging of this Well will be done in accordance  List Name of Company Representative authorized Herb Durant  Address:  P.O. Box 251  Plugging Contractor:  Mike's Testing & Salva	Casing Leak  Ge if additional space is needed): Fill  Ge 650' w/50 sacks cement  Fill  Fill  Ge 650' w/50 sacks cement  Fill	Junk in Hole  with sand to 3900' and du  70 sacks @ 275', 15 sack  ed? Yes No  ne Rules and Regulations of the  ions:  Phone: (620) 886  City / State: Medicine L	imp 5 sacks cement, shoot s @ 40', 60/40 PozMix, 6% gel RECEIVED MAR 0 2 2006 KCC WICHITA State Corporation Commission.
Condition of Well:  Good  Poor  Proposed Method of Plugging (attach a separate page casing for recovery, pull casing and pluge)  Is Well Log attached to this application as required?  If not explain why?  Sent in when drilled  Plugging of this Well will be done in accordance  List Name of Company Representative authorized Herb Durant  Address:  P.O. Box 251  Plugging Contractor: Mike's Testing & Salva	Casing Leak  Ge if additional space is needed): File  Ge if additional space is needed in the space is needed in t	Junk in Hole  with sand to 3900' and du , 70 sacks @ 275', 15 sack  ded? Yes No  ne Rules and Regulations of the tions: Phone: (620 ) 886 City / State: Medicine L KCC License #: 31529	imp 5 sacks cement, shoot s @ 40', 60/40 PozMix, 6% gel  RECEIVED  MAR 0 2 2006  KCC WICHITA  State Corporation Commission.  - 5463  codge, KS 67104
Condition of Well:  Good  Poor  Proposed Method of Plugging (attach a separate page casing for recovery, pull casing and pluge)  Is Well Log attached to this application as required?  If not explain why?  Sent in when drilled  Plugging of this Well will be done in accordance  List Name of Company Representative authorized Herb Durant  Address:  P.O. Box 251  Plugging Contractor:  Mike's Testing & Salva	Casing Leak  Ge if additional space is needed): File  Ge if additional space is needed in the space is needed in t	Junk in Hole  with sand to 3900' and du  70 sacks @ 275', 15 sack  ed? Yes No  ne Rules and Regulations of the  ions:  Phone: (620) 886  City / State: Medicine L	imp 5 sacks cement, shoot s @ 40', 60/40 PozMix, 6% gel  RECEIVED  MAR 0 2 2006  KCC WICHITA  State Corporation Commission.  - 5463  codge, KS 67104