

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

Lease Owner C-G DRILLING CO. Address Union National Bank Bldg.,
(Applicant) Wichita, Kansas

Lease (Farm Name) MADDY Well No. 1

Well Location SE SE NW Sec. 18 Twp. 8 Rge. 17 (X)-(W) W

County Rooks Field Name (if any) _____

Total Depth 3415' Oil ___ Gas ___ Dry Hole X

Was well log filed with application? Yes. If not, explain: _____

Date and hour plugging is desired to begin 8:00 PM June 29, 1952

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.
(Use an additional sheet if necessary) _____

Name of the person on the lease in charge of well for owner _____

Harry Walton Address Plainville, Kansas

Name of Plugging Contractor C-G DRILLING CO.

Address 206 Union National Bank Bldg., Wichita, Kansas.

Invoice covering assessment for plugging this well should be sent to C-G Drilling Co. Address 206 Union National Bank Bldg.,
Wichita, Kansas
and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION
JUL - 7 1952
JUL - 7 1952
CONSERVATION DIVISION
Wichita, Kansas

[Signature]
Applicant or Acting Agent
Date July 1, 1952

PLUGGING
FILE SEC 18 T 8 R 17W
BOOK PAGE 27 LINE 25



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

July 2, 1952

Well No. 1
Lease Buddy
Description SE 25 NW 18-8-17W
County Hooker
File No. 27-25

C & G Drilling, Inc.
206 Union Nat'l. Bank Bldg.
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Hays, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: J. P. Roberts
J. P. ROBERTS

cc: DISTRICT PLUGGING SUPERVISOR