3 Coterado Do	ROIZZIESSON NOI	K-A-R82-3-117	API NUMBER. N/A
etlin, Konson	orby Bullding	•	LEASE NAME Krug
<i>i</i> *		TYPE OR PRINT	WELL NUMBER 8
		NOTICE: Fill out completely and return to Cons. Div.	0.0
	·	office within 30 days.	330 Ft. from Section Lin
ASE OPERATOR_	т. о.	Rush .	SEC. 19 TWP. 85 RGE. 17W(E)or(W
DRESS BO	ox 327 Haysvil	le,Ks. 67060	COUNTY Rooks
DHE / () 773	3-1247 OPER	ATORS LICENSE NO. 3846	Date Well Completed
eractor of We	II oil		Plugging Commenced 12-8-88
1, Gas, D&A,	SWD, Input, W	ater Supply Well)	Plugging Completed 12-9-88
= you notlfy	the KCC Distric	ct Office prior to plugging t	his well? Yes
ich KCC Offic	e did you noti:	fy? Hays , Ks. Dennis	Hammel
		f not, is well log attached?	
			Bottom 3326 T.D. 3409
•		il water, oil and gas formati	
L, GAS OR WA	TER RECORDS	c	ASING RECORD Put In Pulled out None N
reation	Conten.	70 To Size 3409 5 ½	Put In Pulled out Dec 11
		$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	3409 None None 1319 None
			Cower 198
			d, Indicating where the mud Kanguston
cribe in deta	all the monner method or meth	In which the well was plugged ods used in introducing it is	d, indicating where the mud Kany 1960) nto the hole. If cement or other pl
a 115 ad 5 4 -	to the charac	ter of same and depth place	ed. from feet to feet each s
Run tuhina t	O JIOO DUNDEG	13501 purpod 50 galag ATT and	n tubing to 2700' pumped 40 sacks o d 1 hull. Run to 700' pumped 125 sa
Run tubing t	hulls, Run to	1330 Dulibed 30 Sacks ATL an	M T HATT, KAN TO 700, DUMBER 172 SS
with 6 sacks cement and 2	s hulls, Run to Phulls , Pumped	d top of 5% with 25 sack cmen	it and 1 hull at 1001bs (held)
with 6 sacks cement and 2 Pumped 75 sa	s hulls, Run to Phulls , Pumped acks cement and	d top of 5½ with 25 sack cmen 2 hulls down 8 5/8 and 5½ at ription is necessary, use BAC	it and 1 hull at 1001bs (held)
with 6 sacks cement and 2 Pumped 75 sa (11	hulls, Run to hulls , Pumped acks cement and additional desc	d top of 5% with 25 sack cmen 2 hulls down 8 5/8 and 5% at	it and 1 hull at 1001bs (held)
with 6 sacks cement and 2 Pumped 75 sa (11	hulls, Run to hulls , Pumped acks cement and additional desc	2 hulls down 8 5/8 and 5½ at ripilon is necessary, use BAC Gressel Corp.	it and 1 hull at 1001bs (held) 100 lbs. (held) CK of this form.)
with 6 sacks cement and 2 Pumped 75 sa	hulls, Run to hulls, Pumped cks cement and additional desc	2 hulls down 8 5/8 and 5½ at ripilon is necessary, use BAC Gressel Corp.	it and 1 hull at 1001bs (held) 100 lbs. (held) CK of this form.)

GARY D. STEARNS
NOTARY PUBLIC
STATE OF KANSAS
My Appt. Exp. 2-12-92

Form CP-4 Revised 07-86