

CARD MUST BE TYPED

State of Kansas

CARD MUST BE SIGNED ✓

# NOTICE OF INTENTION TO DRILL

(see rules on reverse side)

Expected Spud Date..... **APRIL 7, 1987**  
month day year

API Number 15— **003-22,790-00-00**

OPERATOR: License # **#6004**  
**CALDWELL ENTERPRISES, INC.**

**SE NE NE** Sec. **15** Twp. **21** S, Rg. **20** — East  
**4290** — West

Name **P. O. BOX 42**

**160** Ft. from South Line of Section

Address **GARNETT, KANSAS 66032**

**160** Ft. from East Line of Section

City/State/Zip **GLEN CALDWELL**

(Note: Locate well on Section Plat on reverse side)

Contact Person **913-448-3578**

Nearest lease or unit boundary line **165** feet

Phone **#5820**

County **ANDERSON**

CONTRACTOR: License # **KENT DRILLING COMPANY**

Lease Name **WARE** Well # **M-6**

Name **GARNETT, KANSAS 66032 HAYS, KS 67601**

Ground surface elevation ..... feet MSL

City/State

Domestic well within 330 feet: —yes  —no

Well Drilled For: Well Class: Type Equipment:

Municipal well within one mile: —yes  —no

Oil  Storage  Infield  Mud Rotary

Depth to bottom of fresh water .....

Gas  Inj  Pool Ext.  Air Rotary

Depth to bottom of usable water **125**

OWWO  Expl  Wildcat  Cable

Surface pipe by Alternate: **20** 1  2

If OWWO: old well info as follows:

Surface pipe planned to be set .....

Operator .....

Conductor pipe required **870**

Well Name .....

Projected Total Depth **SQUIRREL** feet

Comp Date ..... Old Total Depth.....

Formation .....

I certify that well will comply with K.S.A. 55-101, et seq., plus eventually plugging hole to KCC specifications.

Date **4/3/87** Signature of Operator or Agent **[Signature]**

Title **AS AGENT**

For KCC Use:

Conductor Pipe Required ..... feet; Minimum Surface Pipe Required ..... feet per Alt. **20**

This Authorization Expires **10-4-87** Approved By **[Signature]** **4-3-87**


**[Signature]**

Must be filed with the K.C.C. five (5) days prior to commencing well  
This card void if drilling not started within six (6) months of date received by K.C.C.

**Important procedures to follow:**

1. Notify District office before setting surface casing.
2. Set surface casing by circulating cement to the top.
3. File completion forms ACO-1 with K.C.C. within 120 days of well spud date, following instructions on ACO-1, side 1, and including copies of wireline logs.
4. Notify District office 48 hours prior to old well workover or re-entry.
5. Prior to filing Intent, prepare a proposed plugging plan in case well is D & A, then obtain approval of plan when calling district office prior to setting surface pipe.
6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
7. Obtain an approved injection docket number before disposing of salt water.
8. Notify K.C.C. within 10 days when injection commences or terminates.

**A Regular Section of Land**  
**1 Mile = 5,280 Ft.**



**RECEIVED** If an alternate 2 completion, cement in the production pipe from  
STATE CORPORATION COMMISSION below any usable water to surface within 120 days of spud date.

APR 3 1987  
04-03-87  
CONSERVATION DIVISION  
Wichita, Kansas

State Corporation Commission of Kansas  
Conservation Division  
200 Colorado Derby Building  
Wichita, Kansas 67202-1212  
(316) 263-3238