Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD

K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

ORRECT Lease Operator: Hess Oil Company API Number: __**15** - 195-21,964-00-00 Giess Lease Name:___ Address: P. O. Box 1009, McPherson, KS 67460 B-1 Phone: (620) 241 -4640 Operator License #: _5663 Well Number: Spot Location (QQQQ): Approx - E/2 - SE - NE Type of Well: oil (Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR) North / V South Section Line Feet from The plugging proposal was approved on:___ 330 Feet from V East / West Section Line (KCC **District** Agent's Name) .s. R._ County:___ Is ACO-1 filed? ✓ Yes No If not, is well log attached? Yes 🗸 No Date Well Completed: 4-19-88 Producing Formation(s): List All (If needed attach another sheet) Mississippi Depth to Top: 4471' Bottom: 4481' T.D. Plugging Commenced: 8-10-06 Depth to Top: ___ _ Bottom: __ Plugging Completed: 8-23-06 Depth to Top: ____ Bottom: ___ T.D. _ Show depth and thickness of all water, oil and gas formations. Oil, Gas or Water Records Casing Record (Surface Conductor & Production) Formation Content Size Put In Pulled Out surface 220' 0' 8-5/8" 220' none production 4505 0' 5-1/2" 4505' none Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. (Failed attempt: Pumped cement down inside of 5-1/2" - 50 sacks with 400# hulls, then 3 sacks gel spacer, but could not pump any more.) Pumped 40 sacks 60/40 pozmix down outside of 5-1/2" on 8-10-06 to fill to surface. On 8-23-06, pushed in tubing to 2025' to wash out 5-1/2". Pulled tubing up to 1995' and pumped 135 sacks 60/40 pozmix, 10% gel, 1 sack hulls through tubing to fill up inside 5-1/2". Finished by pulling tubing out, and pumping in 15 sacks more to fill 5-1/2" to surface. Name of Plugging Contractor: Hess Oil Company RECEIVED Address: same SEP 0 7 2006 Name of Party Responsible for Plugging Fees: Hess Oil Company State of Kansas KCC WICHITA McPherson Bryan Hess, President (Employee of Operator) or (Operator) on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God. (Signature) (Address)_same SUBSCRIBED and SWORN TO before me this 6th day of September 20 06

My Appt Expires 6-1-09
as 67202

NOTARY PUBLIC STATE OF KANSAS Carol A. Nickel