Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD

Form CP-4 December 2003 Type or Print on this Form Form must be Signed All blanks must be Filled

K.A.R. 82-3-117

Lease Operator: Berexco, Inc.						API Number: 15 - 167-07070-00-00			
Address: PO Box 723 Hays, KS 67601					Lease Name: Rusch Seeley				
Phone: (785) 628 -6101 Operator License #: 5363					Well Number: 2				
Type of Well: Oil Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) Oocket #:					Spot Location (QQQQ): E/2 - SE - SE - A/2013				
The plugging proposal was approved on: 9-8-06 (Date)					330 Feet from Fast / West Section Line				
by: Case Morris (KCC District Agent's Name)					Sec. 30 Twp. 14 S. R. 14 ☐ East ✓ West				
Is ACO-1 filed? Yes No If not, is well log attached? Yes No					Col	unty: Russell			
Producing Formation(s): List All (If needed attach another sheet)					Date Well Completed: 11-2-40				
TOR Depth to Top: 2888 Bottom: 2894 T.D. 3145					Plugging Commenced: 9-6-06				
PLATTS Depth to Top: 2819 Bottom: 2826 T.D. 3145					Plugging Completed: 9-8-06				
L-KC O.H. Depth to Top: 2924 Bottom: 3145 T.D.					I lugging Completed.				
Show depth and thickness of all water, oil and gas formations.									
					Surface Conductor & Production)				
Formation	Content	From	То	Size		Put In	Pulled Ou	rt	
		0	2924	7"		11-2-40	***************************************		
Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set. Rig up Perftech shot 2 holes each @ 1400',750',&450'. Run open end tbg to 2000'. Fluid level 300' FS. Mix 125 sks 60/40 poz 10% gel w/ 400# hulls dwn tbg. Pull tbg to 1000' Mix 300 sks 60/40 pox 10% gel w/ 300# hulls. Fld circ to surface, cmt didn't circ to surface. Pull tbg out of hole. Run sandline w/ 1 jt tbg tag cmt @ +/- 725'. Ran open end tbg to 738 - tag cmt Set tbg @ 725' mix 100sks 60/40 poz 10% gel - circ cmt to surface in 7"x2-3/8 annulus. Pull tbg out. Tie to 7" csg - mix 80 sks cmt to top off & circ cmt to celler.									
			7000			***************************************		RECEIVED	
Name of Plugging Contractor: Berexco Inc.						License #: 5363			
Address: PO Box 723 Hays, KS 67601							R	and in some	
Name of Plugging Contractor: Berexco Inc. Address: PO Box 723 Hays, KS 67601 Name of Party Responsible for Plugging Fees: Dennis Kirmer									
State of KS	County,	Ilis		_ , SS.					
	•					-1-2			
sworn on oath, says: That I I same are true and correct, s	o help me God. (\$	Signature)	Deni	herein contain	ned, a	and the log of the abo		cribed well, being first duly ed well is as filed, and the	
SHANN	A MILLER	(Address) PO Box 723 Hays, KS 67601						A	
NOTAR	Y BURSCRIBED and SV	VORN TO befo	ore me this $\frac{1}{2}$	13 day of _	Sept	tember mission Expires: 9	-19-0	, 20 06	
		Notary Publi	follow .	iviy	COIII	тызыон Ехриев:/	., _		

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202