Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION OIL & GAS CONSERVATION DIVISION

WELL PLUGGING RECORD K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Address: $7570 \text{ W } 21\text{st-Bldg.}$ Whone: $(316) 773 2266$ Operation of Well: $D\&A$	1010-D,	Wichita	12 (720 E)	Name	Coy	
		wichiila,	Ks. 6/2401	.ease Name:	•	
	erator License #: _	5118	,	Well Number:		
			1.	Spot Location (QQQC	a): <u>C - SE - NW</u>	
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Ca		(If SV	VD or ENHR)	3300 Feet from North / X South Section Line		
The plugging proposal was approved on:(Date)			(Date)	3300 Feet from X East / West Section Line		
y;		_ (KCC Distric	t Agent's Name)	Sec. 3 Twp. 28	8 s. R. 19 East X w	
Pending s ACO-1 filed? Yes XNo If not	, is well log attach	ed? Yes			a	
Producing Formation(s): List All (If needed attack	h another sheet)			•	: Aug. 3, 2006	
NA Depth to Top	:Botto	om:	TD I	Plugging Commenced: Aug. 3, 2006		
Depth to Top	: Botto	om:	T.D			
Depth to Top	:Botto	Bottom: T.D		Plugging Completed: Aug. 4, 2006		
how depth and thickness of all water, oil and	gas formations.					
Oil, Gas or Water Records			Casing Record (Sun	ace Conductor & Produ	uction)	
Formation Content	From	То	Size	Put In	Pulled Out	
Surface			8 5/8"	452'	None	
	1					
ole. If cement or other plugs were used, star	te the character o	f same depth	placed from (bottom	, to (top) for each pl	ug set.	
ole. If cement or other plugs were used, startless $\frac{1}{\sqrt{w}}$	te the character of acks; 2nd	f same depth p	placed from (bottom	sacks, 3rd	ug set.	
ole. If cement or other plugs were used, startless $\frac{1}{\sqrt{w}}$	te the character of acks; 2nd	f same depth p	placed from (bottom	sacks, 3rd	ug set. _plug @ 60'/w/20	
ole. If cement or other plugs were used, start start plug @ 1200'/w/50 s sacks. Fill to top. T	te the character of acks; 2nd en sacks	fsame depth plug @in ratho	placed from (bottom) $460'/w/50$	sacks, 3rd	ug set. plug @ 60'/w/20 Pos/w/6% gel.	
ole. If cement or other plugs were used, start start plug @ 1200'/w/50 s sacks. Fill to top. T	te the character of acks; 2nd en sacks	f same depth plug din ratho	placed from (bottom $460 ' / \mathrm{w} / 50$	sacks, 3rd ement 60/40	plug @ 60'/w/20 Pos/w/6% gel.	
lame of Plugging Contractor: Pickre	te the character of acks; 2nd en sacks ell Drillin , Wichita	f same depth plug din ratho	placed from (bottom) $460'/w/50$ ple. All ce	sacks, 3rd ement 60/40	plug @ 60'/w/20 Pos/w/6% gel.	
Describe in detail the manner in which the welf cole. If cement or other plugs were used, start last plug @ 1200'/w/50 s sacks. Fill to top. Tolered and the sacks. Fill to top. Tolered and the sacks and the sacks are state of Kansas Countries.	te the character of acks; 2nd en sacks ell Drillin, Wichita	f same depth plug @ in rathogg Co. Ks. 67	placed from (bottom) 460'/w/50 ple. All ce	sacks, 3rd ement 60/40	plug @ 60'/w/20 Pos/w/6% gel. 5123 **RECEL**	