

P CARD MUST BE TYPED

State of Kansas

CARD MUST BE SIGNED

NOTICE OF INTENTION TO DRILL

(see rules on reverse side)

✓ A

Expected Spud Date.....8/20/87.....
month day year

API Number 15— 003-22829-00-00
NW $\frac{1}{4}$, SW $\frac{1}{4}$, NE $\frac{1}{4}$ East

OPERATOR: License #7158.....

~~NW $\frac{1}{4}$, SW $\frac{1}{4}$, NE $\frac{1}{4}$~~ Sec...21. Twp.22... S, Rg...19... West

NameSchulte Oil.....

3740 Ft. from South Line of Section

Address3rd & hwy 59.....

2430 Ft. from East Line of Section

City/State/Zip ...Garnett, KS.66032.....

Contact Person. C.D. Schulte.....

Phone.....913-448-6191.....

(Note: Locate well on Section Plat on reverse side)

Nearest lease or unit boundary line210..... feet

County.....Anderson.....

CONTRACTOR: License #5820.....

Lease Name. Northwest Central Well #13.....

NameKent Drilling Co.....

Pipeline

City/State.....Garnett, KS.66032.....

Ground surface elevation..... feet MSL

Well Drilled For: Well Class: Type Equipment:

Domestic well within 330 feet: yes no

XOil Storage XInfield XMud Rotary

Municipal well within one mile: yes no

Gas Inj Pool Ext. Air Rotary

Depth to bottom of fresh water.....none.....

OWWO Expl Wildcat Cable

Depth to bottom of usable water ..125'.....

If OWWO: old well info as follows:

Surface pipe by Alternate: 1 2 X

Operator

Surface pipe planned to be set20'.....

Well Name

Conductor pipe required

Comp Date..... Old Total Depth.....

Projected Total Depth850'..... feet

I certify that well will comply with K.S.A. 55-101, et seq., plus eventually plugging hole to KCC specifications.

Formation.....squirrel.....

Date7/30/87..... Signature of Operator or Agent

Title.....Operator.....

For KCC Use:

Conductor Pipe Requiredfeet; Minimum Surface Pipe Required20..... feet per Alt. 1 (2)

This Authorization Expires.....2-7-88..... Approved By ..DB 8-7-87.....


Must be filed with the K.C.C. five (5) days prior to commencing well
This card void if drilling not started within six (6) months of date received by K.C.C.

Important procedures to follow:

1. Notify District office before setting surface casing.
2. Set surface casing by circulating cement to the top.
3. File completion forms ACO-1 with K.C.C. within 120 days of well spud date, following instructions on ACO-1, side 1, and including copies of wireline logs.
4. Notify District office 48 hours prior to old well workover or re-entry.
5. Prior to filing Intent, prepare a proposed plugging plan in case well is D & A, then obtain approval of plan when calling district office prior to setting surface pipe.
6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
7. Obtain an approved injection docket number before disposing of salt water.
8. Notify K.C.C. within 10 days when injection commences or terminates.
9. If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.

A Regular Section of Land

1 Mile = 5,280 Ft.



RECEIVED
CONSERVATION DIVISION
Wichita, Kansas

RECEIVED
STATE CORPORATION COMMISSION
Wichita, Kansas

RECEIVED
CONSERVATION DIVISION
Wichita, Kansas

AUG 3 1987

RECEIVED
STATE CORPORATION COMMISSION
Wichita, Kansas

AUG 08 - 07 - 87
CONSERVATION DIVISION
Wichita, Kansas

State Corporation Commission of Kansas
Conservation Division
200 Colorado Derby Building
Wichita, Kansas 67202-1212
(316) 263-3238