

CARD MUST BE TYPED

State of Kansas

CARD MUST BE SIGNED

NOTICE OF INTENTION TO DRILL

(see rules on reverse side)

Starting Date 12 19 1985
month day year **3:50**

API Number 15— **003-22,706-00-00**

OPERATOR: License # **9554**
Name ... **Qzark Resources, Inc.**
Address **Box 345**
City/State/Zip .. **Garnett, Kansas 66032**
Contact Person... **Clyde Boots**
Phone... **316-851-3574**

East
C..SW..SE.... Sec 22... Twp. 22. S, Rg. 19.....
..... **660**... Ft. from South Line of Section
..... **1980**.... Ft. from East Line of Section

(Note: Locate well on Section Plat on reverse side)

CONTRACTOR: License # **6451**
Name ... **Big "E" Drilling**
City/State .. **Route 1, Centerville, KS 66014**

Nearest lease or unit boundary line **.660**..... feet
County... **Anderson**.....
Lease Name... **Cooper**..... Well #... **26E**.....

Well Drilled For: Well Class: Type Equipment:
 Oil SWD Infield Mud Rotary
 Gas Inj Pool Ext. Air Rotary
 OWWO Expl Wildcat Cable

Ground surface elevation **110.0**..... feet MSL

Domestic well within 330 feet: yes no
Municipal well within one mile: yes no

If OWWO: old well info as follows:

Operator
Well Name
Comp Date Old Total Depth.....

Surface pipe by Alternate: 1 2

Depth to bottom of fresh water **none 20**.....

Depth to bottom of usable water **125**.....

Surface pipe planned to be set **20**.....

Projected Total Depth **850**..... feet

Formation..... **Squirrel**.....

I certify that well will comply with K.S.A. 55-101, et seq., plus eventually plugging hole to KCC specifications.

_____ cementing will be done immediately upon setting production casing.

Date **12/19/85** Signature of Operator or Agent **Sherril Chalar** Title..... as agent

Sherril Chalar

For KCC Use:

Conductor Pipe Required feet; Minimum Surface Pipe Required feet per Alt. 1 2


This Authorization Expires **6-19-86** Approved By **12-19-85** **TC**

Must be filed with the K.C.C. five (5) days prior to commencing well
This card void if drilling not started within six (6) months of date received by K.C.C.

Important procedures to follow:

1. Notify District office before setting surface casing.
2. Set surface casing by circulating cement to the top.
3. File completion forms ACO-1 with K.C.C. within 90 days of well completion, following instructions on ACO-1, side 1, and including copies of wireline logs.
4. Notify District office 48 hours prior to old well workover or re-entry.
5. Prior to filing Intent, prepare a proposed plugging plan in case well is D & A, then obtain approval of plan when calling district office prior to setting surface pipe.
6. Submit plugging report (CP-4) to K. C. C. after plugging is completed.
7. Obtain an approved injection docket number before disposing of salt water.
8. Notify K.C.C. within 10 days when production commences or terminates.
9. If an alternate 2 completion, cement on 100' production pipe from below any usable water to surface within 120 days of spud date.

**A Regular Section of Land
1 Mile = 5,280 Ft.**



RECEIVED
STATE CORPORATION COMMISSION
12-19-83
DEC 19 1983
CONSERVATION DIVISION
State Corporation Commission of Kansas
Conservation Division
200 Colorado Derby Building
Wichita, Kansas 67202
(316) 263-3238