

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

**KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117**

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: Cleary Petroleum Corporation
 Address: 2601 NW Expressway, Suite 801W, Oklahoma City, OK 73112
 Phone: (405) 848-5019 Operator License #: 32566
 Type of Well: Dry Hole Docket #: _____
 (Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR)
 The plugging proposal was approved on: 11-08-06 (Date)
 by: Richard Lacey (KCC District Agent's Name)
 Is ACO-1 filed? Yes No If not, is well log attached? Yes No
 Producing Formation(s): List All (If needed attach another sheet)
 _____ Depth to Top: _____ Bottom: _____ T.D. _____
 _____ Depth to Top: _____ Bottom: _____ T.D. _____
 _____ Depth to Top: _____ Bottom: _____ T.D. _____

API Number: 15-145-21536-00-00
 Lease Name: Lupfer
 Well Number: 1-12
 Spot Location (QQQQ): C/2 - NE/4 - NE/4 - NE/4
330 Feet from North / South Section Line
330 Feet from East / West Section Line
 Sec. 12 Twp. 22 S. R. 18 East West
 County: Pawnee
 Date Well Completed: 08-02-06
 Plugging Commenced: 11-08-06
 Plugging Completed: 11-16-06
 09 KCC PKT PER C 12/16/06

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)				
Formation	Content	From	To	Size	Put In	Pulled Out
		Surface	812'	8-5/8"	812'	None
		Surface	4,109'	5-1/2"	4,109'	None

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Ran junk basket & set CIBP @3775'; Made dump bailer run to cap CIBP w/ 2 sxs cmt (16.48' cmt cap); Ran CBL GR from 1200' to surf for bonding (good);
Set add'l CIBP @1140', press to 500#, held, dumped 3 sxs cmt; Sting in hole w/ tbg to 840', pmp w/ 15 sxs gel & 50 sxs cmt, pulled up to 420', pmp 50 sxs cmt,
pull up to 40', pmp 15 sxs cmt, cut off 5-1/2" csg & 7-5/8" csg, weld steele plate over both and cover hole.

Name of Plugging Contractor: Operator to plug Cleary Petroleum Corp License #: 32566
 Address: _____ PKT

Name of Party Responsible for Plugging Fees: Cleary Petroleum Corporation
 State of Oklahoma County, Oklahoma, ss.

Jerry Elgin (Employee of Operator) or (Operator) on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

(Signature) Jerry Elgin
 (Address) 2601 NW Expressway, Suite 801W, Oklahoma City, OK 73112

SUBSCRIBED and SWORN TO before me this 27 day of November, 2006
Elizabeth Black My Commission Expires: _____
 Notary Public

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

