STATE OF KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION 200 Colorado Derby Building Wichita, Kansas 67202

WELL PLUGGING APPLICATION FORM (File One Copy)

Received 6/22/87

API NUMBER 15-163-22,923-20-00 (of this well)
(This must be listed; if no API# was issued, please note drilling completion date.)

LEASE OPER	ATOR	Grasslan	ds Petrol	eum Co.		OPE	RATORS LIC	ENSE NO. 339	15
ADDRESS	P.O. Box :	20413, Wi	chita, KS	67208		PHO	NE # (316)	682-7283	
LEASE (FAR	M) Logsdo	n	WELL NO.	1	WELL I	OCATION 100 SW	O' East of NE SW	COUNTY RO	ooks
SEC. 4	TWP. 9s	RGE	18 (E) or	OT <u>(W)</u>	TAL DEPTH	I 3301	PLUG I	BACK TD	
Check One:									
OIL WELL _	GAS 1	WELL	_ D & A	Х	SWD or IN	J WELL	DOCKET	NO	
S	SURFACE CAS	ING SIZE	8 5/8	SET AT	216	CEMENTED W	ITH 145	SACK	KS ·
	CAS:	ING SIZE .		SET AT		CEMENTED W	ITH	SACK	(S
p	ERFORATED A	AT							Manage
CONDITION	OF WELL: G	00D x	POOF	₹	CASING	G LEAK	JUN	K IN HOLE	
	SUGGESTED								

	1 111								
		(If a	dditional	space	is needed	use back	of form)	·	
IS WELL LO	G ATTACHED	TO THIS	APPLICATI ()	ON AS R	EQUIRED? explain)	4764000000-664-684-684-684-684-684-684-684-684-684	IS ACO	-1 FILED?	Yes
DATE AND H	OUR PLUGGII	NG IS DES	IRED TO E	BEGIN	(5-12-87 @ 2	:30 p.m.		
PLUGGING	,	ELL WILL	BE DONE	IN ACO	ORDANCE V			seg AND THE	RULES ANI
NAME OF CO	MPANY REPRE	ESENTATIV	E AUTHORI	ZED TO	BE IN CHA	ARGE OF PLU	GGING OPER	ATIONS:	
Joh	nn Weis					PHONE :	# (913)	625-4548	
ADDRESS P	0.0. Box 29	6, Hays,	KS 67601						
PLUGGING C	ONTRACTOR _	R & C D	rilling (Co., Inc	•	LICENS	e no.	9087	
ADDRESS	P.O. Box 2	296, Hays	, KS 6760	01		PHONE ₇	# / 913)	625-4548	<u> </u>
PAYMENT WI	LL BE GUARA	ANTEED BY	OPERATOR	R OR AGE	NT SIGN	ED: AN	n Operator	or Agent)	N O
				•	DATE	:	6-16-8	7 (0"	<i>(</i>

NOTICE OF INTENTION TO DRILL

	Juc !		(see rules on	reverse side)
Starting Date	May 19,	1987		API Number 15— 163-22, 923
	mo	nth day	year	100 feet East
OPERATOR: Li	cense #3.3.9).5	*******	SW. NE SW. sec. 4. Twp. 9. S. Rg. 18. X West
			Company	1000 Ft. from South Line of Section
Address . PO.	Box 2041	L 3		ZAP 3530 3630 Ft. from East Line of Section
		KS 672		(Note: Locate well on Section Plat on reverse side)
			*******	Nearest lease or unit boundary line
	.6827.283		•••••	CountyKOOKS
		9087	*******	Lease NameLOgsdon
			••••••	Ground surface elevationNA
City/State	lays, KS			Domestic well within 330 feet:yes X_no
Well Drilled For	::	Well Class:	Type Equipment:	Municipal well within one mile:
X Oil	SWD	Infield	X Mud Rotary	Depth to bottom of fresh water80
Gas	Inj	Pool Ext.	Air Rotary	Depth to bottom of usable water
owwo	Expl	X Wildcat	Cable	Surface pipe by Alternate: 1 2 _X
If OWWO: old w	ell info as follows	s:		Surface pipe by Alternate: $1 - 2 \times 2 \times 200$ Surface pipe planned to be set
Operator	• • • • • • • • • • • • • • • • • • • •		******	Conductor nine required Baneved
Well Name	• • • • • • • • • • • • • • • • • • • •		••••••	Projected Total Depth
Comp Date	o	ld Total Depth	*******	Formation Arbuckle
				Formation Ar buckle Ar buckle Ar buckle 1987
Date5./.13,	1.8.7 Signa	ature of Operato	or or Agent	. Salkef. Title Owner
For KCC Use:				Hays, KS
Conductor Pipe	Required	feet;	Minimum Surface Pi	pe Required
Plain A41	¥7	//~ 7	フェタフ	C-17 07
Saul	6-7-8	37	R. Finis	- 4
y- we	2 ~ 6 1		>	3 Hours Reflec
-	200 7	- Sele	m	() - //-
				East
				S.W NE .S.W. Sec. 4 Twp9s, Rg1.8 <u>X</u> West
				west
		WF		
		PLUC	GING PROPOSA	AL IF ABOVE IS D & A
This plugging pr	oposal will be re			· · · · · · · · · · · · · · · · · · ·
5 p.m. workdays		viewed and appr	roved or revised at the ti	ime the district office is called prior to setting surface casing (call 7 a.m. to
printer in our account		viewed and appı	roved or revised at the t	ime the district office is called prior to setting surface casing (call 7 a.m. to
pilli normany.		eviewed and app	roved or revised at the t	ime the district office is called prior to setting surface casing (call 7 a.m. to
	i) .		·	
lst plug @5.0 2nd plug @ . As	oAbowe.	.Ar.buckla	eet depth with2.5	5sxs of
lst plug @5.0 2nd plug @ . As	oAbowe.	.Ar.buckla	eet depth with2.5	5sxs of
lst plug @5.0 2nd plug @ . As	oAbowe.	.Ar.buckla	eet depth with2.5	5sxs of
1st plug @5.(2nd plug @ .Ar 3rd plug @5.(4th plug @1.)	o. D.!Aho.ve. D.!Below. D.!Below.	.Ar.buckla fe Dakota fe Surfacefe	eet depth with25 eet depth with25 eet depth with106 eet depth with46	5. sxs of 60/40 Poz 6% Ge1 5. sxs of " 0. sxs of " 1.
1st plug @5.0 2nd plug @ .Ar 3rd plug @5.0 4th plug @1.0 5th plug @1.8	oAbo.ve. h.hydr.ite. DBelow. DBelow. ehind.Wir	.Ar.bucklæ fe .Dakota fe .Surfacefe ger. Plugfe	eet depth with25 eet depth with25 eet depth with100 eet depth with40 eet depth with110	5. sxs of 60/40 Poz 6% Ge1 5. sxs of "" 0 sxs of "" 0 sxs of "" 0 sxs of "" 0 sxs of ""
1st plug @5.0 2nd plug @ .Ar 3rd plug @5.0 4th plug @1.0 5th plug @1.8	oAbo.ve. h.hydr.ite. DBelow. DBelow. ehind.Wir	.Ar.buckla fe Dakota fe Surfacefe	eet depth with25 eet depth with25 eet depth with100 eet depth with40 eet depth with110	5. sxs of 60/40 Poz 6% Ge1 5. sxs of " 0. sxs of " 1.
Ist plug @5.02nd plug @5.03rd plug @5.03th plug @1.05th plug @	oAho.v.e. a.h.ydr.ite. OBelow. OBelow. ehind.Wir	.Ar.buckla fe .Dakota fe .Surfacefe .Ser. Plugfe .5	eet depth with25 eet depth with25 eet depth with40 eet depth with40 eet depth with40	5.
Ist plug @5.0 2nd plug @5.0 3rd plug @5.0 4th plug @B.0 5th plug @B.0 (2) Rathole with	o). O.!Aho.ve. o.h.ydr.ite. O.!.Below. O.!.Below. phind Wir controller	Ar.buckla 	eet depth with25 eet depth with25 eet depth with26 eet depth with26 eet depth with26 et depth with26 s	sxs of 60/40 Poz 6% Ge1 sxs of " by Mousehole with sxs ent and the amount of cement to be used is necessary prior to plugging.
Ist plug @5.0 2nd plug @5.0 3rd plug @5.0 4th plug @B.0 5th plug @B.0 (2) Rathole with	o). O.!Aho.ve. o.h.ydr.ite. O.!.Below. O.!.Below. phind Wir controller	Ar.buckla 	eet depth with25 eet depth with25 eet depth with10 eet depth with16 eet depth with16 t office on plug placement	sxs of 60/40 Poz 6% Ge1 sxs of " by Mousehole with
Ist plug @5.02nd plug @5.03rd plug @5.03th plug @1.05th plug @B.05th plug @B	oAho.v.e. h.h.y.d.r.it.e. oBelow. oBelow. h.ind Wir	Ar.buckla 	eet depth with25 eet depth with25 eet depth with10 eet depth with16 eet depth with16 t office on plug placement	sxs of 60/40 Poz 6% Ge1 sxs of " by Mousehole with sxs ent and the amount of cement to be used is necessary prior to plugging.
Ist plug @5.0 2nd plug @5.0 3rd plug @5.0 4th plug @B.0 5th plug @B.0 (2) Rathole with	oAho.v.e. h.h.y.d.r.it.e. oBelow. oBelow. h.ind Wir	Ar.buckla 	eet depth with25 eet depth with25 eet depth with10 eet depth with16 eet depth with16 t office on plug placement	sxs of 60/40 Poz 6% Ge1 sxs of " s
Ist plug @5.02 nd plug @5.03 th plug @5.05 th plug @3.05 Rathole with NOTE: Agreement Addition: Cal	a). O.!Aho.v.e. D.!Below. O.!Below. Phind.Wir ent between open I district office	Ar.buckla 	eet depth with	sxs of 60/40 Poz 6% Ge1 sxs of 11 sxs of 12 sxs of 13 sxs of 14 sxs of 15 sxs of 17 sxs of 17 sxs of 17 sxs of 18 sxs of 1
1st plug @5.02nd plug @5.03rd plug @5.03th plug @1.05th plug @	o.!Aho.ve. h.hydr.ite. o.!.Below. o.!.Below. ehind Wir ent between oper district office	Ar.buckla Dakota Surface Surface Ser. Plugfe 5 rator and district after well is eith	t office on plug placemeter plugged or product	sxs of 60/40 Poz 6% Ge1 sxs of " by Mousehole with sxs ent and the amount of cement to be used is necessary prior to plugging. tion casing is cemented in. FECTIVELY JUN 2 2 1987
Ist plug @5.02nd plug @5.03rd plug @5.04th plug @3.05th plug @3	o.!Aho.ve. h.h.y.dr.ite. o.!Below. o.!Below. c.h.ind.Wir cl ent between open d district office	Ar.buckla Dakota for Surface for Plugfor Sxs rator and district after well is either second	eet depth with	sxs of 60/40 Poz 6% Ge1 sxs of " b Mousehole with sxs ent and the amount of cement to be used is necessary prior to plugging. tion casing is cemented in RECEIVED p.m. workdays) STATE CORPORE TON COMMISSION JUN 2 2 1987 sxs at CONSERVALIDATE STATE TON TON 19
Ist plug @5.02nd plug @5.03rd plug @5	o.!Aho.ve. h.hydr.ite. o.!Below. o.!Below. e.hind.Wip chind.Wip district office se only: f	Ar.buckla	eet depth with	sxs of
Ist plug @5.02nd plug @5.03rd plug @5	o.!Aho.ve. h.hydr.ite. o.!Below. o.!Below. e.hind.Wip chind.Wip district office se only: f	Ar.buckla	eet depth with	sxs of
Ist plug @5.02nd plug @5.03rd plug @5	o.!Aho.ve. h.hydr.ite. o.!Below. o.!Below. e.hind.Wip chind.Wip district office se only: f	Ar.buckla	eet depth with	sxs of 60/40 Poz 6% Ge1 sxs of " s
Ist plug @5.02nd plug @5.03rd plug @5	o.!Aho.ve. h.hydr.ite. o.!Below. o.!Below. e.hind.Wip chind.Wip district office se only: f	Ar.buckla	t office on plug placement plugged or product (Call 7 a.m. to 5	sxs of
Ist plug @5.02nd plug @5.03rd plug @5	o.!Aho.ve. h.hydr.ite. o.!Below. o.!Below. e.hind.Wip chind.Wip district office se only: f	Ar.buckla	t office on plug placement plugged or product (Call 7 a.m. to 5	sxs of 60/40 Poz 6% Ge1 sxs of " s