

CARD MUST BE SIGNED

XX East

.... NE Sec 32 . Twp27 . S, Rge . 22. ☐ West
(location)

.....3465. Ft North from Southeast Corner of Section

.....825.. Ft West from Southeast Corner of Section

(Note: Locate well on Section Plat on reverse side)

Nearest lease or unit boundary line825..... feet.

CountyCrawford.....

Lease NameParker..... **Well#** 14.....

Domestic well within 330 feet : ☐ yes ☒ no

Municipal well within one mile : ☐ yes ☒ no

☒ Oil ☐ Swd ☒ Infield ☒ Mud Rotary

☐ Gas ☐ Inj ☐ Pool Ext. ☐ Air Rotary☐ **OWWO** ☐ **Expl** ☐ **Wildcat** ☐ **Cable**

If OWWO: old well info as follows:

Operator

Well Name

Comp Date **Old Total Depth**

Projected Total Depth600..... feet

Projected Formation at TD

Expected Producing Formations

Depth to Bottom of fresh water20..... feet

Lowest usable water formation

Depth to Bottom of usable water10.0..... feet

Surface pipe by Alternate : 1 ☐ 2 ☒

Surface pipe to be set20..... feet

Conductor pipe if any required feet

Ground surface elevation **feet MSL**

This Authorization Expires 3-12-85

Approved By 9-12-84 *[Signature]*

I certify that we will comply with K.S.A. 55-101, et seq., plus eventually plugging hole to K.C.C. specifications.

Date ...9-12-84... Signature of Operator or Agent *Glen Duck* Title ...As Agent.....

Form C-1 4/84

Must be filed with the K.C.C. five (5) days prior to commencing well
This card void if drilling not started within six (6) months of date received by K.C.C.
CONSERVATION DIVISION
Wichita, Kansas


SFP 12 1984

STATE CORPORATION COMMISSION
A Regular Section of Land
1 Mile = 5,280 Ft.

9-12-84

Important procedures to follow :

1. Notify District office before setting surface casing.
2. Set surface casing by circulating cement to the top.
3. File completion forms ACO-1 with K.C.C. within 90 days of well completion, following instructions on ACO-1, side 1, and including copies of wireline logs.
4. Notify District office 48 hours prior to old well workover or re-entry.
5. Prior to plugging, prepare a plugging plan, then obtain agreement from the appropriate district office for an approved plugging plan.
6. Submit plugging report (CP-4) to K.C.C. after plugging is completed.
7. Obtain an approved injection docket number before disposing of salt water.
8. Notify K.C.C. within 10 days when injection commences or terminates.
9. If an alternate 2 completion, cement in the production pipe from below any usable water to surface within 120 days of spud date.



State Corporation Commission of Kansas
Conservation Division
200 Colorado Derby Building
Wichita, Kansas 67202
(316) 263-3238