

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: Brungardt Oil & Leasing, Inc.
Address: PO Box 871, Russell, KS 67665
Phone: (785)483-4975 Operator License #: 3956
Type of Well: D & A Docket #: _____
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR)
The plugging proposal was approved on: 1-27-2007 (Date)
by: Pat Staab (KCC District Agent's Name)
Is ACO-1 filed? Yes No If not, is well log attached? Yes No
Producing Formation(s): List All (if needed attach another sheet)

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

API Number: 15-141-20,369-00-00
Lease Name: Koelling "C"
Well Number: 1
Spot Location (QQQQ): SW - SW - NW -
1,990 Feet from North / South Section Line
590 Feet from East / West Section Line
Sec. 30 Twp. 10 S. R. 14 East West
County: Osborne
Date Well Completed: 1-27-07
Plugging Commenced: 1-27-07
Plugging Completed: 1-27-07

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)				
Formation	Content	From	To	Size	Put In	Pulled Out
				8 5/8"	217'	Cmtd. w/165 sax

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Run drill pipe to 3,610', pump 25 sax cement thru drill pipe; run drill pipe to 1,030', pump 25 sax cement thru drill pipe; run drill pipe to 540', pump 80 sax cement thru drill pipe; run drill pipe to 267', pump 40 sax cement thru drill pipe; push wiper plug to 40', dump 10 sax cement on plug to cellar. Circulate .15 sax cement down rat hole and 10 sax down mouse hole. Spot mud

Name of Plugging Contractor: Shields Drilling Co. License #: 5184
Address: PO Box 709, Russell, KS 67665

RECEIVED
KANSAS CORPORATION COMMISSION
FEB 07 2007

Name of Party Responsible for Plugging Fees: Brungardt Oil & Leasing, Inc.

State of KANSAS County, RUSSELL, ss.

Burton Beery, Drilling Supt. Contractor
(Employee of Operator) or (Operator)

CONSERVATION DIVISION
WICHITA, KS


sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

(Signature) Burton Beery
(Address) PO Box 709, Russell, KS 67665

SUBSCRIBED and SWORN TO before me this 5th day of February, 2007

Ruth Phillips
Notary Public

My Commission Expires: _____



Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

Handwritten initials