

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
December 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: SunStone Operating Company, LLC
Address: 101 N. Robinson, Suite 810
Phone: (405) 605-1274 Operator License #: 33802
Type of Well: D&A Docket #: _____
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR)
The plugging proposal was approved on: _____ (Date)
by: _____ (KCC District Agent's Name)
Is ACO-1 filed? Yes No If not, is well log attached? Yes No
Producing Formation(s): List All (If needed attach another sheet)

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

Depth to Top: _____ Bottom: _____ T.D. _____

API Number: 15 - 171-20640-0000
Lease Name: Betty
Well Number: 1
Spot Location (QQQQ): _____ - NW - SW - NW
1650 Feet from North / South Section Line
330 Feet from East / West Section Line
Sec. 10 Twp. 19 S. R. 31 East West
County: Scott
Date Well Completed: _____
Plugging Commenced: 8/30/06
Plugging Completed: 8/30/06

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)				
Formation	Content	From	To	Size	Put In	Pulled Out
		Surface	373	8-5/8"	373	0

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.


POOH to 2300'. Pump 50 sx 60/40 Pozmix w 6% gel & 1/4# Floseal. POOH to 1650'. Pump 50 sx 60/40 Pozmix w 6% gel & 1/4# Floseal.
POOH to 700'. Pump 80sx 60/40 Pozmix w 6% gel & 1/4 # Floseal. POOH to 400'. Pump 50sx 60/40 Pozmix w 6% gel & 1/4# Floseal. POOH to 60'. Pump 20 sx 60/40 Pozmix w 6% gel & 1/4# Floseal. Rathole: Pump 15 sx 60/40 Pozmix w 6% gel & 1/4# Floseal.
Mousehole: Pump 10 sx 60/40 Pozmix w 6% gel & 1/4# Floseal.

Name of Plugging Contractor: Cheyenne Well Service, Beredco Inc License #: KLN 6454-5147
Address: P. O. Box 384, Ness City, KS 67560
Name of Party Responsible for Plugging Fees: SunStone Operating Company, LLC
State of _____ County, _____, ss.
Connie Swan (Employee of Operator) or (Operator) on above-described well, being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

KCC PET
3/28/07 per
CP2/3

(Signature) Connie Swan

(Address) 4663 S Maplewood Ave, Tulsa, OK 74135



Notary Public Sherry L. Jelinek My Commission Expires: 2-1-08
Notarized and SWORN TO before me this 22 day of March, 2007

Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

RECEIVED
MAR 26 2007
KCC WICHITA