STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Conservation Division State Corporation Commission 211 No. Broadway

WELL PLUGGING RECORD

		and the second s	r footage from	linge C S	77 N77 NE		
NORTH		Location as "NE/CNW%SW%" or footage from lines C S/2 N/2 NE					
		Lease Owner S. and C. Drilling, Inc.					
	Lease Name C. R. Porter Well No. 1 Office Address Box 271 Hays, Kansas						
	Office Address				5 0 3		
	1	Vell (completed a			11-7	19 6	
		npleted r plugging filed			11-7	19 6	
	Application for	r plugging nied r plugging approv			11-/	19 6	
		nenced				19 6	
		pleted				₁₉ 6	
		andonment of wel				A	
	11000001100100					and the second s	
	If a producing	well is abandon	ed, date of last	t production		19	
						e plugging was con	
Locate well correctly on above Section Plat	mencedr						
ne of Conservation Agent who sup	pervised plugging of the	nis well Els	on Petty	Y			
lucing formation		Depth to top	Bottom_		Total Depth of V	Vell 3628 Fe	
w depth and thickness of all water	r, oil and gas formatic	ons.					
OIL, GAS OR WATER RECOR	rDS				C.	ASING RECORD	
TE, GAS ON WATER RECORD			T		1 		
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED DUT	
			 				
			 				
			 				
			 				
through drill pipe		Set pl with heavy	mud to	xed & po 180 ft.		ks cement poured 20 s. cement.	
through drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20	
through drill pipe through drill pipe	e. Filled w	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20	
through drill pipe through drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20	
through drill pipe through drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20	
through drill pipe through drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20	
through drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20	
through drill pipe through drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20	
through drill pipe through drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20	
chrough drill pipe chrough drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20 s. cement.	
chrough drill pipe chrough drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20	
hrough drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20 s. cement.	
chrough drill pipe chrough drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20 s. cement.	
through drill pipe through drill pipe	e. Filled w e. Mud to 4	. Set pl with heavy 10'. Plug	ug. Min mud to	xed & po 180 ft. ack hull	Mixed &	poured 20 s. cement.	
through drill pipe through drill pipe	e. Filled we. Mud to 4	. Set pl with heavy 10'. Plug	ug. Mir mud to	xed & po 180 ft. ack hull 64	Mixed &	poured 20 s. cement.	
through drill pipe through drill pipe Pluggin	e. Filled we. Mud to 4	. Set plyith heavy 10'. Plug	ug. Mir mud to	xed & po 180 ft. ack hull 64	Mixed &	poured 20 s. cement.	
through drill pipe through drill pipe Pluggin Pluggin me of Plugging Contractor.	e. Filled we. Mud to 4 ng completed	. Set plyith heavy 10'. Plug	ug. Mir mud to	xed & po 180 ft. ack hull 64	Mixed &	poured 20 s. cement.	
through drill pipe through drill pipe Pluggin Pluggin me of Plugging Contractor.	e. Filled we. Mud to 4 ng completed	. Set plyith heavy 10'. Plug	ug. Mir mud to	xed & po 180 ft. ack hull 64	Mixed &	poured 20 s. cement.	
through drill pipe through drill pipe Pluggin Pluggin me of Plugging Contractor	e. Filled we. Mud to 4 ng completed (If addition tools	set plyith heavy 10'. Plug	mud to we will be seen to the	xed & po 180 ft. ack hull 64 STATE COM:	Mixed & sk 10 sk sk sk 10 sk	poured 20 s. cement.	
through drill pipe through drill pipe Pluggin me of Plugging Contractor	e. Filled we. Mud to 4 ng completed (If addition tools	Set plyith heavy 10'. Plug 1 6:30 p.m nal description is necessary	mud to mud to see 2 see n. 11-7-	xed & po 180 ft. ack hull 64 STATE COM:	Mixed & sk 10 sk sk sk 10 sk	poured 20 s. cement.	
through drill pipe through drill pipe Pluggin me of Plugging Contractor dress	e. Filled we. Mud to 4 ng completed (If addition tools	Set plyith heavy 10'. Plug 1 6:30 p.m nal description is necessary	essary, use BACK	xed & po 180 ft. ack hull 64 STATE COME of this sheet)	Mixed & sk 10 sk sk sk 10 sk	e poured 20 s. cement. Owner of the above-descril	
through drill pipe through drill pipe Pluggin me of Plugging Contractor dress ATE OF Il, being first duly sworn on oath	e. Filled we will be a mud to 4 mg completed of the completed of the completed of the completed of the complete of the complet	o. Set plyith heavy 10'. Plug 16:30 p.m. DUNTY OF	employee of cacts, statemen	xed & po 180 ft. ack hull 64 STATE COME of this sheet)	Mixed & sk 10 sk sk sk 10 sk	e poured 20 s. cement. Owner of the above-descril	
through drill pipe through drill pipe Pluggin Pluggin me of Plugging Contractor dress ATE OF all, being first duly sworn on oath	e. Filled we will be a mud to 4 mg completed of the completed of the completed of the completed of the complete of the complet	o. Set plyith heavy 10'. Plug 10'. P	employee of cacts, statemen	xed & po 180 ft. ack hull 64 STATE COME of this sheet)	Mixed & sk 10 sk sk sk 10 sk	e poured 20 s. cement. Owner of the above-descril	
through drill pipe through drill pipe Pluggin me of Plugging Contractor dress ATE OF all, being first duly sworn on oath	e. Filled we will be a mud to 4 mg completed of the completed of the completed of the completed of the complete of the complet	o. Set plyith heavy 10'. Plug 16:30 p.m. DUNTY OF	employee of cacts, statemen	xed & po 180 ft. ack hull 64 STATE COME of this sheet)	Mixed & sk 10 sk sk sk 10 sk	e poured 20 s. cement. Owner of the above-descril	
through drill pipe through drill pipe Pluggin me of Plugging Contractor dress ATE OF all, being first duly sworn on oath	e. Filled we will be a mud to 4 mg completed of the completed of the completed of the completed of the complete of the complet	o. Set plyith heavy 10'. Plug 10'. P	employee of cacts, statemen	xed & po 180 ft. ack hull 64 STATE COME of this sheet)	Mixed & sk 10 sk sk sk 10 sk	e poured 20 s. cement. Owner of the above-descril	
through drill pipe through drill pipe Pluggin Pluggin me of Plugging Contractor dress ATE OF ell, being first duly sworn on oath ove-described well as filed and the	e. Filled we will be a mud to 4 mg completed of the complete of the compl	o. Set playith heavy 10'. Plug 10'. Plug 16:30 p.m. nal description is necessary of the and correct. So (Signature)	employee of cacts, statemen	xed & po 180 ft. ack hull 64 STATE COME of this sheet)	Mixed & sk 10 sk sk sk 10 sk	e poured 20 s. cement.	
through drill pipe through drill pipe Pluggin Pluggin me of Plugging Contractor dress ATE OF all, being first duly sworn on oath	e. Filled we will be a mud to 4 mg completed of the complete of the compl	o. Set plyith heavy 10'. Plug 10'. P	employee of cacts, statemen	xed & po 180 ft. ack hull 64 STATE COME of this sheet)	Mixed & sk 10 sk sk sk 10 sk	e poured 20 s. cement. Owner of the above-describ	
through drill pipe through drill pipe Pluggin Pluggin me of Plugging Contractor dress ATE OF All, being first duly sworn on oath ove-described well as filed and the	e. Filled we will be a mud to 4 mg completed of the complete of the comple	Note the place of the and correct. So (Signature)	employee of cacts, statemen	xed & po 180 ft. ack hull 64 STATE COME of this sheet)	Mixed & sk 10 sk sk sk 10 sk	e poured 20 s. cement. Owner of the above-describ	
through drill pipe through drill pipe Pluggin me of Plugging Contractor dress ATE OF all, being first duly sworn on oath ove-described well as filed and th	e. Filled we will be a mud to 4 mg completed of the complete of the comple	Note the place of the and correct. So (Signature)	employee of cacts, statemen	xed & po 180 ft. ack hull 64 STATE COME of this sheet)	Mixed & sk 10 sk sk sk 10 sk	e poured 20 s. cement. Owner of the above-descril	

5441

CERTIFIED DRILLER'S LOG

COMPANY: S. and C. Drilling, Inc.

Box 271

Hays, Kansas

CONTRACTOR: CO. TOOLS

COMMENCED UNDER SURFACE: 10-27-64

COMPLETED: 11-7-64

Opened hole to deepen: 11-12-64

COMPLETED: 11-15-64

LEASE: C. R. Porter

LOCATION: C S/2 N/2 NE

30-9-19W

Rooks County

CASING RECORD: 205' of 8-5/8"

Cemented with 125 sks.

ELEVATION: 2119 D.F.

2114 Gr. L.

POTENTIAL: D & A

FIGURES DENOTE TOP OF FORMATION.

FORMATION:	DEPTH:	
Surface clay & sand Shale & shells Shale Sand Shale Sand & shale Shale Sand Shale & sand Shale & sand Shale & red bed Shale & red bed Shale & shells Shale with lime streaks Shale Shale & lime Lime & shale Conglomerate Arbuckle	0 35 180 790 870 950 1020 1040 1210 1300 1530 1568 1825 2097 2245 2379 2470 2930 3208 3553 3582	JAN 13 1965 CONSERVATION DIVISION STATE CORPORATION COMMISSION JAN 13 1965 CONSERVATION DIVISION Wichita, Kansas
After emening hele	3628 T.D	D & A
After opening hole:		
Arbuckle remainder of hole.	3653 T. D.	D & A

S. and C. Orilling, Inc.

Sullivan, Exec. Vice- Pres.

I hereby certify that this is a true and correct copy of the above log to the best of my knowledge.