

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 30 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
September 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: J. D. Production
Address: P.O. Box 254 Geneseo, KS
Phone: (620) 824-6156 Operator License #: 8917
Type of Well: Gas Docket #: _____
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) (If SWD or ENHR)
The plugging proposal was approved on: _____ (Date)
by: Virgal Cothier (KCC District Agent's Name)
Is ACO-1 filed? Yes No If not, is well log attached? Yes No
Producing Formation(s): List All (If needed attach another sheet)
_____ Depth to Top: _____ Bottom: _____ T.D. _____
_____ Depth to Top: _____ Bottom: _____ T.D. _____
_____ Depth to Top: _____ Bottom: _____ T.D. _____

API Number: 15-159-20573-00-00
Lease Name: O'Neill
Well Number: 1
Spot Location (OOQQ): _____ C _____ SE _____ NW
3334 Feet from _____ North / South Section Line
3392 Feet from East / _____ West Section Line
Sec. 34 Twp. 18 S. R. 8 _____ East West
County: Rice
Date Well Completed: 9/8/1975
Plugging Commenced: 7/20/07
Plugging Completed: 7/20/07

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)				
Formation	Content	From	To	Size	Put In	Pulled Out
				<u>7.00 8 5/8"</u>	203'	None
				4 1/2"	1287'	968'
<u>KCC PER CP2/3 8/16/07</u>						

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed, from _____ feet to _____ feet each set.

Pulled out 38 jts. of 2 3/8" tubing. Sanded bottom to 1100' w/ 4sx. cement. Rigged up floor & pulled slips out. Cut casing @ 1050', not loose. Came up to 968', cut casing loose. Rigged up Copeland & pumped 35sx. @ 965' Pulled up to 750' & pumped 35sx. Pulled up to 260' & circulated cement with 80 sx. 60/40 Poz 4% Gel

Name of Plugging Contractor: Mike's Testing & Salvage, Inc. License #: 31529 RECEIVED
Address: P.O. Box 467 Chase, Kansas 67524 KANSAS CORPORATION COMMISSION

Name of Party Responsible for Plugging Fees: J.D. Production AUG 08 2007

State of Kansas County: Rice ss. _____
Mike Kelso (Employee of Operator) or (Operator) on above-described well, being first duly

sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.


(Signature) Mike Kelso

(Address) P.O. Box 467 Chase, Kansas 67524

SUBSCRIBED and SWORN TO before me this 7th day of August, 2007

Irene Herzberg
Notary Public

My Commission Expires: _____



Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

PKT