

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM  
File One Copy

Lease Owner Petroleum, Inc. Address 311 East Third, Wichita, Kansas  
(Applicant)

Lease (Farm Name) THOMPSON 'A' Well No. 1

Well Location NE NE SE Sec. 32 Twp. 8S Rge. (E) - (W) 18W

County Rooks Field Name (if any) \_\_\_\_\_

Total Depth 3485' Oil \_\_\_\_\_ Gas \_\_\_\_\_ Dry Hole X

Was well log filed with application? \_\_\_\_\_ If not, explain: \_\_\_\_\_

\_\_\_\_\_ Herewith \_\_\_\_\_

Date and hour plugging is desired to begin January 2, 1956

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner \_\_\_\_\_

Mr. C. W. Bard Address 1201 Taft, Great Bend, Kansas

Plugging Contractor Garvey Drilling Company

Plugging Contractor's License No. \*\*\*\*\*

Address R. R. #2 - Great Bend, Kansas

Invoice covering assessment for plugging this well should be sent to \_\_\_\_\_

Petroleum, Inc. Address 311 East Third, Wichita, Kansas

and payment will be guaranteed by applicant.

Karl E. Becker  
Applicant or Acting Agent

Date January 2, 1956

JAN 12 1956  
CONSERVATION DIVISION  
WICHITA, KANSAS

**PLUGGING**  
FILE SEC. 32 T. 8 R. 18W  
BOOK PAGE 30 LINE 13



STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
211 NORTH BROADWAY  
WICHITA, KANSAS

January 9, 1956

Well No.	1
Lease	Thompson "A"
Description	NE 1/4 SW 32-8-18W
County	Hooker
File No.	30-13

Petroleum, Inc.  
311 East Third  
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Nay 8, Kansas.

STATE CORPORATION COMMISSION  
CONSERVATION DIVISION

By S. S. Greider  
S. S. Greider  
WELL PLUGGING SUPERVISOR

cc:  
District Plugging Supervisor