|5-16320520-00-00 STATE OF KANSAS

STATE CORPORATION COMMISSION CONSERVATION DIVISION

Rev. 3-15-72 FORM CP-1

	CONSERVATION DIVISION	FORM CP-1
	P. O. BOX 17027 Wichita, Kansas 67217	STATE COPIE
	WELL PLUGGING APPLICATION FORM	An PORIEIL
Lease Owner	File One Copy  W.  Mr. J.B. Collins	STATE CORP. C. P. J. P. O.
Estimphylipse Colorina halle when chi salle sharper and the colorina sh	Box 393, Plainville, Kansas 67663	See Son
	Hamel woll	
	SW SW SE Sec. 6 Twp. 8S Rge. 20	
		WASHINGTON CONTROL ACCIONATION CONTROL OF THE CONTR
	Rooks Total Depth 3505' Fi	decembrane at \$100-based everywher, sterler covering in outside up an ever attitue
Oil Well Gas Well	Input Well SWD Well Rotary D	8 A X
Well Log filed with ap	oplication as required Yes	
Date and hour plugging	is desired to begin April 8, 1974 - 3:3	80 P.M.
	WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-12 TTE CORPORATION COMMISSION.	8 OF THE RULES AND
Name of company repres	entative authorized to be in charge of plugg	ing operations:
William State of the Control of the	Address	
Plugging Contractor	Red Tiger Drilling Company Li	cense No.
Address	1720 Wichita Plaza, Wichita, Kansas 672	02
Invoice covering asses	sment for plugging this well should be sent	to:
Name	Mr. J.B. Collins	
Address	Box 393, Plainville, Kansas 67663	BORGON CANCER Dan BREICH ge Meille Gelle Gelde Gel
and payment will be gu	aranteed by applicant or acting agent. MR. J.B. COLL	INS
	Signed:	
	Applicant	or Acting Agent
	Date:	



## 15-163-20520-00-00

## State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water) P.O. Box 17027 3830 S. Meridian WICHITA, KANSAS 67217

April 15, 1974

## WELL PLUGGING AUTHORITY

Well No.

Hamel

Lease

Description County

SW SW SE Sec. 6-8S-20W

Total Depth

Rooks 3505

Plugging Contractor Red Tiger Drilling

J. B. Collins P. O. Box 393 Plainville, Kansas 67663

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Vours very freiv.

is hereby assigned to supervise the plugging of the above named well.