KANSAS

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

EIVED

J. P. Roberts Administrator 500 Insurance Building Wichita 2, Kansas

'NV. NO. _

15-163-20078-00-00

DEC 4 186/ 12-04-1967 Constitution Division

Operator's Full Name Three G Oil, Inc.,
Complete Address: 1101 Wichita Plaza Wichita, Kansas
Lease Name Benedick Well No. 1
Location SW NE SW Sec. 3 Twp. 10 Rge. 18 (E) (W) X
County Rooks Total Depth 3770
Abandoned Oil Well Gas Well Input Well SWD Well D & A X
Other well as hereafter indicated:
Plugging Contractor: H = 30 Drlg, Inc.,
Address: Wichita, Kansas License No.
Operation Completed: Hour 6 A Day 2 Month 12 Year 1967
The Above well was plugged as follows:
RTD 3770' 8 5/8 csg set at 239' cwc. 180 sc.
Gunned pits, circulated heavy mud, set cementing plug at 800' and displaced 100 sc
cement thru drill pipe. Heavy mud to 240° set cementing plug and displaced 25 sc cem.
thru drill pipe. Heavy mud to 40° set cementing plug, 1/2 sc hulls and 10 sc cement to
base of cellar. Plugged rat hole with 2 sc cement.
hereby certify that the above well was plugged as herein stated.
Signed: Son J. M. assey. Well Plugging Supervisor
DATE 12/5/10

State of Kansas

ROBERT B. DOCKING WILLIAM L. MITCHELL JAMES O. GREENLEAF Commissioner DALE E. SAFFELS Commissioner RAYMOND B. HARVEY E. EDWARD JOHNSON Gen. Counsel

15-163-20078-00-00

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water) 500 Insurance Bldg. 212 N. Market WICHITA, KANSAS 67202

VERBAL PERMIT FORM (To Be Filed By Plugging Agent)

15-113-20078-00-00

DEC 4 196/

12-04-1967 CONTRACTOR DIVISION

J. P. Roberts Administrator 500 Insurance Building Wichita, Kansas 67202

Dear Sir:

Governor

Chairman

Secretary

Mr.	Cameror	1	of	H-30 Drlg.I	ne.	has this	
date	requested	permission	to plug	the followi	ng describe	d well:	
Mr.	Came re n	,	guar	antees payme	nt of the p	lugging fee.	
Opera	ator's full	Name:	Three G	Oil, Inc.,			
Comp.	Lete Addres	3 2	1101 Wic	hita Plaza	Wichita,	Kansas	
Lease	Name:	Ben	edick		Well No. 1		
		•				e. 18 (E) (W) X	
*	ty:				Depth 3770		
Gas V	VellIn	out Well	swd w	ellD &	A X Lost	t Hole	
		,			•	ll as follows:	
Gun pits, circulate heavy mud, set cementing plug at 800° and displace							
100 s	c cement th	ru drill l	pipe. Hea	avy mud to 21	+0° set ceme	nting plug and	
lispl	ace 25 sc c	ement thru	ı d ri ll p	pipe. Heavy n	nud to 40° s	et cementing	
olug,	1/2 sc hul	ls and 10	sc cemer	nt to base of	cellar. Pl	ug rat hole	
vith :	2 sc cement	•					

Very truly yours,