

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 30 days from plugging date.

KANSAS CORPORATION COMMISSION
OIL & GAS CONSERVATION DIVISION
WELL PLUGGING RECORD
K.A.R. 82-3-117

Form CP-4
September 2003
Type or Print on this Form
Form must be Signed
All blanks must be Filled

Lease Operator: Vess Oil Corporation
Address: 1700 Eaterfront Pkwy. #500 Wichita, Ks. 67206
Phone: (316) 682-1537 Operator License #: 5030
Type of Well: Oil DH KCCPRT Per CPA/3 10/12/07
(Oil, Gas D&A, SWD, ENHR, Water Supply Well, Cathodic, Other) Docket #: _____ (If SWD or ENHR)

API Number: 15-191-20,389-00-01

Lease Name: Springer

Well Number: 1 OWWO KCCPRT 10/12/07 PM

Spot Location (OOQQ): Approx. C-SW-NE ROBINS

1965 Feet from North / South Section Line

1830 Feet from East / West Section Line

Sec. 21 Twp. 33 S. R. 4 East West

County: Sumner

Date Well Completed: _____

Plugging Commenced: 8-7-07

Plugging Completed: 8-24-07

The plugging proposal was approved on: _____ (Date)

by: Steve Van Giesen (KCC District Agent's Name)

Is ACO-1 filed? Yes No If not, is well log attached? Yes No

Producing Formation(s): List All (If needed attach another sheet)

_____ Depth to Top: _____ Bottom: _____ T.D. _____
_____ Depth to Top: _____ Bottom: _____ T.D. _____
_____ Depth to Top: _____ Bottom: _____ T.D. _____

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface Conductor & Production)				
Formation	Content	From	To	Size	Put In	Pulled Out
				8-5/8"	258'	None
				4-1/2"	4303'	3390'

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed, from _____ feet to _____ feet each set.

Plugged off bottom with sand to 4120' and 4 sxs. cement. Cut casing loose @3390', pulled 1210' of casing, well kicked off, pumped 100sxs. @2180', 35 sxs. @800' & 200 sxs. @500'. Top plug was leaking, had to drill out cement. Ran tubing to 1850', pumped 50 sxs. cement, pulled up to 854', pumped 50 sxs. cement, pulled up to 509', pumped 50 sxs. cement, pulled up to 305' and circulated 100 sxs. to surface. Layed rest of tubing down. Plugging Complete.

Name of Plugging Contractor: Mike's Testing & Salvage, Inc. License #: 31529

Address: P.O. Box 467 Chase, Kansas 67524

Name of Party Responsible for Plugging Fees: Vess Oil Corporation

State of Kansas County: Rice ss.

Mike Kelso (Employee of Operator) or (Operator) on above-described well, being first duty sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.


(Signature) Mike Kelso

(Address) P.O. Box 467 Chase, Kansas 67524

SUBSCRIBED and SWORN TO before me this 2nd day of October, 2007

Irene Herzberg
Notary Public

My Commission Expires: _____



Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

RECEIVED
KANSAS CORPORATION COMMISSION
OCT 05 2007

[Handwritten initials]