STATE OF KANSAS STATE CORPORATION COMMISSION

Form CP-4

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
212 No. Market
Wichita Kaness

WELL PLUGGING RECORD

212 No. Market	Rooks		Count	y. 3ec 1	wp nge	(E) 19 (W)
Wichita, Kansas NORTH	Location as "NE	CNW%SW%"	or footage fro	m lines NW	NW SW	
MODIFICAÇÃO DE SECURIO DE CONTRACTOR DE CONT	Lease Owner	Rains &				
	Lease Name			7		Well No. 1
	1			_		ta, Kansas
	Character of We					11-26 19 66
	Date well comp Application for			and the majority describes a second state of the second state of t		11-26 19 66
	Application for p				And the state of t	11-26 19 66
	Plugging comme					11-26 ₁₉ 66
	Plugging comple					<u>11-26 ₁₉ 66</u>
					no oil or	gas found
	in commercial quantities If a producing well is abandoned, date of last production					
Locate well correctly on above				ation Division o	r its agents befo	ore plugging was com-
Section Plat me of Conservation Agent who su	menced?	well T.e	o Masse	v Havs	Kangag	oceaning and the second
ducing formation	D	epth to top	Botton	y , 114 <u>y</u> 10 ,	Total Depth of	Well 3565 Feet
ow depth and thickness of all wat						
_					,	TACING DECORD
OIL, GAS OR WATER RECO	מש				1	CASING RECORD
FORMATION	CONTENT	FROM	ОТ	SIZE	PUT IN	PULLED DUT
				8-5/8	228.95	
						*
			+			
				1		
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented 1shed plug and Set solid by	d throug d cement ridge an	h drill ed thru d cappe	pipe wit	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented ished plug and Set solid bring completed (If additional	d througd cement ridge an at 5:00	h drill ed thru d capped P.M.	pipe wit drill pi d with 8	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi	set. 10'. Cemented ished plug and Set solid browning completed in the completed in the complete in the comple	d through cement ridge an at 5:00 description is need to be a second to be a seco	h drill ed thru d capped P.M. P.M.	pipe witdrill pid with 8	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu	set. 10'. Cemented ished plug and Set solid browning completed in the completed in the complete in the comple	d through cement ridge an at 5:00 description is need to be a second to be a seco	h drill ed thru d capped P.M. P.M.	pipe witdrill pid with 8	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi	set. 10'. Cemented ished plug and Set solid browning completed in the completed in the complete in the comple	d througd cement ridge an at 5:00	h drill ed thru d capped P.M. P.M.	pipe witdrill pid with 8	th 25 sac	ks. Mud 20 sax.
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi	set. 10'. Cemented ished plug and Set solid browning completed in the completed in the complete in the comple	d throught cement ridge an at 5:00 description is need to be a second wich ita	h drill ed thru d capped P.M. P.M. essary, use BACK Oil Co. , Kansas	pipe with drill pid with 8	th 25 sactipe with sax. 2	ks. Mud 20 sax.
rat hole. Plugging Contractor diress 1425 Wichita	set. 10'. Cemented ished plug and Set solid by Ing completed ing completed ing completed ing completed ing Rains & Will Plaza Bldg.,	d through cement ridge an at 5:00 description is need to be a second with the liamson wichita	h drill ed thru d capped P.M. essary, use BACK Oil Co. , Kansas	pipe with drill pid with 8	th 25 sactipe with sax. 2	ks. Mud 20 sax. sax. in
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi me of Plugging Contractor_ idress	Set. 10'. Cemented ished plug and Set solid by Ing completed ing completed ing completed ing Rains & Will Plaza Bldg., COULT, says: That I have known is the control of t	d through cement ridge an at 5:00 description is need to the liamson wich ita NTY OF S weldge of the	h drill ed thru d capped P.M. essary, use BACK Oil Co. , Kansas edgwick	pipe with drill pid with 8	th 25 sactipe with sax. 2	ks. Mud 20 sax. sax. in
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi me of Plugging Contractor_ ldress1425_Wichita ATE OFKansasWilson_Rains sll, being first duly sworn on oath	Set. 10'. Cemented ished plug and Set solid by Ing completed ing completed ing completed ing Rains & Will Plaza Bldg., COULT, says: That I have known is the control of t	d through cement ridge an at 5:00 description is need to be with the liamson wichita	h drill ed thru d capped P.M. essary, use BACK Oil Co. , Kansas edgwick	pipe with drill pid with 8 With 8 Of this sheet) Sowner) or (ownents, and matter	th 25 sactipe with sax. 2	ks. Mud 20 sax. sax. in
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi me of Plugging Contractor ldress 1425 Wichita "ATE OF Kansas Wilson Rains sll, being first duly sworn on oath	completed (If additional Rains & Will Plaza Bldg., COULT, says: That I have known at the same are true and	d throught cement ridge an at 5:00 description is need liamson Wichita NTY OF S owledge of the decorrec So	h drill ed thru d capped P.M. essary, use BACK Oil Co. , Kansas edgwick employee of acts, statement	pipe with drill pid with 8 d with 8 for this sheet) sowner) or (ownents, and matter	th 25 sactipe with sax. 2	ks. Mud 20 sax. sax. in
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi	completed (If additional Rains & Will Plaza Bldg., COULT, says: That I have known at the same are true and	d throught cement ridge an at 5:00 description is need tiamson wichita NTY OF S owledge of the d correct So (Signature)	h drill ed thru d capped P.M. essary, use BACK Oil Co. , Kansas edgwick employee of cats, statement help me God. Wilson I	pipe with drill pid with 8 with 8 of this sheet) sowner) or (ownents, and matter	sax. 2	ks. Mud 20 sax. sax. in of the above-described ed and the log of the
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi ame of Plugging Contractor ddress 1425 Wichita "ATE OF Kansas Wilson Rains sll, being first duly sworn on oath	completed (If additional Rains & Will Plaza Bldg., COULT, says: That I have known at the same are true and	d throught cement ridge an at 5:00 description is need tiamson wichita NTY OF S owledge of the d correct So (Signature)	h drill ed thru d capped P.M. essary, use BACK Oil Co. , Kansas edgwick employee of cats, statement help me God. Wilson I	pipe with drill pid with 8 d with 8 Gof this sheet) Sowner) or (ownents, and matter Rains (Chita Pla	sax. 2	ks. Mud 20 sax. sax. in
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi me of Plugging Contractor_ ldress1425_Wichita ATE OFKansasWilson_Rains ll, being first duly sworn on oath	set. 10'. Cemented ished plug and Set solid by ing completed. (If additional Rains & Will Plaza Bldg., COULT, says: That I have known at the same are true and the same are tr	d throught cement ridge an at 5:00 description is need tiamson wichita NTY OF S owledge of the d correct So (Signature)	h drill ed thru d capped P.M. essary, use BACK Oil Co. , Kansas edgwick employee of efacts, statement help me God. Wilson I	pipe with drill pid with 8 of this sheet) Sowner) or (ownents, and matter Rains (Chita Pla	sax. 2 sax. 2 sax. 2 ss. er or operator) of the sherein contains and say an	ks. Mud 20 sax. sax. in of the above-described and the log of the
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi me of Plugging Contractor dress 1425 Wichita ATE OF Kansas Wilson Rains ll, being first duly sworn on oath ove-described well as filed and the	set. 10'. Cemented ished plug and Set solid by ing completed. (If additional Rains & Will Plaza Bldg., COULT, says: That I have known at the same are true and the same are tr	d throught cement ridge an at 5:00 description is need Liamson Wichita NTY OF S owledge of the d correct So (Signature)	h drill ed thru d capped P.M. essary, use BACK Oil Co. , Kansas edgwick employee of efacts, statement help me God. Wilson I	pipe with drill pid with 8 of this sheet) Sowner) or (ownents, and matter Rains (Chita Pla	sax. 2	ks. Mud 20 sax. sax. in of the above-described and the log of the
Pushed plug to 54 back to 220'. Pu Mud back to 40'. rat hole. Pluggi me of Plugging Contractor dress 1425 Wichita ATE OF Kansas Wilson Rains II, being first duly sworn on oath ove-described well as filed and the	(If additional Rains & Will Plaza Bldg., COULT, says: That I have known at the same are true and fore me this 30	d throught cement ridge an at 5:00 description is need Liamson Wichita NTY OF S owledge of the d correct So (Signature)	h drill ed thru d capped P.M. essary, use BACK Oil Co. , Kansas edgwick employee of acts, stateme heln me Cod Wilson I 1425 Wic Novemb	pipe with drill pid with 8 of this sheet) Sowner) or (ownents, and matter Rains (Chita Pla	sax. 2 sax. 2 sax. 2 ss. er or operator) of the sherein contains and say an	ks. Mud 20 sax. sax. in of the above-described and the log of the

ROTARY DRILLING LOG

Operator: Rains & Williamson Oil Co.

#1 Stull

NW NW SW Sec. 8-9S-19W Rooks County, Kansas

Contractor:

Rains & Williamson Oil Co.

Commenced: 11-19-66

Completed: 11-26-66

Remarks: Set 228.95° of 8-5/8" surface pipe with 165 sacks GL-3.

FORMATIONS

Soil & Rock	75 °
Shale	945°
D. Sand	1180,
Shale	1464°
Anhydrite	1506°
Red Bed	1860°
Shale	218 5 °
Lime & Shale	2335°
Lime w/Shale	2480°
Lime & Shale	2860°
Lime W/Shale	3010°
Lime & Shale	3260°
Lime w/Shale	3325°
Lime & Shale	3490°
Lime w/Shale	3525°
Lime	3 54 5 °
Arb. Lime	3565°
Rotary Total Depth ((D&A) 3565°



We certify the above log is live and correct to the best of one knowledge and belief.

RAINS & WILLHAMSON OLL CO.

o busiles and sword to before me, a Notary Public in and for the State of the seas, county of Sadgwick, this 30# day of November 1965.

TV A TRANSPIROR MEGIFORS

Marie J. Bricana Continuos matrico