STATE OF KANSAS STATE CORPORATION COMMISSION 200 Colorado Derby Building Wichitz, Kansas 67202	WELL PLUGGING RECORD K.A.R82-3-117	API NUMBER 5-20-49 - 0 1491-00
		LEASE NAME Thompson
	TYPE OR PRINT NOTICE: Fill out completely and return to Cons. Div. office within 30 days.	WELL NUMBER3
		330 . Ft. from S Section Line
		330 Ft. from E Section Line
LEASE OPERATOR AFG Energy In	nc.	SEC. 9 TWP. 98 RGE. 17 (6) or (W)
ADDRESS P.O. Box 458 Hays , Ka	•	COUNTY Rooks
PHONE \$ ( 913 625-6374 OPERATORS LICENSE NO. 3456		Date Well Completed 5-20-49
Character of Wellojl		Plugging Commenced 6-16-93
(Oil, Gas, D&A, SWD, Input, Wat	ter Supply Well)	Plugging Completed
The plugging proposal was appro		(da†e)
by Don Butcher		(XCC District Agent's Name).
Is ACO-1 filed? Yes If		· · · · · · · · · · · · · · · · · · ·
		Bottom 3470 T.D. 3470'
Show depth and thickness of all	water, oil and gas formation	15.
OIL, GAS OR WATER RECORDS	CAS	SING RECORD
Formation Content		tuo belluq ni tu
Sand Oil & Water		26 None
	<u>" 3340 3458 5 1/2"</u>	3487' None
praced and the method of metho	os used in introducina it int	Indicating where the mud fluid was to the hole. If cement or other plug d, from feet to feet each set
		1 102
Name of Plugging Contractor		11014
Address Russell , Kansas		License No ENED RECEIVED COMMISSION STATE LORDON AND 1993
NAME OF PARTY RESPONSIBLE FOR P	LUCCINO EEEC.	STATE I DOPPING
STATE OF Kansas	COUNTY OFEllis	ployee of Operatory of Operator) o
Terry W. Piesker	(Em	ployee of Operatorition (Operator) o
services, and marrate life.	n contained and the log of th	That I have knowledge of the facts e above-described well as filed that
the same are true and correct,	so help me God. (Signature) <u>(</u>	Verry W. Presher
LINDA K. PFANNENSTIEL	(Address)	
NOTARY PUBLIC STATE DE KANSAS DAND	SWORN TO before me this 16	day of June
My Appt. Exp. 2/5/56	× ,	2 De State
и. а.	Expires: $2/5/96$	Notary Public
USE ONLY ONE SIDE OF EAC	CH FORM	

Form CP-4 Revised 05-88

15-163-01491-00-00

## Thompson #3 SE SE SE Sec. 9 -9S - 17W

Rooks Co., Kansas

-Condition of Well-

3-10-80

Had casing leak at 624'

Squeezed w/ 100 sx. common, 2% cc.

Appeared as if cement circulated.

Cement in cellar.

3-27-88

Set Cast Iron BP at 3143'.

3-15-90

Went in to repair casing.

Bottom holes - 1705' to 1736'.

Not communicated. Squeezed 1736' w/ 75 sx. common. Squeezed 1705' w/

75 sx. Common.

3-16-90

Went back in to find other holes -

Cement solid at 955'. Spotted holes

-675' to 165' from surface. Decided

to Abandon and plug.

6-16-93

cement. Cemented from 1736' to 955 NTE CORPORATION COMMISSION previously. Pumped 80 sec. previously. Pumped 80 sxs. 60/40 Poz., July 8 1993 10% gel. and 250# LT-11

10% gel. and 250# Hulls down tubing. Circulated kansas

Pulled tubing. Tied on to 5 1/2" Casing. Pumped 10 sxs. of same. Pressured to 500#. Held solid.

10 3/4" could not be found. Cement

in cellar.