

KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION AGENT'S REPORT

15-163-1982A 00-00
01009-00-01
RECEIVED
STATE CORPORATION COMMISSION
3/7/61
MAR 7 1961
CONSERVATION DIVISION
Wichita, Kansas

TO:
Jewel M. Ogden, Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

File No. _____ County: _____ Rooks _____
Location: NW NW NW Sec. 24 Twp. 9 Rge. 19 (E) (W) _____
Name of Field: _____ Total Depth: 3517

I have this date completed supervision of plugging of:

Lease Name: Thyfault Well No. 2

Operator's Full Name: Skelly Oil Co

Complete Address: 212 Wolcott Bldg Hutchinson, Kansas

Plugging Contractor: same & Halliburton Co

Address: _____ License No. 135

Oil Well Gas Well _____ Input Well _____ SWD Well _____ D & A _____

Other well as hereafter indicated: _____

Was any delay in plugging operations caused by Conservation Division Agent? Yes _____ No

If yes how long? _____ Reason: _____

Operation Completed: Hour 1PM Day 25 Month 2 Year 61

The above well was plugged as follows:

8 5/8" 292' circulated with cement - 5 1/2" 3515' with 500 sax cement -
& squeezed at 997' with 175 sax cement - perforated 3275 - PB 3290'.
No pipe recovery - Pumped hole full heavy mud (40 sax Gel) pumped plug
followed by 65 sax cement - found top cement at 1150' - filled hole with
gel mud 1150' to 600', set 10 sax cement at 600' - gel mud to 40', filled
with cement 40' to 0'.

Mudding and cementing by Halliburton Co.

Signed: *Jedon Letty*
Conservation Division Agent

Reviewed: *J. Lewis Bueh*
Field Supervisor

Remarks:

INVOICED
DATE 3/13/61
INV. NO. 2792-11