

15-065-00945-00-00

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Powell Drilling Company Address 412 Union Center, Wichita, Kansas
(Applicant)

Lease (Farm Name) Griffith Well No. 1

Well Location NW NW NW Sec. 21 Twp. 8 Rge. 23 ~~(XX)~~ - (W)

County Graham Field Name (if any) _____

Total Depth 3735 Oil Gas Dry Hole Dry Hole

Was well log filed with application? yes If not, explain: _____

Date and hour plugging is desired to begin December 11, 1957 - 4:00 P.M.

Plugging of the well will be done in accordance with the Rules and Regulations
of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

A. L. Thompson Address Box 62, Ellis, Kansas

Plugging Contractor Powell Drilling Company

Plugging Contractor's License No. _____

Address 412 Union Center, Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Powell Drilling Company Address 412 Union Center, Wichita, Kansas

and payment will be guaranteed by applicant.

RECEIVED
STATE CORPORATION COMMISSION

DEC 13 1957

CONSERVATION DIVISION
Wichita, Kansas

12-13-57

POWELL DRILLING COMPANY

[Signature]
Applicant or Acting Agent

Date December 11, 1957

PLUGGING
DEC 21 8 R236
BOOK PAGE 68 LINE 36

STATE OF KANSAS
State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

15-065-00945-00-00

December 13, 1957


Well No.	1
Lease	Griffith
Description	NW NW NW 21-8-23W
County	Graham
File No.	68-36

Powell Drilling Company
112 Union Center
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Eldon Petty, Box 326, Hays, Kansas Ph. 4-3218

Very truly yours,


Jewel M. Ogden
Director of Conservation Division

cc:
District Plugging Supervisor