Form CP-2/3

TO: STATE CORPORATION COMMISSION	API number: 15-175-21,025 -00-0
CONSERVATION DIVISION - PLUGGING 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	SE SW NE /4 SEC. 22 , 08 S, 26 W 2970 feet from S section line 1650 feet from E section line
Operator license# <u>6113</u>	Lease_C ROBBEN well #1-22
Operator: <u>LANDMARK OIL EXPLORATION</u>	
Address: 250 N. WATER SUITE 308 WICHITA, KANSAS 67202 (316) 265-8181	Well total depth 3850 feet Conductor Pipe: inch @ feet Surface pipe 8 5/8 inch @ 291 feet
Aband. oil well, Gas well, Inpu	ut well, SWD, D & A _X_
Plugging contractor: <u>HALLIBURTON SERVICES</u> License#	
Address:	
Company to plug at: Hour: PM Day:	28 Month: OCTOBER Year: 1991
Plugging proposal received from: RODNEY FARR	
Company: MURFIN DRILLING COMPANY	phone:
Were: Spot plugs through drill pipe w/ heavy mud between all plugs.	
1st plug @ 2090 feet with 25 sacks	Rat hole: 15 sacks
2nd plug @ <u>1210</u> feet " 100 "	Mousehole: 10 sacks Tree Compassion
3rd plug @ <u>345</u> feet " 40 "	NOV 4 1991
4th plug @ <u>40</u> feet " 10	with 8 5/8" wiper plug / (-4-91)
Plugging Proposal Received by: <u>Marvin L. Miller</u>	
Plugging operations attended by agent?	All[], Part[], None[X]
Completed: Hour: 7:00 PM , Day: 28 , Mon	th: <u>OCTOBER</u> , Year: <u>1991</u>
Actual plugging report: <u>Hole reported plugged as above.</u> Order sx 60/40 pozmix w/ 6% gel and 1/4# celloflake or flowcel per sk	
Remarks: Elevation: 2431, Anhydrite: 2071-	2105feet, Arbuckle: NONE.
Did NOT penetrate Arbuckle, cemented by HALLUBURTON SERVICES	
I Ad O / Cata Dot [X] observe the plugging. Marin of miller	
DATE 11-22-91 2:18	Marvin L. Miller P.I.R.T.II
INV. NO. 2262 July 7/26 0,	(agent)