4-031890

15-179.05176-00-01

	4- <u>031890</u>		1-03116-00-01
,	*	D-18,6	
	RPORATION COMMISSION	API number: 15-	
	TION DIVISION - PLUGGING RADO DERBY BUILDING	<u>SW SE SW</u> /4 SEC. <u>2</u> <u>330</u> feet from	S section line
	KADO DERBI BUILDING KANSAS 67202	3630 feet from	E section line
WICHIII,	Temoria Viava		
Operator	license#_5364_	Lease <u>Taylor</u>	well # 2A
- Operator	P.O. Box 723	County <u>Sheridan</u>	
3 3 3	D.O. Dom 700	Wall tatal danth 3	100 feet
Address:	Hays, Kansas 67601	Conductor Pipe: 0	inch @ O feet
-	nays, kansas 0/001	Surface pipe 8 5/8	Inch @ 276 feet
Aband. o	il well, Gas well, Inp	ut well, SWD <u>X</u>	_, D & A
	contractor: B. J. Services		
•	Hays, Kansas 67601		
Company	to plug at: Hour: P.M. Day:	17 Month: January	Year: 1989
Plugging	proposal received from: Bob G	rant	
Company:	Beren Corporation	Phone:	
Were:	Order 100 sxs. thrifty mix ce and 200# hulls.	ment blend 65/35 por	mix - 10% gel
Marie and the second se			
B			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Plugging	Proposal Received by: Carl	Goodrow	FED 23 SS 2/2
	operations attended by agent?		
Complete	d: Hour: <u>1:30P.M.</u> , Day: <u>17</u> , Mo	nth: January	, Year: <u>1989</u>
Actual p	lugging report: <u>8 5/8" set @ 00' cwc. 400 sxs. Squeezed 4</u>	2/6' WITH CWC. 185	SXS. 4 1/2"
blend wi	th 200# hulls mixed into Max.	P.S.T. 800#. Close	in P.S.T. 350#.
	plete. Cement at surface in b		
Remarks:	This is a report to replace	the "original" mispl	laced one.
Bottom n	u of casing(in note):GOOD <u>*</u> B lug(in place):VES	-NO Dakota 21:	NU
Plugged	This is a report to replace n of casing(in hole):GOOD / B lug(in place):YES,CALC / through TUBING, CASING /	Elevation:	GL
	()/ (id not[] observe the p	<i>A</i> • (o ()
# ## #	All the same -		

HO-

(agent)

Form CP-2/3