FORM CP-1

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
500 INSURANCE BUILDING
212 NORTH MARKET
WICHITA, KANSAS 67202

## WELL PLUGGING APPLICATION FORM File One Copy

Lease Owner John O. Farmer, Inc.
Address Box 352, Russell, Kansas 67665
Lease (Farm Name) Mickelson "C" Well No. 2
Well Location NW, SE, NE, Sec. 27 Twp. 8S Rge. 22W (E) (W)
County Graham County Field Name (If Any) Mickelson
Total Depth 3797' Oil Well X Gas Well Input Well SWD Well D & A
Well Log filed with application Yes or Well Log filed with Plugging Supervisor
Date and hour plugging is desired to begin May 18, 1971
Plugging of the well will be done in accordance with the Rules and Regulations of the State
Corporation Commission.
Name of company representative in charge of plugging operations Isadore T. Dreher
305 South Madison Address Plainville, Kansas 67663
Plugging Contractor Ralph Comstock Casing Pulling, Inc. License No.
AddressStafford, Kansas
invoice covering assessment for plugging this well should be sent to John O. Farmer, Inc.
Box 352 Address Russell, Kansas 67665
and payment will be guaranteed by applicant. Signed: John O. Paranel
Applicant or Acting Agent Bresident Date: April 26, 1971
Received:
Received: 6-9-197/

State of Kansas



## State Corporation Commission

## CONSERVATION DIVISION

(Oil, Gas and Water)

500 Insurance Bldg.

212 N. Market

WICHITA, KANSAS 67202

April 27, 1971

## WELL PLUGGING AUTHORITY

Well No.

Lease

Description

County

Total Depth

Plugging Contractor

2

Mickelson "C"

NW SE NE 27-8-22W

Graham 3797

Ralph Comstock Casing

Pulling

Gentlemen:

P.O. Box 352

John O. Farmer, Inc.

Russell, Kansas 67665

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Very truly yours,

Lewis Brock, Administrator

Mr. W. L. Nichols, P.O. Box 157, Morland, Kansas 67650 is hereby assigned to supervise the plugging of the above named well.