Form CP-4

STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Conservation Division State Corporation Commission

WELL PLUGGING RECORD

NORTH				7/11		e.3 (E) (W)	
		E/CNW%SW%"			E-SE-NW		
	Lease Owner Calvin Applegate Lease Name Ralston Well No. 1 Office Address Box 172, Augusta, Kdansas						
		Vell (completed		· / /			
	Date well com	Date well completed 6————————————————————————————————————					
	Application for	Application for plugging approved 19					
	Plugging commenced 6-8-64 19						
	Plugging completed 6-8-64 19					19	
	Reason for aba	ndonment of we	ll or producin	g formation	dry hol	<u>.e</u>	
	7f a producing	and in about	- 1 J.4 - C1			19	
						efore plugging was com-	
Locate well correctly on above Section Plat	menced?		,			yes	
Name of Conservation Agent who supe	ervised plugging of th	is well Par	<u>ul Turpin</u>	.			
Producing formation			Botton	n	Total Depth of	of Well 3111 Feet	
Show depth and thickness of all water	, oil and gas formation	ns.					
OIL, CAS OR WATER RECORE	OS					CASING RECORD	
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED DUT	
	And the second s						
			ļ		 		
			-				
			20 sacks				
Set a 5 ft. rock to surface. (bridge at 30 :	ft. and add	ded_10_sa	cks cement	RECE	TON COMMISSION 164 1964	
Set a 5 ft. rock	bridge at 30 :	ft. and add	ded_10_sa	cks cement	RECE ATE CORPORAT 7/2 JUL 2 ONSERVATI		
Set a 5 ft. rock	bridge at 30 : 484 ft. of 8	ft. and add	ded 10 sa	cks cement	RECE ATE CORPORAT 7/2 JUL 2 ONSERVATI	10N COMMESSION /64 1964 ON DIVISION	
Set a 5 ft. rock to surface. (bridge at 30 : 484 ft. of 8 /	ft. and add 5/8" surface l description is necessary	ded 10 sa ce pipe)	cks cement	RECE ATE CORPORAT 7/2 JUL 2 ONSERVATI	10N COMMISSION 164 1964 ON DIVISION	
Set a 5 ft. rock to surface. (bridge at 30 : 484 ft. of 8 /	ft. and add 5/8" surface l description is necessary	ded 10 sa ce pipe)	cks cement	RECE ATE CORPORAT 7/2 JUL 2 ONSERVATI	10N COMMISSION 164 1964 ON DIVISION	