

KANSAS  
STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

**RECEIVED**  
STATE CORPORATION COMMISSION

TO:  
J. P. Roberts  
Assistant Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

15-163-00012-00-00

JUN 6 1962  
06-06-1962  
CONSERVATION DIVISION  
Wichita, Kansas

File No. \_\_\_\_\_ County: \_\_\_\_\_ Rooks

Location: NW NW NW Sec. 13 Twp. 10 Rge. \_\_\_\_\_ (E) \_\_\_\_\_ (W) 16

Name of Field: \_\_\_\_\_ Total Depth: 3500

I have this date completed supervision of plugging of:

Lease Name: Boller Well No. 1

Operator's Full Name: Raymond Oil Co

Complete Address: 410 4th Natl Bk Bldg Wichita, Kansas

Plugging Contractor same

Address: \_\_\_\_\_ License No. \_\_\_\_\_

Oil Well \_\_\_\_\_ Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well \_\_\_\_\_ D & A x

Other well as hereafter indicated: \_\_\_\_\_

Was any delay in plugging operations caused by Conservation Division Agent?  
Yes \_\_\_\_\_ No x

If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 9AM Day 29 Month 5 Year 62

The above well was plugged as follows:

8 5/8" 204' circulated with cement.  
Circulated hole with heavy mud, set cementing plug at 200' displaced  
25 sack cement through drill pipe, heavy mud to 35', set plug, hulls and  
filled to bottom cellar with cement.

Signed: *Edson Peety*  
Conservation Division Agent

Reviewed: *Harold J. Harris*  
Field Supervisor

Remarks:

**INVOICED**  
DATE 6/9/62  
INV. NO. 5116-w