15-045-20045-00 00

KANSAS

Form CP-3 Rev. 6-26-62

STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

RECEIVED
STATE CURPORATION COMMISSION

J. P. Roberts Administrator 500 Insurance Building Wichita 2, Kansas

INV. NO.

6/19/67 JUN 19 1967

CONSERVATION DIVISION Wightha, Karbes

	650 4th Nationa				•
ase Name	Olin Babcock		ell No	1	
ocation 13201 F	FEL & 440' FSLSE	Sec. 21	Twp. 8 F	ge(E)_	(w)25
ounty	Graham	Total	Depth	39901	
andoned Oil Well	Gas Well	Input Well	SWD Well	D & A	<u>x</u>
her well as here	after indicated:				
ugging Contractor	: Leben Drilling,	Incorporated			
ldress:	Box #486, Great	Bend, Kansas	•	License No	
eration Completed	1: Hour 4:30AMDay	16 Mon	t h 6	Year 19	967
e Above well was	nlugged og follower				
	bragged we rottows:				
	,	circulated wi	th 185 Sx		,
018 5/8" Sur	face pipe, cement				Κ.
o'8 5/8" Sur	face pipe, cement of with heavy mud, set	t plug @ 540'	and disp	la ced 20 Sz	
rculated hole ment thru DP.	face pipe, cement with heavy mud, set	t plug @ 540' , set plug wi	and disp th $\frac{1}{4}$ sk.	la ced 20 Sz hulls and c	lis-
rculated hole ment thru DP.	face pipe, cement of with heavy mud, set Heavy mud to 270', ment thru DP. Heav	t plug @ 540' , set plug wi	and disp th $\frac{1}{4}$ sk.	la ced 20 Sz hulls and c	lis-
rculated hole ment thru DP.	face pipe, cement with heavy mud, set	t plug @ 540' , set plug wi	and disp th $\frac{1}{4}$ sk.	la ced 20 Sz hulls and c	lis-
irculated hole ement thru DP.	face pipe, cement of with heavy mud, set Heavy mud to 270', ment thru DP. Heav	t plug @ 540' , set plug wi	and disp th $\frac{1}{4}$ sk.	la ced 20 Sz hulls and c	lis-
irculated hole ement thru DP.	face pipe, cement of with heavy mud, set Heavy mud to 270', ment thru DP. Heav	t plug @ 540' , set plug wi	and disp th $\frac{1}{4}$ sk.	la ced 20 Sz hulls and c	lis-
50'8 5/8" Surinculated hole ement thru DP. Laced 20 Sx. certals and 10 Sx.	face pipe, cement of with heavy mud, set Heavy mud to 270', ment thru DP. Heav cement to bottom of	t plug @ 540', set plug wivy mud to 40'	and disp	la ced 20 Sz hulls and og with $\frac{1}{2}$ sa	lis-
50'8 5/8" Sur irculated hole ement thru DP. laced 20 Sx. centils and 10 Sx.	face pipe, cement of with heavy mud, set Heavy mud to 270', ment thru DP. Heav	t plug @ 540', set plug wivy mud to 40'	and disp	la ced 20 Sz hulls and og with $\frac{1}{2}$ sa	lis-
50'8 5/8" Surinculated hole ement thru DP. Laced 20 Sx. certals and 10 Sx.	face pipe, cement of with heavy mud, set Heavy mud to 270', ment thru DP. Heav cement to bottom of	t plug @ 540' , set plug wi vy mud to 40' of cellar. plugged as her	and disposed the disposed set of the disposed	la ced 20 Sz hulls and og with $\frac{1}{2}$ sa	lis- ack