TATE OF KANSAS

My Commission expires:

WELL PLUGGING RECORD

API	NUMBER	15-193-20,400 00-
		Saddlor

STATE CORPORATION	COMMISSION	K.A.R82-3	-117		PI NUMBER 15-193-20,400 00-0
200 Colorado Derby Wichita, Kansas (y Building			L	EASE NAME Saddler
	į	TYPE OR PRI	NT		ELL NUMBER1
	. '	NOTICE: Fill out and return to C			POT LOCATION C NW/4 SW/4
	•	office within 3			EC. 29 TWP.85 RGE. 32W/ Efor (W)
LEASE OPERATOR WE	est Kansas Crud	le Inc.			ounty Thomas
ADDRESS RR 1, Box	77, Selden, I	Kansas 67757			ate Well Completed 3/28/86
012 /75	2766		7931		lugging Commenced $\frac{3/29/86}{}$
PHONE # (913) 475-	1	RATURS LICENSE NO	•/OJI	·	lugging Completed 3/29/86
Character of Well_ (Oll, Gas, D&A, S)	<u>D & A</u> WD, Input, Wate	r Supply Well)		۲	lugging Completed
Did you notify the	e KCC/KDHE Joi	it District Office	prior t	o pluggin	g this well? Yes
Which KCC/KDHE Jo	int Office did	you notify? Hay	rs, Kansa	as 67601	- Carl Goodrow
Is ACO-1 filed?					
—— Producing formation	on	Depth to t	ор	bo	ttomT.D. 4,965'
Show depth and th					
OIL, GAS OR WATER		1.		CASING	RECORD
Formation	Conto	ent From To	81ze 8 5/8''	295.59	2
	l				
Describe in detai	l the manner in	n which the well w e method or method	as prugg Is used i	ea, inaic n introdu	caring where icing it into
the hole. If cemes	nt or other pla	igs were used stat	e, the c	haracter	of same and
depth placed, from	m_feet to_fe 2730' w/20 s	et each set.	a 1870'	w/100 s	x cement & 1 sx flowseal;
3rd Plug @	a 340' w/40 sx	cement: Run cemer	it 40' to	0' w/no	plug or hulls
		(Plugs calculated		olacement)
100 SX 60/	740 POZIILX, 6%	Gel & 1 sx flowse	3d.L		
(If ad	ditional descr	lption is necessar	y, use B	ACK of th	
Name of Plugging	Contractor R	ed Tiger Drilling	Company		License No5302
Address 1720 KS	SB Building, W	ichita, Kansas 6	7202		
<i>i</i> *	. !				
STATE OF	·	COUNTY OF			,ss.
	4				operator) or
(operator) of abo	ve-described w	eil, being first o	luly swor	n on oat!	n, says: That
the log of the ab	or the facts, ove-described	statements, and ma well as filed that	the sam	e are tr	ue and
correct, so help	me God.				harles Jong
OTATE CORFORATION LI	•				
APR 16 1986	ISSION :		(Addr	ess) <u>K</u>	21 Box 77 Gelden Ko.6
CONSET 1 0 1986	suas	CRIBED AND SWORN T	TO before	me this	14 1 day of april , 1986
CONSERVATION DIVISION Wichita, Kansas	1-16-86			Dese	
THINSAS W	1000 P	The same that the same to the			Notary Public

Appt. Exp. (-/1-8)

Form CP-4 Revised 01-84

days in _	March	15			/6	パクームニ		
Starting Date:	month	day yes	1986	API Nui	mber 15 /7	3-20,	400-	-00-00
*		oay ye.	n1 .					Last
OPERATOR: Li	cense # ./O.J.		• • • • • • • • • • • • • • • • • • • •	N.W.	SW Sec	.29. _{Twp} 8	. s, Rge 32.	📛 West
NameW	est Kansas C			•••	cation)	·		
	R. 1. Box. 77				47.30 r	t North from Sc	outheast Corn	er of Section
City/State/Zip	Selden, Kans	as. 67.757.			1600	Ft West from Sc		
	Charles Youn				(Note: Locate w	ell on Section Plat	on reverse side)	ci or section
	13-475-2766							
				110410	lease or unit bound	lary line550	•••••••	feet.
	License #				Thomas		• • • • • • • • • • • • • • • • • • • •	
T.T.	ed Tiger Dri			2764136 7 11	_{ame} Saddler		Well#	
City/State	ichita, Kans	as	• • • • • • • • • • • • • • • • • • • •	· · · Domesti	c well within 330 feet	t: 🔲 yes	₩ no	
Well Drilled For:	Well Class	: T	ype Equipmer	it: Municip	al well within one m	ile: 🗍 yes	₩ no	
⊞ Oil □ Sw	d 🔲 Infield	Æ	Mud Rotary	•				
[] Gas □ Inj	#*Pool Ex	ı t.	Air Rotary	Depth to	Bottom of fresh w	ater 280		feet
□ OWWO □ Ex	pl Wildcat	r-	Cable		isable water format			
If OWWO: oldwe		. •	•		Bottom of usable			6.44
			•		pipe by Alternate:	1 🛛 2 🗆		ieei
-				Our mee				
				-	pipe to be set	-		
•	01				or pipe if any requi	ired	• • • • • • • • • • • • • • • • • • • •	feet
	pth4900			t Ground	surface elevation . thorization Expires	ي.3128	S	feet MSL
	n at TDbat.te		-	This Aut	thorization Expires		,-1.9.25.	· · · /] · · · · · ·
Expected Producing	g Formations .LKC.	.Cherokee	Miss	Approve	d By	. 3 . 7.1.4.7.87	5	Lu
certify that we will c	omply with K.S.A. 55-	101, et seq., plu	s eventually p	lugging hole to K.C.C	. specifications.		•	CHAUS.
								יייינאפוני ב
				A 1/			- 2	echir
Date .12 .Marck	386 Signature of	Operator or Ac	gent Ass	les Vous	~-∉ Title V	ice Presi	dent 🔻	PCH/KOHM
Date .12 Meroh	186 Signature of		_	les Jon	Title V	ice Presi	dent	PC+11-0
Date 12 March			_	L.1	Title V	ice Presi	dent.	PCHIP Dead
Date .12 Merol			_	L.1	Vater	ice Presi	dent	1 C-1 4/84
Pate 12 Merol			rud3-	18-86	Water	sopple	dent , well	10 C-1 4/84 10 D
Date 12 March		Operator or As	rud3-	18-86	Water	sopple	dent , well	10 C-1 4/84 10 D
Date 12 March			rud3-	L.1	Water	Sopple	dent , well	10 C-1 4/84 10 D
Bi		us J	oud3-1KLA	pprox C.NW.	Water :	Sopple	dent , well	10 C-1 4/84 10 D
Bi		us J	oud3-1KLA	18-86	Water :	Sopple	dent , well	10 C-1 4/84 10 D
Bi	llAye	PLUGO	oud3- IKL ^A GING PRO	pprox C.NW.	SW sec	29 Twp8.	dent	C-1 4/84
Bi	DEAY!	PLUGO	oud3- IKL ^A GING PRO	pprox C.NW.	SW sec	29 Twp8.	dent	C-1 4/84
This plugging pro	LLA Y e	PLUGO	oud3- IKL ^A GING PRO	POSAL IF ABO	SW Sec OVE IS D & A lict office is called po	29 Twp	s, Rg. 3.21	C-1 4/84 — East W. X West (call 7 a.m. to
This plugging pro	DAYE	PLUGO	IKL A GING PRO ved or revised	POSAL IF ABO	SW Sec OVE IS D & A lict office is called po	29 Twp	s, Rg. 3.21	C-1 4/84 — East W. X West (call 7 a.m. to
This plugging pre 5 p.m. workdays)	DAYE	PLUGO ved and approv	GING PROved or revised	POSAL IF ABO at the time the distri	DVE IS D & A ict office is called po	29 Twp	s, Rg. 3.21	C-1 4/84 East X West (call 7 a.m. to
This plugging pro 5 p.m. workdays) 1st plug @	pposal will be review	PLUGO ved and approv	GING PROved or revised depth with .	POSAL IF ABO at the time the distri	OVE IS D & A sectoffice is called promote sectors of	29 Twp8. rior to setting st	s, Rg. 3.21	C-1 4/84 — East W. X West (call 7 a.m. to
This plugging pro 5 p.m. workdays) 1st plug @	pposal will be review	PLUGO ved and approv feet feet feet	GING PROved or revised depth with . depth with .	POSAL IF ABO at the time the district 20 20 100 & 1	OVE IS D & A ict office is called po	29 Twp8. rior to setting st 60-40 flake	s, Rg. 3.2V	C-1 4/84 East X West (call 7 a.m. to
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 1330 340	PLUGO ved and approv feet feet feet	GING PROved or revised depth with	POSAL IF ABO at the time the distriction 20 20 100 & 1 40	OVE IS D & A ict office is called po	29 Twp8. rior to setting st 60-40 flake	s, Rg. 3.2V	C-1 4/84 East X West (call 7 a.m. to
This plugging pre 5 p.m. workdays) 1st plug @	pposal will be review 4900' 2716 1330 340 40bri	PLUGO ved and approv feet feet feet	GING PROved or revised depth with	POSAL IF ABO at the time the district 20 20 100 & 1	OVE IS D & A ict office is called po sxs of sk. Cesks of sxs of sk. hulsksof	29 Twp8. rior to setting st 60-40 flake	dent s, Rg. 3.21 urface casing (C-1 4/84 East X West (call 7 a.m. to
This plugging pro 5 p.m. workdays) 1st plug @	pposal will be review 4900' 2716 1330 340 40bri	PLUGO ved and approv feet feet feet	GING PROved or revised depth with	POSAL IF ABO at the time the distriction 20 20 100 & 1 40	OVE IS D & A ict office is called po sxs of sk. Cesks of sxs of sk. hulsksof	29 Twp8. rior to setting st 60-40 flake	dent s, Rg. 3.21 urface casing (C-1 4/84 East X West (call 7 a.m. to
This plugging pre 5 p.m. workdays) 1st plug @	pposal will be review 4900' 2716 1330 340 40bri	PLUGO ved and approv feet feet feet	GING PROved or revised depth with	POSAL IF ABO at the time the distriction 20 20 100 & 1 40	OVE IS D & A ict office is called po sxs of sk. Cesks of sxs of sk. hulsksof	29 Twp8. rior to setting st 60-40 flake	dent s, Rg. 3.21 urface casing (C-1 4/84 — East W. X West. (call 7 a.m. to) 6% ge1
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 1330 340 40 bris	PLUGO ved and approv feet feet feet ge plete	GING PROved or revised depth with .	POSAL IF ABO at the time the distriction 20 20 100 & 1 40	SW sec OVE IS D & A ict office is called po sxs of sk. cesks of sk. cesks of sk. cesks of sk. huls sof (b) Mount	29 Twp8. rior to setting st 60-40 flake sehole with	dent s, Rg. 3.21 urface casing of the poz.,	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 330 340 40 15	PLUGO ved and approv feet feet feet feet sxs and district of	GING PROved or revised depth with depth with depth with depth with depth with definition of the depth with depth with definition of the depth with de	POSAL IF ABO at the time the district 20 20 100 & 1 40 100 & 1	SW Sec DVE IS D & A ict office is called pr sxs of	29 Twp8. rior to setting st 60-40 flake sehole with	dent s, Rg. 3.21 urface casing of the poz.,	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 330 340 40 15	PLUGO ved and approv feet feet feet feet sxs and district of	GING PRO depth with a depth with depth with depth with depth with depth with defined by the depth with depth	POSAL IF ABC at the time the district 20 20 100 & 1 40 100 & 1 100 & 100	SW sec DVE IS D & A act office is called property of the second	29 Twp8. rior to setting st 60-40 flake sehole with	dent s, Rg. 3.21 urface casing of the poz.,	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @ 2nd plug @ 4th plug @ 5th plug @ (2) Rathole with NOTE: Agreeme In Addition: Call	oposal will be review 4900' 2716 330 340 40 15 ht between operator district office after	PLUGO ved and approv feet feet feet feet sxs and district of	GING PRO depth with a depth with depth with depth with depth with depth with defined by the depth with depth	POSAL IF ABO at the time the district 20 20 100 & 1 40 100 & 1	SW sec DVE IS D & A act office is called property of the second	29 Twp8. rior to setting st 60-40 flake sehole with	dent s, Rg. 3.21 urface casing of the poz.,	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 330 340 40 bri 15 at between operator district office after	PLUGO ved and approved feet feet feet sxs and district or r well is either	GING PROved or revised depth with	POSAL IF ABC at the time the district 20 20 100 & 1 40 100 & 1 100 & 100	SW sec DVE IS D & A act office is called property of the second	29 Twp8. rior to setting st 60-40 flake sehole with	dent s, Rg. 3.21 urface casing of the poz.,	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 330 340 40 bri 15 at between operator district office after	PLUGO ved and approved feet feet feet sxs and district or r well is either	GING PROved or revised depth with	POSAL IF ABC at the time the district 20 20 100 & 1 40 100 & 1 100 & 100	SW sec DVE IS D & A act office is called property of the second	29 Twp8. rior to setting st 60-40 flake sehole with	dent s, Rg. 3.21 urface casing of the poz.,	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @ 2nd plug @ 4th plug @ 5th plug @ (2) Rathole with NOTE: Agreeme! In Addition: Call District office us API #15—	oposal will be review 4900' 2716 330 340 40 bri 15 ht between operator district office after	PLUGO ved and approved and approved and approved	GING PROved or revised depth with	POSAL IF ABO at the time the district 20	OVE IS D & A ict office is called pr	29 Twp	dent s, Rg. 3.21 urface casing of the poz.,	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	oposal will be review 4900' 2716 330 340 40 bri 15 ht between operator district office after	PLUGO ved and approved and approved and approved	GING PROved or revised depth with	POSAL IF ABC at the time the district 20 20 100 & 1 40 100 & 1 100 & 100	OVE IS D & A ict office is called pr	29 Twp8. rior to setting st 60-40 flake sehole with	dent s, Rg. 3.21 urface casing of the poz.,	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 330 340 40 15 ht between operator district office after c only: 193-6	PLUGO ved and approved and approved and approved	GING PRO depth with a depth with	POSAL IF ABO at the time the district 20 20 100 & 1 40 10. & 1.	SW Sec DVE IS D & A ict office is called pr sxs of sxs of sxs of sxs of (b) Mountainmount of cement to seemented in. ays)	29 Twp8. rior to setting su 60-40 flake sehole with o be used is necessary.	s, Rg. 3.21 urface casing (DOZ., (N/A essary prior (C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 1330 340 40bri15 Int between operator district office after only: 272 surface only:	PLUGO ved and approved and approved and approved and approved appr	GING PRO depth with d	POSAL IF ABO at the time the district 20 20 100 & 1 40 10. & 1.	SW Sec SW Sec OVE IS D & A ict office is called property of the second	29 Twp8. rior to setting st 60-40 flake sehole with o be used is necessary. hours,	s, Rg. 3.21 urface casing (DOZ., (C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 1330 340 40bri15 Int between operator district office after only: 272 surface only:	PLUGO ved and approved and approved and approved and approved appr	GING PRO depth with d	POSAL IF ABC at the time the district 20 20 100 & 1.40 10. & 1.50 placement and the approduction casing is m. to 5 p.m. workd	DVE IS D & A act office is called property of the second	29 Twp8. rior to setting su 60-40 flake sehole with be used is necessary sxs on Co	s, Rg. 3.21 urface casing of the control of the co	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 1330 340 40bri15 Int between operator district office after only: 272 surface only:	PLUGO ved and approved and approved and approved and approved appr	GING PRO depth with d	POSAL IF ABC at the time the district 20 20 100 & 1.40 10. & 1.50 placement and the approduction casing is m. to 5 p.m. workd	DVE IS D & A act office is called property of the second	29 Twp8. rior to setting su 60-40 flake sehole with be used is necessary sxs on Co	s, Rg. 3.21 urface casing of the control of the co	C-1 4/84 — East W. — X West. (call 7 a.m. to) 6% ge1.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 1330 340 40bri15 Int between operator district office after only: 272 surface only:	PLUGO ved and approved and approved and approved and approved appr	GING PRO depth with d	POSAL IF ABC at the time the district 20 20 100 & 1.40 10. & 1.50 placement and the approduction casing is m. to 5 p.m. workd	DVE IS D & A act office is called property of the second	29 Twp8. rior to setting su 60-40 flake sehole with be used is necessary sxs on Co	s, Rg. 3.21 urface casing of the control of the co	C-1 4/84 — East W X West (call 7 a.m. to 6% gel sxs to plugging.
This plugging pro 5 p.m. workdays) 1st plug @	posal will be review 4900' 2716 1330 340 40bri15 Int between operator district office after only: 272 surface only:	PLUGO ved and approved and approved and approved and approved appr	GING PRO depth with d	POSAL IF ABO at the time the district 20 20 100 & 1 40 10. & 1. s placement and the approduction casing is im. to 5 p.m. workd	SW Sec SW Sec OVE IS D & A ict office is called property of the second	29Twp8. rior to setting su 60-40 flake sehole with be used is necessary sxs on CO	s, Rg. 3.21 urface casing of the control of the co	C-1 4/84 — East W West (call 7 a.m. to 6% gel ., 19 ., 19, 19