STATE CORPORATION COMISSION 200 Colorado Perby Bldg. Wichita, Karsas 67202 WELL PLIKKING RECORD AC

Make Required Affidavit	T YTNUCO	「homas		SEC. 1	6 TUP	8S ROF :	33M & W.	
	Location a	as in qua SW NE SW	riers or	footage	from lines:	1000	E/W	
	Lease Owne	er Si	unburst	Explorati	on Company,	Inc.		
	Lease Name	e BREM	ENKAMP	G'	We:	11 No. 1		
					Wichita, K			
	Character	of Well	(Complet	ed as <b>011</b>	., Cas or Dry	y Hole): Di	y Holē	
	Date Well	Complete	d	Jur	ne 19, 1983			
					ne 19, 1983			
	Plugging o	commenced	·	Jun	ne 19, 1983			
		Plugging completed June 19, 1983						
Locate Well					roducing for			
correctly on above					as encounte		<del></del>	
Section Platt.					nservation l	Division or	it's	
Nome of Consequent	Agent's be						·	
Name of Conservation Ager								
Producing formation		Depth to	tob	bot	ton	T.D. 4810'	<del></del>	
Show depth and thickness		c, oil and	igas fo	rmaticns.	٠			
OTL, CAS OR WATER RECORDS	3			r:		Casing	Record	
Formation .	Content	Pròm	To	Size	Put In		ed Out	
		<del> </del>	<u> </u>					
					L	}		
or other plugs were used,	state the c	LIDOUS TISE	מו חו	TYCCUC 1 no	it into the	hald re	cement	
or other plugs were used, to	state the child set et lst plug et 2nd plug	@ 2760' w	of same	and dept	it into the	hald re	cement	
or other plugs were used, to	state the child set et 1st plug et 2nd plug et 3rd plug	0 2760' w 0 1690' w 0 410' wi	of same	and dept	it into the h placed, fr	hald re	cement	
or other plugs were used, feet for eac  Se Se Se Se Se	state the che plug set et 1st plug et 2nd plug et 3rd plug et 4th plug of sx. in Rat	@ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10	of same with 20 with 100 th 40 s Bridg sx. in	sx. sx. x. e with 10	h placed, fr	hald re	cement	
or other plugs were used, feet for eac  Se Se Se Se 10	state the cent plug set et 1st plug set et 2nd plug set 3rd plug set 4th plug set 4th plug set 90 sx. in Rat 9-50 pozmix.	@ 2760' w @ 1690' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel,	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c.	sx. sx. x. e with 10 Mousehole	h placed, fr	hald re	cement	
or other plugs were used, to	state the che plug set et 1st plug et 2nd plug et 3rd plug et 4th plug of sx. in Rat	@ 2760' w @ 1690' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel,	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c.	sx. sx. x. e with 10 Mousehole	h placed, fr	hald re	cement	
or other plugs were used, to feet for eac  Se Se Se 10	state the che plug set.  et 1st plug set.  et 2nd plug et 3rd plug et 4th plug of 50 sx. in Rat of 50 pozmix.  lug was down	@ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel. @ 8:00 a	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/	sx. sx. x. e with 10 Mousehole	h placed, fr	e hold. If	cement	
or other plugs were used, to feet for eac  So So So So P  (If additional	et 1st plug et 2nd plug et 3rd plug et 4th plug of 50 sx. in Rat 0-50 pozmix. lug was down description or Abercrom	@ 2760' w @ 1690' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel, @ 8:00 a	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/	sx. sx. e with 10 Mousehole 19/83. se BACK oc.	f this sheet	e hold. If	cement	
or other plugs were used, to	et 1st plug et 2nd plug et 3rd plug et 4th plug of 50 sx. in Rat 0-50 pozmix. lug was down description or Abercrom	ethods use character @ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel. @ 8:00 a	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/	sx. sx. x. e with 10 Mousehole 19/83.	f this sheet	e hold. If	cement	
or other plugs were used, to	et 1st plug et 2nd plug et 3rd plug et 3rd plug et 4th plug of 50 pozmix. lug was down description or Abercrom 801 Union	ethods use character @ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel. @ 8:00 a	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/	sx. sx. x. e with 10 Mousehole 19/83. se BACK oc. a, KS 6720	f this sheet	hold. If	feet	
or other plugs were used, to feet for each See	et 1st plug et 1st plug et 2nd plug et 3rd plug et 3rd plug et 4th plug o sx. in Rat 0-50 pozmix. lug was down  description or Abercrom 801 Union  COUNTY OF President	ethods use character @ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel, @ 8:00 a lis neces bie Drill n Center, Sedgwic	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/	sx. sx. x. e with 10 Mousehole 19/83. se BACK oc. a, KS 6720 ,ss. her) or	f this sheet  (owner or open I have been	e hold. If	the	
or other plugs were used, to feet for eac  So So So So So Pl  (If additional lame of Plugging Contract  Kansas  STATE OF  Kansas  ack L. Partridge, Vice F above-described well, bein facts, statements, and ma	et 1st plug et 2nd plug et 3rd plug et 3rd plug et 4th plug osx. in Rat 0-50 pozmix. lug was down  description or Abercromb 801 Union  COUNTY OF President ng first dul tters berein	ethods use character @ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel. @ 8:00 a lis neces bie Drill n Center, Sedgwic (enploy y sworn of	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/ sary, u ing, In Wichit k ee of o o o o o o o o o o o o o o o o o o	sx. sx. x. e with 10 Mousehole 19/83. se BACK oc. a, KS 6720 ,ss. mer) or says: The	f this sheet  (owner or open I have been	e hold. If	the	
or other plugs were used, feet for eac  Se Se Se Se The second of the se	et 1st plug et 2nd plug et 3rd plug et 3rd plug et 4th plug osx. in Rat 0-50 pozmix. lug was down  description or Abercromb 801 Union  COUNTY OF President ng first dul tters berein	ethods use character @ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel. @ 8:00 a lis neces bie Drill n Center, Sedgwic (enploy y sworn of	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/ sary, u ing, In Wichit k ee of o o o ath, d and th So help (Signal	sx. sx. x. e with 10 Mousehole 19/83. se BACK oc. a, KS 6720 ,ss. wher) or says: The log of one Cod. ature)	sx.  f this sheet  cowner or ophat I have k  the above-d	e hold. If con  erator) of mowledge or lescribed was a lescrib	the the all as	
or other plugs were used, to feet for eac  Second S	et 1st plug et 2nd plug et 3rd plug et 3rd plug et 4th plug osx. in Rat 0-50 pozmix. lug was down  description or Abercromb 801 Union  COUNTY OF President ng first dul tters berein	ethods use character @ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel. @ 8:00 a lis neces bie Drill n Center, Sedgwic (enploy y sworn of	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/ sary, u ing, In Wichit k ee of o o o ath, d and th So help (Signal	sx. sx. x. e with 10 Mousehole 19/83. se BACK oc. a, KS 6720 ,ss. wher) or says: The log of one Cod. ature)	f this sheet  (owner or open I have been	e hold. If com  erator) of mowledge or lescribed with the control of the control	the the all as	
or other plugs were used, to feet for each set facts, statements, and manage of the set facts, statements, and manage for each set facts.	et 1st plug et 2nd plug et 3rd plug et 3rd plug et 4th plug o sx. in Rat 0-50 pozmix. lug was down  description or Abercromb 801 Union  COUNTY OF President ng first dul tters herein re true and	ethods use character @ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel. @ 8:00 a lis neces bie Drill n Center, Sedgwic (employ y sworn of containe correct.	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/ sary, u ing, In Wichit k ee of o o o ath, d and th So help (Signal	sx. sx. x. e with 10 Mousehole 19/83. se BACK oc. a, KS 6720 ,ss. wher) or says: The log of	f this sheet  SX.  f this sheet  Cull fenter, Wichi  (Addr	e hold. If com  erator) of chowledge of lescribed was lesc	the the all as	
(If additional Name of Plugging Contract:  STATE OF  Kansas  Jack L. Partridge, Vice Fabove-described well, being facts, statements, and manifiled and that the same and filed and that the same and same	et 1st plug et 2nd plug et 3rd plug et 3rd plug et 4th plug o sx. in Rat 0-50 pozmix. lug was down  description or Abercromb 801 Union  COUNTY OF President ng first dul tters herein re true and	ethods use character @ 2760' w @ 1690' w @ 410' wi @ 40' Sol hole. 10 6% gel. @ 8:00 a lis neces bie Drill n Center, Sedgwic (employ y sworn of containe correct.	of same with 20 with 100 th 40 s Bridg sx. in 3% c.c. m., 6/ sary, u ing, In wichit k ee of o n oath, d and th So help (Signa 80	sx. sx. x. e with 10 Mousehole 19/83. se BACK oc. a, KS 6720 ,ss. wher) or says: The log of one Cod. ature)	f this sheet  SX.  f this sheet  Cull fenter, Wichi  (Addr	e hold. If com  erator) of mowledge or lescribed with the control of the control	the the all as	
or other plugs were used, to	et 1st plug et 2nd plug et 3rd plug et 3rd plug et 4th plug o sx. in Rat 0-50 pozmix. lug was down  description or Abercromb 801 Union  COUNTY OF President ng first dul tters herein re true and	ethods use character  0 2760' w 0 1690' w 0 410' wi 0 40' Sol hole. 10 6% gel, 0 8:00 a  is neces bie Drill n Center, Sedgwic (employ y sworn of containe correct.	of same of sam	sx. sx. x. e with 10 Mousehole 19/83. se BACK oc. a, KS 6720 ,ss. wher) or says: The log of	f this sheet  SX.  SX.  (owner or ophat I have kethe above-denter, Wiching Addity  erry  No. 1	e hold. If com  erator) of chowledge of lescribed was lesc	the the all as	

CONSERVATION DIVISION Wichita, Kansas