

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM 15-173-03518-0000
File One Copy

Lease Owner Bedell-Catt Drilling Company Address 701 Petroleum Bldg. Wichita, Kans
(Applicant)

Lease (Farm Name) Edson Well No. 1-A

Well Location NW NW NE Sec. 12 Twp. 26S Rge 2 (E) XXXXXX

County Sedgwick Field Name (if any) Greenwich Pool

Total Depth 2900 2890 ANB KCC Oil Gas Dry Hole X

Was well log filed with application? No If not, explain:

Date and hour plugging is desired to begin Aug. 23, 1957

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner A. J. Marsh - Toolpusher

R #3 Address Augusta, Kansas

Plugging Contractor Bedell-Catt Drilling Company

Plugging Contractor's License No. 208

Address 701 Petroleum Bldg. Wichita 2, Kansas

Invoice covering assessment for plugging this well should be sent to

Bedell-Catt Drilling Company Address 701 Petroleum Bldg., Wichita 2, Kans.

and payment will be guaranteed by applicant.

BEDELL-CATT DRILLING COMPANY
By: Carl B. Bevel
Applicant or Acting Agent

Date Aug. 23, 1957 RECEIVED
STATE CORPORATION COMMISSION

PLUGGING
FILE SEC. 12 T. 26 R. 2E
BOOK PAGE 40 LINE 7

AUG 27 1957
8-27-57
CONSERVATION DIVISION
Wichita, Kansas



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS
August 27, 1957


Well No.	A-A
Lease	Edson
Description	NW NW NE 12-26-2E
County	Sedgwick
File No.	40-7

Redell-Catt Drilling Company
701 Petroleum Building
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Ruel Durkee, Box 597, McPherson, Kansas

Very truly yours,


Jewel M. Ogden
Director of Conservation Division

cc:
District Plugging Supervisor