IF HOLE IS PLUGGED A THIRD COPY IS NEEDED. FOR INJECTION OR DISPOSAL FOUR COPIES ARE NEEDED.

CONSCINATION DIVISION -

Wichita, Kansas

FILL	Company, I	NFORMATIO	J	UIRED:	WELL NO.	SHOW GEOLOGICAL	MARKERS LOGS RUN.	
Show all important zones of potosity and contents thereof; cored intervals, and cluding depth interval tested, cushion used, time tool open, flowing and shut-in pr					and recoveries.	OR OTHER DESCRIPTIVE INFORMATION.		
and the second s	DESCRIPTION, CO		В,	ТОР	воттом	NAME	DEPTH	
Check if r	o Drill S	tem Tests	kun•			Anhydrite Topeka Heebner Lansing-K. RTD	1894 3344 3562 3599 4030	
		·.						
•								
				·			,	
, ,								
e gamene —			• •			a an		
If additional	space is n	eeded use	Page 2,	Side 2				
Report of all string	set — surface,		production, et	c. CASING	RECORD (N	ew) or (Used)		
Purpose of string	Size hole drilled	Sixe casing set (in O.D.)	Weight lbs/ft.	Setting depth	Type cement	Sacks	Type and percent additives	
	I	1				1		

Report of all strin	ıgs set — surface,	intermediate,	production, e	c. CASING	RECORD	(New)	or (Use		
Purpose of string	Size hole drilled	Size casing set			Туре с	ement	Sacks	Type and percent additives	
Surface	124"	8-5/8"	24#	245	Commo	n	170	2% gel, 3% c	
	<u> </u>					-			
			;						
			 						
LINER RECORD			PERFORA				ATION RECORD		
Top, ft.	Bottom, ft.	Sacks o	ement	Shot	Shots per ft.		te & type	Depth interval	
	TUBING REC	ORD							
Size	Setting depth	Packer	set at						
		ACID, FRACT	TURE, SHOT	, CEMENT S	QUEEZE RI	CORD			
	Ame	ount and kind of	material used					Depth interval treated	
				•	·				
v.					į.				
Date of first production	1	Produc	ing method (fl	owing, pumping,	, gas lift, etc	.)	Grav	rity	
Estimated Production:	Oil T.P.		Gas	,	Wate	' %	bbls.	Gas-oil ratio	
Disposition of gos (ven			, jois.			rforati			

> .